





report date: 2024-03-28

General information

Make	BMW
Model	520 520D SE
Colour	Grey
Year of manufacture	2012
Top speed	140 mph
Gearbox	8 speed automatic

Engine & fuel consumption

Power	181 BHP
Max. torque	380 Nm at 1.750 rpm
Engine capacity	1.995 сс
Cylinders	4
Fuel type	Diesel
Consumption city	49.6 mpg
Consumption extra urban	68.9 mpg
Consumption combined	60.1 mpg
CO2 emission	123 g/km
CO2 label	D



CarCheck.co.uk page 1/13



Internet history

Entr	. 1
EIIU	vт

Lifety 1	
Date	2021-01-28
Pictures	0
Listing price	View report

source: autoonline.co.uk

CarCheck.co.uk page 2/13



MOT history

MOT expiry date	2025-04-08
MOT pass rate	82 %
MOT passed	9
Failed MOT tests	2
Total advice items	23
Total items failed	2

MOT #11	2024-04-09 10:30
MOT test number	841400971433
Result	✓ Passed
Next expiry date	2025-04-08
Advice Offside Rear Child Seat fitted not allowing full inspection of adult belt	

MOT #10		2023-04-01 09:33
MOT test	number	420012915884
Result		✓ Passed
Minor	Offside Obligatory mirror slightly damaged (3.3 (b) (i))	
Advice	Offside Rear Child Seat fitted not allowing full inspection of adult belt	
Advice	Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))	
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))	

CarCheck.co.uk page 3/13



report date: 2024-03-28

MOT #9 2023-04-01 09:33 965403443253 **MOT** test number Result × Failed **Advice** Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i)) Minor Offside Obligatory mirror slightly damaged (3.3 (b) (i)) Pass with rectification Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii)) **Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt Advice Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b)) **Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #8

MOT test number

Fesult

Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt

Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #7		2021-04-06 14:53
MOT test	number	202078867178
Result		✓ Passed
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14	(a) (ii))
Advice	Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

CarCheck.co.uk page 4/13



report date: 2024-03-28

MOT test number
623437736346

Result

Advice Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Fail Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #5

MOT test number

S15822076833

Result

Advice

Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

 MOT #4
 2018-07-02 14:01

 MOT test number
 990296568060

 Result
 ✓ Passed

 MOT #3
 2017-07-12 15:16

 MOT test number
 131269997012

 Result
 ✓ Passed

 MOT #2
 2016-07-05 14:37

MOT test number

Result

Advice Nsf tyre low on outter edge

Advice Rear Brake pad(s) wearing thin (3.5.1g)

CarCheck.co.uk page 5/13



report date: 2024-03-28

MOT #1

MOT test number

749155995125

Result

Advice Rear Brake pad(s) wearing thin (3.5.1g)

CarCheck.co.uk page 6/13



Tax & MOT check



Tax status	Valid until 1 April
Days left	337
MOT expiry date	8 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-

CarCheck.co.uk page 7/13



report date: 2024-03-28

Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report here for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Tyne	



Extra BMW salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



faste since

EX12PTU

report date: 2024-03-28

More info >

Owner history For how long did the current and previous owner(s) have this BMW? How many owners did this BMW have? Check it in the premium report and see all owner registrations. Download the full report here. More info > Plate changes See in this check if this BMW had different number plates.

CarCheck.co.uk page 10/13



Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this BMW is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2012-07-27
Last registration	2024-04-09
Complete history	See info



Registration #1	2012-07-27	23 mi
Registration #2	2015-07-14	34.953 mi
Registration #3	2016-07-05	47.432 mi
Registration #4	2017-07-12	60.815 mi
Registration #5	2018-07-02	72.820 mi
Registration #6	2019-07-01	84.568 mi
Registration #7		11.777 mi
Registration #8		11.777 es
Registration #9		11.777 mi
Registration #10		11.777 es
Registration #11		11.777 mi
Registration #12		0.00 44
Registration #13		0.77 66

More info >

CarCheck.co.uk page 12/13



Car features

S0225	Air conditionin
50295	
50482	
50501	
60566	
60567	
50569	

Safety ratings

NCAP rating	****
Adult	95%
Children	83%
Pedestrian	78%
Safety systems	100%
Overall rating	90%
Video	see crash video



Dimensions & weight

Width	1860 mm
Height	1475 mm
Length	4899 mm
Wheel base	2968 mm
Kerb weight	1625 kg
Max. allowed weight	2235 kg

Additional information

Fuel tank capacity	70 I
Fuel delivery	Direct Injection
Number of doors	4
Number of seats CarCheck.co.uk	5 page 13/1:

Number of axles 2

Engine number 90778224