



report date: 2024-03-29

General information

Make	FORD
Model	FOCUS ZETEC S TDCI
Colour	Red
Year of manufacture	2012
Top speed	120 mph
0 - 60 mph	10.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	113 BHP
Max. torque	285 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	55.4 mpg
Consumption extra urban	76.3 mpg
Consumption combined	67.3 mpg
CO2 emission	109 g/km
CO2 label	B






Internet history

Entry 1

Date	2021-05-25
Pictures	29
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-06-06
MOT pass rate	67 %
MOT passed	10
Failed MOT tests	5
Total advice items	39
Total items failed	8

MOT #15	2023-06-02 15:02
MOT test number	313968290580
Result	✓ Passed
Next expiry date	2024-06-06
Advice	Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))
Minor	Nearside Front Obligatory mirror slightly damaged (3.3 (b) (i))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))
Minor	Nearside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))
Advice	Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))

**MOT #14**

2023-06-02 11:38

MOT test number

588784062419

Result**✗ Failed****Fail**

Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))

Minor

Nearside Front Obligatory mirror slightly damaged (3.3 (b) (i))

Advice

Nearside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))

Advice

Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))

Minor

Nearside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

Advice

Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice

Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))

MOT #13

2022-05-30 08:28

MOT test number

542431549010

Result**✓ Passed****Advice**

Nearside Front Child Seat fitted not allowing full inspection of adult belt

Advice

Central Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice

Nearside Front Inner Tyre worn close to legal limit/worn on edge wear on edge (5.2.3 (e))

Minor

Nearside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

Advice

Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice

Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Minor

Offside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

**MOT #12**

2022-05-30 08:28

MOT test number

100270199850

Result

✗ Failed

- Advice** Nearside Front Inner Tyre worn close to legal limit/worn on edge wear on edge (5.2.3 (e))
- Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Minor** Nearside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Front Child Seat fitted not allowing full inspection of adult belt
- Pass with rectification** Front Undertray likely to become detached (6.2.1 (a) (ii))
- Minor** Offside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Advice** Central Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #11

2022-05-27 11:05

MOT test number

784825120975

Result

✗ Failed

- Advice** Nearside Front Child Seat fitted not allowing full inspection of adult belt
- Fail** Nearside Front Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
- Advice** Central Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Front Inner Tyre worn close to legal limit/worn on edge wear on edge (5.2.3 (e))
- Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Fail** Offside Front Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #10

2021-06-07 09:31

MOT test number

328430674692

Result

✓ Passed

**MOT #9** 2020-09-14 12:44**MOT test number** 947073468583**Result** ✓ Passed**MOT #8** 2019-09-06 15:48**MOT test number** 232936215928**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge 2.5mm (5.2.3 (e))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #7** 2019-09-06 08:31**MOT test number** 318532970501**Result** ✗ Failed**Advice** Offside Rear Tyre worn close to legal limit/worn on edge 1.6mm (5.2.3 (e))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge 2.5mm (5.2.3 (e))**Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**MOT #6** 2018-09-10 08:22**MOT test number** 286539934955**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to legal limit/worn on edge 2mm (5.2.3 (e))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge 2mm (5.2.3 (e))**MOT #5** 2017-09-11 11:35**MOT test number** 805270898014**Result** ✓ Passed

**MOT #4** 2017-09-11 10:25**MOT test number** 721164525076**Result** ✗ Failed**Fail** Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**Fail** Offside Front position lamp(s) not working (1.1.A.3b)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened BOTH CORRODED+LIPPED (3.5.1i)**MOT #3** 2016-09-02 14:31**MOT test number** 623875051854**Result** ✓ Passed**MOT #2** 2015-09-14 00:00**MOT test number** 182084039773**Result** ✓ Passed**MOT #1** 2015-06-08 11:55**MOT test number** 499589255187**Result** ✓ Passed



Tax & MOT check

✓
Taxed

Tax due:
1 June 2024

✓
MOT

Expires:
6 June 2024

Tax status	Valid until 1 June
Days left	34
MOT expiry date	6 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	B
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	SG12YDD
Plate since	2019-03-29
Current registration	SG12YDD
Plate since	2019-03-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2012-08-27
Last registration	2023-06-02
Complete history	See info



Registration #1	2012-08-27	23 mi
Registration #2	2015-06-08	55.991 mi
Registration #3	2015-09-14	60.583 mi
Registration #4	2016-09-02	73.750 mi
Registration #5	2017-09-11	84.797 mi
Registration #6	2017-09-11	84.797 mi
Registration #7	2018-09-10	94.753 mi
Registration #8	2019-09-06	102.300 mi
Registration #9	2019-09-06	102.300 mi
Registration #10	2019-09-06	102.300 mi
Registration #11	2019-09-06	102.300 mi
Registration #12	2019-09-06	102.300 mi
Registration #13	2019-09-06	102.300 mi
Registration #14	2019-09-06	102.300 mi
Registration #15	2019-09-06	102.300 mi
Registration #16	2019-09-06	102.300 mi
Registration #17	2019-09-06	102.300 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	92%
Children	82%
Pedestrian	72%
Safety systems	71%
Overall rating	84%
Video	see crash video



Dimensions & weight

Width	2010 mm
Height	1469 mm
Length	4360 mm
Wheel base	2648 mm
Max. allowed weight	1900 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2

