

Ford



General information

Make	FORD
Model	FOCUS ZETEC
Colour	Black
Year of manufacture	2009
Top speed	115 mph
0 - 60 mph	11.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	99 BHP
Max. torque	143 Nm at 4.000 rpm
Engine capacity	1.596 cc
Cylinders	4
Fuel type	Petrol
Consumption city	30.7 mpg
Consumption extra urban	51.4 mpg
Consumption combined	40.9 mpg
CO2 emission	159 g/km
CO2 label	G







Internet history

Entry 1	
Date	2021-01-30
Pictures	8
Listing price	View report



source: autoonline.co.uk



MOT history

MOT expiry date	2025-03-03
MOT pass rate	75 %
MOT passed	12
Failed MOT tests	4
Total advice items	8
Total items failed	9

MOT #16	2024-02-12 12:57
MOT test number	303884279941
Result	✓ Passed
Next expiry date	2025-03-03

MOT #15	2023-03-03 10:17
MOT test number	280775214202
Result	✓ Passed
Advice Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))	

MOT #14	2022-02-25 10:18
MOT test number	332925073266
Result	✓ Passed

MOT #13	2021-03-04 17:34
MOT test number	379268301531
Result	✓ Passed
Advice Front Brake disc worn, but not excessively (1.1.14 (a) (i))	
Advice Rear exhaust hanger defective	





MOT #12	2021-03-03 12:29
MOT test number	857726650987
Result	🗙 Failed
Fail Rear Brakes imbalanced across an axle o/s lower results than n/s during imbalance	e test (1.2.1 (b) (i))
Advice Front Brake disc worn, but not excessively (1.1.14 (a) (i))	
Advice Rear exhaust hanger defective	
Fail Windscreen washer provides insufficient washer liquid (3.5 (a))	

MOT #11		2018-09-12 15:11
MOT test nun	nber	338958244396
Result		✓ Passed
Advice Fro	ont Brake disc worn, pitted or scored, but not seriously weakened (1.1.1	14 (a) (ii))

МОТ #10	2018-09-11 15:06	
MOT test number	986881626963	
Result	🗙 Failed	
Fail Nearside Front Suspension arm pin or bush excessively worn The main bush (5.	.3.4 (a) (i))	
Pass with rectification Windscreen washer provides insufficient washer liquid (3.5	5 (a))	
Fail Offside Front Suspension arm pin or bush excessively worn The main bush (5.3.4 (a) (i))		
Fail Nearside Front Position lamp not working (4.2.1 (a))		

МОТ #9	2017-08-21 14:05
MOT test number	648271749976
Result	✓ Passed



MOT #8	2017-08-21 08:07
MOT test number	767776910204
Result	🗙 Failed
Fail Offside Front coil spring broken (2.4.C.1a)	
Fail Offside Rear fog lamp not working (1.3.2b)	

МОТ #7	2016-08-15 08:30
MOT test number	921853883690
Result	✓ Passed

MOT #6		2016-08-15 08:30
MOT test number		177954250000
Result		🗙 Failed
Pass with rectification	Offside Rear fog lamp not working (1.3.2b)	

MOT #5	2015-08-24 09:09
MOT test number	401442929854
Result	✓ Passed
Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	

MOT #4	2014-08-18 13:51
MOT test number	705830134245
Result	✓ Passed
MOT #3	2013-08-12 09:31
MOTION	045204422251

MOT test	number	945294423251
Result		✓ Passed
Notice	O/s/n/s/f tyres wearing on inside edges.	

CarCheck.co.uk

HY59HFW

report date: 2024-03-29





MOT #2	2012-08-11 10:22
MOT test number	366104822217
Result	✓ Passed
MOT #1	2011-09-01 14:59
MOT test number	899604641265
Result	✓ Passed



Tax & MOT check

✓ Taxed Tax due: 1 September 2024	MOT Expires: 3 March 2025
Tax status	Valid until 1 September
Days left	125
MOT expiry date	3 March 2025
Full MOT history	See MOT history
Tax calculation	

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-





Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1		
Date	F	
Category		ARME
Туре		
Damage 2		AMPLE
	E E	
Date		\$
Category	AMP	
Туре	No. Contraction of the second se	

Extra FORD salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4





Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	

	More info >
Plate changes	
See in this check if this FORD had different number plates.	
Number of plates	,
Current registration	
Plate since	
Current registration	
Plate since	
	More info >





Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2009-09-03
Last registration	2024-02-12
Complete history	See info



Registration #1	2009-09-03	23 mi
Registration #2	2011-09-01	23.501 mi
Registration #3	2012-08-11	29.397 mi
Registration #4	2013-08-12	36.253 mi
Registration #5	2014-08-18	42.766 mi
Registration #6	2015-08-24	49.132 mi
Registration #7	2016-08-15	54.234 mi
Registration #8	2016-08-15	54.234 mi
Registration #9	2017-08-21	59.512 mi
Registration #10		11.777 esi
Registration #11		11.777 est
Registration #12		11.777 esi
Registration #13		11.777 est
Registration #14		11.777 esi
Registration #15		11.777 est
Registration #16		11.777 esi
Registration #17		11.777 mi
Registration #18		11.777 est





Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating

Video

**** see crash video



Dimensions & weight	
Width	1998 mm
Height	1430 mm
Length	4152 mm
Wheel base	2640 mm
Kerb weight	1277 kg
Max. allowed weight	1820 kg
Additional information	
Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 13/13

Number of axles	2
Engine number	9U51607