



report date: 2024-03-29

General information

Make	VOLVO
Model	V70 D5 SE EU4
Colour	Gold
Year of manufacture	2006
Top speed	137 mph
0 - 60 mph	10.2 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	185 BHP
Max. torque	400 Nm at 2.000 rpm
Engine capacity	2.401 cc
Cylinders	5
Fuel type	Diesel
Consumption city	26.9 mpg
Consumption extra urban	44.1 mpg
Consumption combined	35.8 mpg
CO2 emission	209 g/km
CO2 label	K





Internet history

Entry 1

Date	2021-08-04
Pictures	24
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-08-18
MOT pass rate	76 %
MOT passed	16
Failed MOT tests	5
Total advice items	12
Total items failed	9

MOT #21	2023-08-18 10:59
MOT test number	920626580556
Result	✓ Passed
Next expiry date	2024-08-18
Advice	Parking brake lever on warning light not working

MOT #20	2023-08-18 07:56
MOT test number	350653368793
Result	✗ Failed
Fail	Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))
Fail	Nearside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
Fail	Nearside Track rod end ball joint has excessive play (2.1.3 (b) (i))
Advice	Parking brake lever on warning light not working

MOT #19	2022-08-17 08:41
MOT test number	743891404091
Result	✓ Passed

MOT #18	2021-08-19 09:10
MOT test number	823826264142
Result	✓ Passed

**MOT #17** 2021-08-09 14:03**MOT test number** 125317378977**Result** ✗ Failed**Fail** Front Headlamp not working on main beam (4.1.1 (a) (ii))**Fail** All direction indicators not working (4.4.1 (a) (ii))**MOT #16** 2021-01-26 09:37**MOT test number** 928140220440**Result** ✓ Passed**MOT #15** 2020-02-05 12:03**MOT test number** 295647658093**Result** ✓ Passed**MOT #14** 2020-02-04 17:10**MOT test number** 346711914349**Result** ✗ Failed**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Fail** Front Service brake imbalanced across an axle (1.2.1 (b) (i))**Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Pass with rectification** Offside Headlamp aim too low (4.1.2 (a))**MOT #13** 2020-02-04 10:40**MOT test number** 606247431540**Result** ✗ Failed**Fail** Offside Brakes imbalanced across an axle by more than 50% (1.2.1 (b) (ii))

**MOT #12** 2019-02-06 11:17**MOT test number** 709583740717**Result** ✓ Passed**MOT #11** 2018-02-08 14:43**MOT test number** 330165487100**Result** ✓ Passed**Advice** Nearside rear brake fluctuating, but not excessively (3.7.B.3)**Advice** Offside rear brake fluctuating, but not excessively (3.7.B.3)**MOT #10** 2017-02-09 13:03**MOT test number** 786091086234**Result** ✓ Passed**MOT #9** 2017-02-09 13:03**MOT test number** 927393494327**Result** ✗ Failed**Pass with rectification** Nearside Rear Registration plate lamp not working (1.1.C.1d)**MOT #8** 2016-02-11 13:01**MOT test number** 582392834622**Result** ✓ Passed**Advice** Offside Front tyre bald on inner edge.**Advice** Centre exhaust mounting broken off.**MOT #7** 2015-02-12 12:56**MOT test number** 988803445096**Result** ✓ Passed



MOT #6	2014-02-12 14:25
---------------	------------------

MOT test number	729243044070
------------------------	--------------

Result	✓ Passed
---------------	----------

Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
---------------	---

Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)
---------------	--

MOT #5	2013-02-18 15:12
---------------	------------------

MOT test number	838219843039
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #4	2012-02-15 15:50
---------------	------------------

MOT test number	918996542096
------------------------	--------------

Result	✓ Passed
---------------	----------

Advice	Offside Rear Rear wheel bearing has slight play (2.6.2)
---------------	---

MOT #3	2011-02-15 10:30
---------------	------------------

MOT test number	919796941061
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #2	2010-02-16 11:17
---------------	------------------

MOT test number	200647240098
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #1	2009-02-24 10:23
---------------	------------------

MOT test number	222765159034
------------------------	--------------

Result	✓ Passed
---------------	----------



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
18 August 2024

Tax status	Valid until 1 August
Days left	94
MOT expiry date	18 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2006-03-04
Last registration	2023-08-18
Complete history	See info



Registration #1	2006-03-04	9 mi
Registration #2	2009-02-24	11.350 mi
Registration #3	2010-02-16	15.280 mi
Registration #4	2011-02-15	18.805 mi
Registration #5	2012-02-15	24.635 mi
Registration #6	2013-02-18	30.121 mi
Registration #7	2014-02-12	35.231 mi
Registration #8	2015-02-12	39.678 mi
Registration #9	2016-02-11	44.549 mi
Registration #10	2017-02-09	50.563 mi
Registration #11	2017-02-09	50.563 mi
Registration #12	2018-02-08	57.312 mi
Registration #13	2019-02-08	64.061 mi
Registration #14	2020-02-08	70.810 mi
Registration #15	2021-02-08	77.559 mi
Registration #16	2022-02-08	84.308 mi
Registration #17	2023-02-08	91.057 mi
Registration #18	2024-02-08	97.806 mi
Registration #19	2025-02-08	104.555 mi
Registration #20	2026-02-08	111.304 mi
Registration #21	2027-02-08	118.053 mi
Registration #22	2028-02-08	124.802 mi
Registration #23	2029-02-08	131.551 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1804 mm
Height	1465 mm
Length	4710 mm
Wheel base	2755 mm
Kerb weight	1611 kg
Max. allowed weight	2180 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	394140