



report date: 2024-03-29

General information

Make	KIA
Model	SOUL CRDI 2
Colour	White
Year of manufacture	2010
Top speed	113 mph
0 - 60 mph	11.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	126 BHP
Max. torque	260 Nm at 1.900 rpm
Engine capacity	1.582 cc
Cylinders	4
Fuel type	Diesel
Consumption city	44.8 mpg
Consumption extra urban	61.4 mpg
Consumption combined	45.6 mpg
CO2 emission	137 g/km
CO2 label	E






Internet history

Entry 1

Date	2021-05-21
Pictures	33
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



MOT history

MOT expiry date	2024-09-06
MOT pass rate	60 %
MOT passed	12
Failed MOT tests	8
Total advice items	67
Total items failed	30

MOT #20	2023-09-07 12:38
---------	------------------

MOT test number	862275781538
-----------------	--------------

Result	✓ Passed
--------	----------

Next expiry date	2024-09-06
------------------	------------

- Advice** Offside Front Coil spring corroded (5.3.1 (b) (i))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement REAR BUSH SEPARATING (5.3.4 (a) (i))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Rear Coil spring corroded BOTH REAR SPRINGS (5.3.1 (b) (i))
- Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement REAR BUSH SEPARATING (5.3.4 (a) (i))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**MOT #19**

2023-08-30 15:46

**MOT test number**

301114615466

**Result****✗ Failed****Fail**

Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))

**Advice**

Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**Advice**

Offside Rear Coil spring corroded (5.3.1 (b) (i))

**Advice**

Offside Rear Nail in tyre

**Advice**

Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**Advice**

Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice**

Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**Advice**

Nearside Rear Coil spring corroded (5.3.1 (b) (i))

**Fail**

Offside Parking brake inoperative on one side (1.4.1 (a))

**Advice**

Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**Advice**

Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #18**

2023-08-16 13:14

**MOT test number**

705795432804

**Result****✗ Failed**

- Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Fail** Offside Rear Service brake excessively fluctuating (1.2.1 (e))
- Advice** Offside Rear Nail in tyre
- Fail** Offside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- Fail** Front Windscreen washer not working (3.5 (a))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Fail** Nearside Parking brake inoperative on one side (1.4.1 (a))
- Fail** Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))
- Minor** Offside Rear Tyre obviously under inflated (5.2.3 (l))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))
- Fail** Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))
- Fail** Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Minor** Nearside Front Tyre obviously under inflated (5.2.3 (l))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #17**

2022-07-23 08:50

**MOT test number**

301006088907

**Result**

✓ Passed

- Advice** Nearside Front Service brake binding but not excessively (1.2.1 (f))
- Advice** Fuel tank corroded
- Advice** Offside Front Track rod end ball joint has slight play (2.1.3 (b) (i))
- Advice** Brake pipe corroded, covered in grease or other material brake pipes under sealed unable to check fully (1.1.11 (c))
- Advice** Wiper washer control switch faulty

**MOT #16**

2022-07-16 07:37

**MOT test number**

878391435987

**Result**

✗ Failed

- Advice** Fuel tank corroded
- Advice** Offside Front Track rod end ball joint has slight play (2.1.3 (b) (i))
- Advice** Brake pipe corroded, covered in grease or other material brake pipes under sealed unable to check fully (1.1.11 (c))
- Fail** Nearside Front Anti-roll bar ball joint excessively worn (5.3.4 (a) (i))
- Advice** Wiper washer control switch faulty
- Advice** Nearside Front Service brake binding but not excessively (1.2.1 (f))
- Fail** Nearside Front Windscreen washer provides insufficient washer liquid (3.5 (a))

**MOT #15**

2021-07-01 10:39

**MOT test number**

479677792330

**Result**

✓ Passed

- Advice** Advice on slight pitting and grease and paint on o/s/r and n/s/r metal brake pipes to flex y and at o/s/r and n/s/r flex y brake pipes to calipers at Ferrells

**MOT #14** 2021-05-10 16:24**MOT test number** 401670498038**Result** ✗ Failed**Fail** Offside Rear Brake hose ferrule excessively corroded (1.1.12 (f) (i))**Fail** Nearside Rear Brake pipe excessively corroded (1.1.11 (c))**Fail** Nearside Rear Brake hose ferrule excessively corroded (1.1.12 (f) (i))**Fail** Offside Rear Brake pipe excessively corroded (1.1.11 (c))**MOT #13** 2020-08-07 14:26**MOT test number** 968095456813**Result** ✓ Passed**MOT #12** 2020-08-07 09:38**MOT test number** 325211688736**Result** ✗ Failed**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Fail** Central Front Tyre has a tear, caused by separation or partial failure of its structure inner sidewall (5.2.3 (d) (ii))**Fail** Offside Rear Tyre has a tear, caused by separation or partial failure of its structure inner sidewall (5.2.3 (d) (ii))**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Fail** Nearside Front Tyre has a tear, caused by separation or partial failure of its structure inner sidewall (5.2.3 (d) (ii))**Fail** Nearside Rear Tyre has a tear, caused by separation or partial failure of its structure inner sidewall (5.2.3 (d) (ii))**Fail** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

**MOT #11**

2019-08-19 15:15

**MOT test number**

575243994477

**Result**

✓ Passed

- Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #10**

2019-06-27 10:39

**MOT test number**

510464505549

**Result**

✓ Passed

- Advice** Nearside Front wiper blade slightly smearing
- Advice** Offside Front tyre cracked & perished
- Advice** Offside Rear tyre cracked & perished
- Advice** Offside Front wiper blade slightly smearing
- Advice** Nearside Front tyre cracked & perished
- Advice** Nearside Rear tyre cracked & perished

**MOT #9**

2018-07-10 13:32

**MOT test number**

831139892440

**Result**

✓ Passed

- Advice** All 4 tyres slightly cracked on tread
- Advice** All 4 flexi hoses corroded



**MOT #8** 2018-07-09 09:23**MOT test number** 416429354664**Result** ✗ Failed**Fail** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))**Advice** All 4 flexi hoses corroded**Fail** Windscreen washer not working (3.5 (a))**Advice** All 4 tyres slightly cracked on tread**MOT #7** 2017-06-13 14:59**MOT test number** 778746286977**Result** ✓ Passed**Advice** BOTH FRONT BRAKE PIPES AT CALIPERS CORRODED**Advice** BOTH REAR BRAKE PIPES AT CSLIPERS CORRODED**MOT #6** 2017-06-13 09:29**MOT test number** 668053555791**Result** ✗ Failed**Fail** Nearside Front brake disc in such a condition that it is seriously weakened on inside face (3.5.1i)**Advice** BOTH FRONT BRAKE PIPES AT CALIPERS CORRODED**Fail** Offside Front brake disc in such a condition that it is seriously weakened on inside face (3.5.1i)**Advice** BOTH REAR BRAKE PIPES AT CSLIPERS CORRODED**MOT #5** 2016-07-12 08:26**MOT test number** 167384830563**Result** ✓ Passed

**MOT #4** 2015-10-12 09:47**MOT test number** 298256411835**Result** ✓ Passed**MOT #3** 2014-10-21 14:34**MOT test number** 567294194294**Result** ✓ Passed**Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #2** 2014-10-21 12:25**MOT test number** 188084294251**Result** ✗ Failed**Fail** Nearside Front brake disc in such a condition that it is seriously weakened (3.5.1i)**Fail** Service brake: efficiency below requirements (3.7.B.7)**Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Offside Front brake disc in such a condition that it is seriously weakened (3.5.1i)**Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #1** 2013-10-21 11:38**MOT test number** 106074693262**Result** ✓ Passed



Tax & MOT check

X

Untaxed

Tax expired:  
1 August 2023

✓

MOT

Expires:  
6 September 2024

Tax status	Expired at 1 August 2023
Days left	273 days too late
MOT expiry date	6 September 2024
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra KIA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this KIA? How many owners did this KIA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this KIA had different number plates.

Number of plates	1
Current registration	
Plate since	2019-09-29
Current registration	
Plate since	2019-09-29

More info >



Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this KIA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2010-10-25
Last registration	2023-09-07
Complete history	<a href="#">See info</a>



Registration #1	2010-10-25	22 mi
Registration #2	2013-10-21	10.081 mi
Registration #3	2014-10-21	13.164 mi
Registration #4	2014-10-21	87.846 mi
Registration #5	2015-10-12	16.988 mi
Registration #6	2016-07-12	22.087 mi
Registration #7	2017-06-13	25.208 mi
Registration #8	2017-06-13	25.208 mi
Registration #9	2018-07-09	26.964 mi
Registration #10	2018-07-10	26.964 mi
Registration #11	2019-06-27	27.872 mi
Registration #12	2019-06-27	27.872 mi
Registration #13	2019-06-27	27.872 mi
Registration #14	2019-06-27	27.872 mi
Registration #15	2019-06-27	27.872 mi
Registration #16	2019-06-27	27.872 mi
Registration #17	2019-06-27	27.872 mi
Registration #18	2019-06-27	27.872 mi
Registration #19	2019-06-27	27.872 mi
Registration #20	2019-06-27	27.872 mi
Registration #21	2019-06-27	27.872 mi
Registration #22	2019-06-27	27.872 mi

More info >





Car features

The KIA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete KIA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	87%
Children	86%
Pedestrian	39%
Safety systems	86%
Overall rating	77%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1785 mm
Height	1610 mm
Length	4105 mm
Wheel base	2550 mm
Kerb weight	1345 kg
Max. allowed weight	1780 kg

Additional information

Fuel tank capacity	48 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	D4FBAH528135