





report date: 2024-03-29

General information

| Make | VOLKSWAGEN |
|---------------------|----------------|
| Model | FOX |
| Colour | Silver |
| Year of manufacture | 2010 |
| Top speed | 92 mph |
| 0 - 60 mph | 17.5 seconds |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| Power | 55 BHP |
|-------------------------|---------------------|
| Max. torque | 108 Nm at 3.000 rpm |
| Engine capacity | 1.198 сс |
| Cylinders | 3 |
| Fuel type | Petrol |
| Consumption city | 36.2 mpg |
| Consumption extra urban | 55.4 mpg |
| Consumption combined | 46.3 mpg |
| CO2 emission | 139 g/km |
| CO2 label | E |



CarCheck.co.uk page 1/12




Internet history

Entry 1

 Date
 2021-12-07


 Pictures
 20

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



MOT history

| MOT expiry date | 2024-05-05 |
|--------------------|------------|
| MOT pass rate | 85 % |
| MOT passed | 11 |
| Failed MOT tests | 2 |
| Total advice items | 2 |
| Total items failed | 2 |

| MOT #13 | 2023-04-14 11:17 |
|------------------|------------------|
| MOT test number | 645264140671 |
| Result | ✓ Passed |
| Next expiry date | 2024-05-05 |

| MOI #12 | | 2023-04-14 06.34 |
|---------------|---|------------------|
| MOT test numb | er | 475339313020 |
| Result | | × Failed |
| DANGEROUS | Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e)) | |
| DANGEROUS | Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e)) | |

| MOT #11 | 2022-04-26 09:57 |
|-----------------|------------------|
| MOT test number | 437215962854 |
| Result | ✓ Passed |

| MOT #10 | | 2022-04-26 09:57 |
|-------------------------|---|------------------|
| MOT test number | | 668575789267 |
| Result | | X Failed |
| Pass with rectification | Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii)) | |
| Pass with rectification | Offside Headlamp aim too low (4.1.2 (a)) | |

CarCheck.co.uk page 3/12



| MOT #9 | 2021-04-30 11:01 |
|-----------------|------------------|
| MOT test number | 237124050792 |
| Result | ✓ Passed |
| | |
| MOT #8 | 2020-05-06 09:50 |
| MOT test number | 362920519247 |
| Result | ✓ Passed |
| | |
| MOT #7 | 2019-05-09 09:40 |
| MOT test number | 687834468039 |
| Result | ✓ Passed |
| | |
| MOT #6 | 2018-05-04 11:54 |
| MOT test number | 639355252750 |
| Result | ✓ Passed |
| | |
| MOT #5 | 2017-05-08 11:16 |
| MOT test number | 877812302125 |
| Result | ✓ Passed |
| | |
| MOT #4 | 2016-05-05 15:19 |
| MOT test number | 792303342108 |
| Result | ✓ Passed |
| | |
| MOT #3 | 2015-05-07 14:13 |
| MOT test number | 497027525137 |
| Result | ✓ Passed |
| | |
| MOT #2 | 2014-05-01 14:35 |
| MOT test number | 878821324106 |
| Result | ✓ Passed |

CarCheck.co.uk page 4/12



MOT #1 2013-05-02 14:00

MOT test number 916962723197

Result ✓ Passed

CarCheck.co.uk page 5/12



Tax & MOT check



| Tax status | Valid until 1 February |
|------------------|------------------------|
| Days left | 278 |
| MOT expiry date | 5 May 2024 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 48 |
|---|------------|
| Band | Е |
| Single payment (12 months) | £ 180,00,- |
| Single six month payment | £ 99,00,- |
| Total payable by 12 monthly instalments | £ 189,00,- |

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report here for the results.

Damage 1


Date

Category
Type

Damage 2

Date
Category

Туре



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



More info >

Owner history

| For how long did the current and previous owner(s) have this VOLKSWAGEN? How many VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Downere. | |
|---|-------------|
| ********* | |
| *************************************** | |
| *************************************** | |
| *************************************** | |
| ,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,, | |
| *************************************** | |
| | More info > |
| Plate changes | |
| See in this check if this VOLKSWAGEN had different number plates. | |
| Number of plates | , |
| Current registration | UK NE |
| Plate since | |
| Current registration | OK SIN |
| Plate since | |
| | |

CarCheck.co.uk page 9/12



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |

Contact info


More info >

CarCheck.co.uk page 10/12



Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 15 |
| First mileage registration | 2010-05-10 |
| Last registration | 2023-04-14 |
| Complete history | See info |



| Registration #1 | 2010-05-10 | 13 mi |
|------------------|------------|-----------|
| Registration #2 | 2013-05-02 | 5.885 mi |
| Registration #3 | 2014-05-01 | 9.173 mi |
| Registration #4 | 2015-05-07 | 12.287 mi |
| Registration #5 | 2016-05-05 | 15.358 mi |
| Registration #6 | 2017-05-08 | 17.754 mi |
| Registration #7 | 2018-05-04 | 19.888 mi |
| Registration #8 | 2019-05-09 | 22.148 mi |
| Registration #9 | | 11.777 es |
| Registration #10 | | 77,777 44 |
| Registration #11 | | 91.777 es |
| Registration #12 | | 11.777 es |
| Registration #13 | | 91.777 es |
| Registration #14 | | 11.777 es |
| Registration #15 | | 11.777 ms |

More info >

CarCheck.co.uk page 11/12



Car features

| S0225 | Air conditioning |
|-------|------------------|
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

Safety ratings

| NCAP rating | ★★★★ ★ |
|-------------|-----------------|
| Video | see crash video |



Dimensions & weight

| Width | 1660 mm |
|---------------------|---------|
| Height | 1544 mm |
| Length | 3828 mm |
| Wheel base | 2465 mm |
| Kerb weight | 1069 kg |
| Max. allowed weight | 1480 kg |

Additional information

| Fuel tank capacity | 50 l |
|--------------------|-----------------------|
| Fuel delivery | Multi-Point Injection |
| Number of doors | 3 |
| CarChaeleeaule | maga 12/12 |

CarCheck.co.uk page 12/12

| Number of seats | 4 |
|-----------------|------------|
| Number of axles | 2 |
| Engine number | CHF 058721 |