



report date: 2024-03-28

General information

Make	MAZDA
Model	2 TS
Colour	Black
Year of manufacture	2011
Top speed	104 mph
0 - 60 mph	14.0 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	74 BHP
Max. torque	121 Nm at 3.500 rpm
Engine capacity	1.349 cc
Cylinders	4
Fuel type	Petrol
Consumption city	40.9 mpg
Consumption extra urban	67.3 mpg
Consumption combined	54.3 mpg
CO2 emission	115 g/km
CO2 label	C



Internet history

Entry 1

Date	2021-06-18
Pictures	6
Listing price	View report



source: **autotrader.co.uk**



MOT history

MOT expiry date	2024-09-10
MOT pass rate	71 %
MOT passed	10
Failed MOT tests	4
Total advice items	4
Total items failed	10

MOT #14	2023-08-24 15:38
MOT test number	318647930711
Result	✓ Passed
Next expiry date	2024-09-10

MOT #13	2023-08-24 15:32
MOT test number	295969775380
Result	✗ Failed
Fail	Rear Stop lamp(s) all not working (4.3.1 (a) (iii))

MOT #12	2023-08-24 07:04
MOT test number	974510513849
Result	✗ Failed
Fail	Nearside Front Tyre has ply or cords exposed split on inner side wall (5.2.3 (d) (ii))
Fail	Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords split to inner side wall (5.2.3 (d) (i))
Fail	Offside Rear Tyre has a lump, caused by separation or partial failure of its structure (5.2.3 (d) (ii))
Fail	Rear Stop lamp(s) all not working (4.3.1 (a) (iii))
Fail	Offside Front Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

**MOT #11** 2022-08-26 09:32**MOT test number** 947632345557**Result** ✓ Passed**MOT #10** 2021-09-04 11:32**MOT test number** 627002447299**Result** ✓ Passed**MOT #9** 2020-09-10 08:50**MOT test number** 805862520332**Result** ✓ Passed**MOT #8** 2020-09-09 09:05**MOT test number** 831880028619**Result** ✗ Failed**Fail** Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))**Fail** Offside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))**Fail** Nearside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))**Advice** Rear Service brake imbalance requirements only just met. It would appear that the braking system requires adjustment or repair. (1.2.1 (b) (i))**MOT #7** 2019-09-07 10:19**MOT test number** 869011378917**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #6** 2018-09-08 08:51**MOT test number** 863808381878**Result** ✓ Passed

**MOT #5** 2018-09-08 08:51**MOT test number** 352665851559**Result** ✗ Failed**Pass with rectification** Front Windscreen washer not working (3.5 (a))**MOT #4** 2017-09-05 16:18**MOT test number** 939178130023**Result** ✓ Passed**MOT #3** 2016-09-08 12:33**MOT test number** 183391695810**Result** ✓ Passed**Advice** No tread on inside of rear tyres .. tyres splitting**MOT #2** 2015-09-11 13:17**MOT test number** 812159835284**Result** ✓ Passed**MOT #1** 2014-09-11 10:18**MOT test number** 169614454262**Result** ✓ Passed**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
10 September 2024

Tax status	Valid until 1 September
Days left	125
MOT expiry date	10 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this MAZDA had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled. If not, and you buy this MAZDA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this MAZDA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2011-10-14
Last registration	2023-08-24
Complete history	See info



Registration #1	2011-10-14	18 mi
Registration #2	2014-09-11	31.066 mi
Registration #3	2015-09-11	36.410 mi
Registration #4	2016-09-08	42.292 mi
Registration #5	2017-09-05	47.385 mi
Registration #6	2018-09-08	53.322 mi
Registration #7	2018-09-08	53.322 mi
Registration #8	2019-09-07	60.494 mi
Registration #9	2020-09-07	66.494 mi
Registration #10	2021-09-07	72.494 mi
Registration #11	2022-09-07	78.494 mi
Registration #12	2023-09-07	84.494 mi
Registration #13	2024-09-07	90.494 mi
Registration #14	2025-09-07	96.494 mi
Registration #15	2026-09-07	102.494 mi
Registration #16	2027-09-07	108.494 mi

More info >



Safety ratings

NCAP rating	★★★★★
Video	see crash video



Dimensions & weight

Width	1695 mm
Height	1475 mm
Length	3885 mm
Wheel base	2490 mm
Kerb weight	1025 kg
Max. allowed weight	1455 kg

Additional information

Fuel tank capacity	42 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	5
Number of axles	2
Engine number	ZJ A22455