



HYUNDAI

EN56VXP

report date: 2024-03-29

General information

Make	HYUNDAI
Model	COUPE SIII
Colour	Silver
Year of manufacture	-
Top speed	129 mph
Gearbox	4 speed Manual

Engine & fuel consumption

Power	141 BHP
Max. torque	186 Nm at 4.500 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	25.9 mpg
Consumption extra urban	44.1 mpg
Consumption combined	35.3 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-06-27
Pictures	12
Listing price	View report



source: autotrader.co.uk



MOT history

MOT #18 2020-10-06 13:37**MOT test number** 672458409133**Result** ✓ Passed**Next expiry date** 2021-10-29

Advice Nearside Rear Anti-roll bar pin or bush worn but not resulting in excessive movement d bush (5.3.4 (a) (i))

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

Advice Offside Rear Anti-roll bar pin or bush worn but not resulting in excessive movement d bush (5.3.4 (a) (i))

MOT #17 2020-10-06 09:08**MOT test number** 362654559144**Result** ✗ Failed

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Rear Anti-roll bar pin or bush worn but not resulting in excessive movement d bush (5.3.4 (a) (i))

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Fail Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Advice Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

Advice Offside Rear Anti-roll bar pin or bush worn but not resulting in excessive movement d bush (5.3.4 (a) (i))

MOT #16 2019-10-26 13:02**MOT test number** 549212888515**Result** ✓ Passed

Advice Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #15**

2018-10-30 16:21

MOT test number

492763602610

Result

✓ Passed

- Advice** Offside Rear Anti-roll bar pin or bush worn but not resulting in excessive movement D bush (5.3.4 (a) (i))
- Advice** Engine cover fitted
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside front tyre worn out of shape on inner edge
- Advice** Nearside Rear Anti-roll bar pin or bush worn but not resulting in excessive movement D bush (5.3.4 (a) (i))
- Advice** Nearside Rear Shock absorbers has a slightly worn bush (5.3.2 (c))
- Advice** Under trays fitted
- Advice** Chip in windscreen less than 10mm

MOT #14

2018-10-13 09:34

MOT test number

903621412332

Result

✗ Failed

- Minor** Nearside Front Steering rack gaiter damaged or deteriorated, but preventing the ingress of dirt split (2.1.3 (g) (i))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Nearside Registration plate lamp does not illuminate simultaneously with the position lamps (4.7.2 (a))
- Fail** Offside Rear Parking brake inoperative on one side low effort (1.4.1 (a))
- Fail** Nearside Front Position lamp not working (4.2.1 (a))
- Fail** Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))
- Fail** Nearside Rear Parking brake inoperative on one side low effort (1.4.1 (a))
- Fail** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))

**MOT #13** 2017-10-19 09:49**MOT test number** 757570879586**Result** ✓ Passed**MOT #12** 2017-10-16 14:48**MOT test number** 751927571688**Result** ✗ Failed

- Fail** Offside Registration plate lamp not working (1.1.C.1d)
- Fail** Offside Front Brake pad(s) modified and seriously weakened (3.5.1n)
- Fail** Offside Front Body has a projection caused by damage o/s/f bumper edge sticking out past the body (6.1.C.1)
- Fail** Front Brakes imbalanced across an axle (3.7.B.5b)
- Fail** Offside Front brake caliper leaking (3.6.A.1)
- Fail** Anti-lock braking system warning lamp indicates an ABS fault (3.4.1c)

MOT #11 2016-10-13 09:31**MOT test number** 635518168931**Result** ✓ Passed

- Advice** Front bumper damaged
- Advice** Front Anti-roll bar has slight play in a pin/bush (2.4.G.2)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #10 2015-10-22 15:38**MOT test number** 476299590221**Result** ✓ Passed

- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Rear tyre has a nail in the tread



MOT #9	2015-10-16 14:50
MOT test number	220357528938
Result	✗ Failed
Fail	Offside Rear rear parking brake recording little or no effort (3.7.B.6a)
Fail	Rear parking (secondary) brakes imbalanced (3.7.B.6b)
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
Fail	Parking brake: efficiency below requirements (3.7.B.7)
Advice	Offside Rear tyre has a nail in the tread

MOT #8	2014-10-20 14:56
MOT test number	225613594229
Result	✓ Passed
Notice	Parking brake performance only just met borderline pass

MOT #7	2014-10-16 15:01
MOT test number	956019184234
Result	✗ Failed
Fail	Nearside rear parking brake recording little or no effort (3.7.B.6a)
Fail	Parking brake: efficiency below requirements (3.7.B.7)
Fail	Offside Outer Front Front constant velocity joint gaiter damaged to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)
Fail	Offside rear parking brake recording little or no effort (3.7.B.6a)

**MOT #6** 2013-10-03 15:01**MOT test number** 157406373244**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #5** 2012-10-12 12:38**MOT test number** 338366382466**Result** ✓ Passed**MOT #4** 2012-10-10 11:30**MOT test number** 275264482259**Result** ✗ Failed**Fail** Offside Front Tyre has a bulge, caused by separation or partial failure of its structure (4.1.D.1b)**MOT #3** 2012-02-20 16:42**MOT test number** 486121052067**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**MOT #2** 2011-02-24 11:07**MOT test number** 158315851069**Result** ✓ Passed**MOT #1** 2010-02-22 15:02**MOT test number** 472003250032**Result** ✓ Passed



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	EN56VXP
Plate since	2019-03-29
Current registration	EN56VXP
Plate since	2019-03-29

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2007-02-15
Last registration	2020-10-06
Complete history	See info



Registration #1	2007-02-15	15 mi
Registration #2	2010-02-22	10.599 mi
Registration #3	2011-02-24	14.141 mi
Registration #4	2012-02-20	15.428 mi
Registration #5	2012-10-10	18.054 mi
Registration #6	2012-10-12	18.054 mi
Registration #7	2013-10-03	28.155 mi
Registration #8	2014-10-16	42.416 mi
Registration #9	2014-10-20	42.528 mi
Registration #10	2015-10-16	55.287 mi
Registration #11	2016-10-16	68.054 mi
Registration #12	2017-10-16	80.821 mi
Registration #13	2018-10-16	93.588 mi
Registration #14	2019-10-16	106.355 mi
Registration #15	2020-10-16	119.122 mi
Registration #16	2021-10-16	131.889 mi
Registration #17	2022-10-16	144.656 mi
Registration #18	2023-10-16	157.423 mi
Registration #19	2024-10-16	170.190 mi
Registration #20	2025-10-16	182.957 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1760 mm
Height	1330 mm
Length	4395 mm
Wheel base	2530 mm
Kerb weight	1342 kg
Max. allowed weight	1740 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4
Number of axles	2
Engine number	G4GC6748112