



PEUGEOT




report date: 2024-03-29

General information

Make	PEUGEOT
Model	107 VERVE
Colour	Black
Year of manufacture	2009
Top speed	98 mph
0 - 60 mph	14.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	67 BHP
Max. torque	93 Nm at 3.600 rpm
Engine capacity	998 cc
Cylinders	3
Fuel type	Petrol
Consumption city	51.4 mpg
Consumption extra urban	72.4 mpg
Consumption combined	62.8 mpg
CO2 emission	106 g/km
CO2 label	B





Internet history

**Entry 1**

Date	2021-02-03
Pictures	1
Listing price	<a href="#">View report</a>



source: [autoonline.co.uk](http://autoonline.co.uk)



MOT history

MOT expiry date	2025-03-17
MOT pass rate	60 %
MOT passed	12
Failed MOT tests	8
Total advice items	34
Total items failed	12

**MOT #20** 2024-03-13 15:11

**MOT test number** 588289912598

**Result** ✓ Passed

**Next expiry date** 2025-03-17

- Advice** Child Seat fitted not allowing full inspection of adult belt
- Advice** Offside Front Tyre worn close to legal limit/worn on edge bald inner edge (5.2.3 (e))
- Advice** Nearside Front Outer Road wheel slightly distorted (5.2.2 (c) (i))

**MOT #19** 2024-03-12 14:46

**MOT test number** 375950579376

**Result** ✗ Failed

- Advice** Nearside Rear Valve stem slightly damaged perished (5.2.3 (j))
- Fail** Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
- Advice** Nearside Rear Outer Road wheel slightly distorted (5.2.2 (c) (i))
- Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm heavily perished (5.2.3 (e))
- Advice** Child Seat fitted not allowing full inspection of adult belt
- Advice** Nearside Front Outer Road wheel slightly distorted (5.2.2 (c) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge bald inner edge (5.2.3 (e))



MOT #18 2023-03-15 11:49

MOT test number 100343030983

Result ✔ Passed

- Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt
- Minor** Hazard warning switch faulty fiddly to turn on (4.4.2 (a) (i))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge tread depth low 2mm and tyre heavily perished (5.2.3 (e))
- Advice** Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))
- Advice** Nearside Rear Valve stem slightly damaged perished (5.2.3 (j))

MOT #17 2023-03-15 11:49

MOT test number 455493171067

Result ✘ Failed

- Advice** Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge tread depth low 2mm and tyre heavily perished (5.2.3 (e))
- Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt
- Minor** Hazard warning switch faulty fiddly to turn on (4.4.2 (a) (i))
- Pass with rectification** Windscreen washer provides insufficient washer liquid (3.5 (a))
- Advice** Nearside Rear Valve stem slightly damaged perished (5.2.3 (j))



MOT #16 2022-03-15 15:29

MOT test number 116595443071

Result ✔ Passed

**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing starting to perish and tread depth 3mm (5.2.3 (d) (ii))

**Advice** Offside Rear Tyre slightly damaged/cracking or perishing heavily perished, no cords visible at time of test (5.2.3 (d) (ii))

**Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt

**Advice** Nearside Front Tyre worn close to legal limit/worn on edge and tyre perishing (5.2.3 (e))

**Advice** Nearside Rear Service brake binding but not excessively (1.2.1 (f))

MOT #15 2022-03-15 15:29

MOT test number 491814292297

Result ✘ Failed

**Advice** Nearside Front Tyre worn close to legal limit/worn on edge and tyre perishing (5.2.3 (e))

**Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt

**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing starting to perish and tread depth 3mm (5.2.3 (d) (ii))

**Advice** Nearside Rear Service brake binding but not excessively (1.2.1 (f))

**Pass with rectification** Offside Front Tyre has ply or cords exposed inner edge of tread (5.2.3 (d) (ii))

**Advice** Offside Rear Tyre slightly damaged/cracking or perishing heavily perished, no cords visible at time of test (5.2.3 (d) (ii))

MOT #14 2021-03-18 10:37

MOT test number 102819113554

Result ✔ Passed

MOT #13 2020-06-19 12:07

MOT test number 816975441863

Result ✔ Passed



<b>MOT #12</b>	2020-06-16 14:14
<b>MOT test number</b>	514287726112
<b>Result</b>	✗ Failed
<b>Fail</b>	Hazard warning lamps inoperative (4.4.1 (e))
<b>Fail</b>	All direction indicators not working (4.4.1 (a) (ii))
<b>Fail</b>	Hazard warning switch inoperative (4.4.2 (a) (ii))

<b>MOT #11</b>	2019-07-23 11:48
<b>MOT test number</b>	978966269004
<b>Result</b>	✓ Passed

<b>MOT #10</b>	2019-07-23 11:48
<b>MOT test number</b>	749011340344
<b>Result</b>	✗ Failed
<b>Pass with rectification</b>	Offside Rear Position lamp not working (4.2.1 (a) (ii))

<b>MOT #9</b>	2018-07-07 09:37
<b>MOT test number</b>	616227153049
<b>Result</b>	✓ Passed

<b>MOT #8</b>	2017-07-21 14:29
<b>MOT test number</b>	622201664553
<b>Result</b>	✓ Passed

<b>MOT #7</b>	2017-07-20 12:19
<b>MOT test number</b>	756992868448
<b>Result</b>	✗ Failed
<b>Fail</b>	Nearside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)



**MOT #6** 2016-03-17 13:27

**MOT test number** 150824373573

**Result** ✔ Passed

**Advice** Front Brake pad(s) wearing thin (3.5.1g)

**MOT #5** 2016-03-12 12:27

**MOT test number** 882132047249

**Result** ✘ Failed

**Advice** Front Brake pad(s) wearing thin (3.5.1g)

**Fail** Hazard warning switch faulty (1.4.B.1d)

**Fail** Windscreen wiper does not clear the windscreen effectively (8.2.2)

**MOT #4** 2015-03-17 11:26

**MOT test number** 706356975093

**Result** ✔ Passed

**Notice** Engine covers fitted obscuring some components in the engine bay

**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #3** 2015-03-17 11:26

**MOT test number** 256446175004

**Result** ✘ Failed

**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**Notice** Engine covers fitted obscuring some components in the engine bay

**Pass with rectification** Centre Windscreen wiper does not clear the windscreen effectively (8.2.2)

**MOT #2** 2013-12-16 12:17

**MOT test number** 337550353378

**Result** ✔ Passed



<b>MOT #1</b>	2012-12-12 08:52
<b>MOT test number</b>	655517042357
<b>Result</b>	✓ Passed



Tax & MOT check

**×**  
**Untaxed**

**Tax expired:**  
1 March 2023

**✓**  
**MOT**

**Expires:**  
17 March 2025

<b>Tax status</b>	Expired at 1 March 2023
<b>Days left</b>	425 days too late
<b>MOT expiry date</b>	17 March 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	B
<b>Single payment (12 months)</b>	£ 20,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	£ 21,00,-




Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



**Vehicle valuation**

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

<b>Trade retail value</b>	£ 19,999
<b>Auction value</b>	£ 19,999
<b>Average private trade value</b>	£ 19,999

[More info >](#)



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start	End

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	LL59NHN
Plate since	2024-03-29
Current registration	LL59NHN
Plate since	2024-03-29

More info >



**Finance check**

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.


<b>Finance company</b>	REDACTED
<b>Date of agreement</b>	REDACTED
<b>Agreement type</b>	REDACTED
<b>Agreement term</b>	REDACTED
<b>Agreement number</b>	REDACTED
<b>Contact info</b>	REDACTED

**More info** >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2009-12-18
Last registration	2024-03-13
Complete history	<a href="#">See info</a>



Registration #1	2009-12-18	26 mi
Registration #2	2012-12-12	7.321 mi
Registration #3	2013-12-16	7.814 mi
Registration #4	2015-03-17	16.474 mi
Registration #5	2016-03-12	20.922 mi
Registration #6	2016-03-17	20.932 mi
Registration #7	2017-07-20	22.190 mi
Registration #8	2017-07-21	22.190 mi
Registration #9	2018-07-07	22.447 mi
Registration #10	2019-07-23	22.832 mi
Registration #11	2019-07-23	22.832 mi
Registration #12	2019-07-23	22.832 mi
Registration #13	2019-07-23	22.832 mi
Registration #14	2019-07-23	22.832 mi
Registration #15	2019-07-23	22.832 mi
Registration #16	2019-07-23	22.832 mi
Registration #17	2019-07-23	22.832 mi
Registration #18	2019-07-23	22.832 mi
Registration #19	2019-07-23	22.832 mi
Registration #20	2019-07-23	22.832 mi
Registration #21	2019-07-23	22.832 mi

[More info >](#)



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1630 mm
Height	1470 mm
Length	3430 mm
Wheel base	2340 mm
Kerb weight	875 kg
Max. allowed weight	1190 kg

Additional information

Fuel tank capacity	35 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	4

<b>Number of axles</b>	2
<b>Engine number</b>	6218893