





report date: 2024-03-28

### General information

Make	HONDA
Model	CIVIC I-DTEC SE PLUS
Colour	Brown
Year of manufacture	2014
Top speed	129 mph
0 - 60 mph	10.5 seconds
Gearbox	6 speed Manual

### Engine & fuel consumption

Power	118 BHP
Max. torque	300 Nm at 2.000 rpm
Engine capacity	1.597 cc
Cylinders	4
Fuel type	Diesel
Consumption city	70.6 mpg
Consumption extra urban	85.6 mpg
Consumption combined	78.5 mpg
CO2 emission	94 g/km
CO2 label	A



CarCheck.co.uk page 1/10



report date: 2024-03-28

## Internet history

### Entry 1

Date 2021-06-11

Pictures 15

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/10



report date: 2024-03-28

B 4	$\sim$ $-$		
10.71	$^{\prime}$	hic	tory
101	C I	1115	I OI V
	•		,

MOT expiry date	2024-02-28
MOT pass rate	67 %
MOT passed	6
Failed MOT tests	3
Total advice items	1
Total items failed	7

MOT #9	2023-02-03 10:53
MOT test number	241764331537
Result	<b>✓</b> Passed
Next expiry date	2024-02-28

MOT #8	2023-02-02 10:40
MOT test number	604840109596
Result	<b>×</b> Failed
Fail Offside Front Anti-roll bar linkage ball joint likely to become detached (5.3.4 (a) (ii))	

MOT #7	2022-03-01 10:00
MOT test number	344047040798
Result	<b>✓</b> Passed
MOT #6	2021-02-06 10:07
MOT test number	141529545909
Result	<b>✓</b> Passed
MOT #5	2020-02-20 16:35
MOT test number	468992498702
Result	<b>✓</b> Passed

CarCheck.co.uk page 3/10



report date: 2024-03-28

MOT test number

Result

Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Fail Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

MOT #3

MOT test number

628239731072

Result

Advice Offside Rear Child Seat fitted not allowing full inspection of adult belt

 MOT #2
 2017-12-28 16:00

 MOT test number
 685678183932

 Result
 ✓ Passed

MOT test number

475575333426

Result

Tyre pressure monitoring system warning lamp indicates a fault (4.1.D.4)

Fail Windscreen washer provides insufficient washer liquid (8.2.3)

Fail Offside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)

Fail Windscreen has a sticker or other obstruction encroaching into the swept area by more than 40mm outside zone 'A' (8.3.1e)

CarCheck.co.uk page 4/10



report date: 2024-03-28

### Damage history

Check the damage history for this HONDA. See if, where and when this HONDA had damage and the car repair costs. We also check if this HONDA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



#### Extra HONDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 5/10



report date: 2024-03-28

### Vehicle valuation

What is this car worth? See the vehicle value of this HONDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 6/10



Owner history

# ND64SNU

report date: 2024-03-28

For how long did the current and previous owner(s) have this HONDA? How many owners did this HONDA have? Check it in the premium report and see all owner registrations. Download the full report <a href="here">here</a> .	DΑ
THE STATE OF THE S	
***************************************	

More info >

## Plate changes

More info >

CarCheck.co.uk page 7/10



report date: 2024-03-28

### Finance check

Check if this HONDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HONDA has been settled.

If not, and you buy this HONDA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HONDA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 8/10



report date: 2024-03-28

## Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2014-12-05
Last registration	2023-02-03
Complete history	See info



Registration #1	2014-12-05	13 mi
Registration #2	2017-12-28	67.458 mi
Registration #3	2017-12-28	67.458 mi
Registration #4	2019-04-20	95.540 mi
Registration #5	2020-02-20	108.029 mi
Registration #6	2020-02-20	108.029 mi
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 esi
Registration #10		11.777 es
Registration #11		19.397 mg

More info >

CarCheck.co.uk page 9/10



report date: 2024-03-28

## Safety ratings

NCAP rating	****
Adult	94%
Children	83%
Pedestrian	69%
Safety systems	86%
Overall rating	86%
Video	see crash video



## Dimensions & weight

Width	2065 mm
Height	1470 mm
Length	4300 mm
Kerb weight	1428 kg
Max. allowed weight	1870 kg

## Additional information

Fuel tank capacity	50 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	N16A12001722

CarCheck.co.uk page 10/10