



report date: 2024-03-29

General information

| | |
|---------------------|------------------|
| Make | KIA |
| Model | SOUL CRDI SHAKER |
| Colour | Silver |
| Year of manufacture | 2013 |
| Top speed | 112 mph |
| 0 - 60 mph | 10.3 seconds |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 126 BHP |
| Max. torque | 260 Nm at 1.900 rpm |
| Engine capacity | 1.582 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 49.6 mpg |
| Consumption extra urban | 64.2 mpg |
| Consumption combined | 57.7 mpg |
| CO2 emission | 129 g/km |
| CO2 label | D |








Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-06-04 |
| Pictures | 20 |
| Listing price | View report |



source: yesauto.com



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2024-07-12 |
| MOT pass rate | 73 % |
| MOT passed | 8 |
| Failed MOT tests | 3 |
| Total advice items | 19 |
| Total items failed | 5 |

| | |
|------------------|--|
| MOT #11 | 2023-06-14 11:38 |
| MOT test number | 245194999947 |
| Result | ✓ Passed |
| Next expiry date | 2024-07-12 |
| Minor | Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i)) |

| | |
|-----------------|--|
| MOT #10 | 2023-06-07 13:36 |
| MOT test number | 441603145130 |
| Result | ✗ Failed |
| Advice | Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) |
| Fail | Offside Front Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii)) |
| Advice | Offside Rear Tyre worn close to legal limit/worn on edge 3mm (5.2.3 (e)) |
| Minor | Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i)) |
| Advice | Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) |
| Advice | Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i)) |

**MOT #9** 2022-06-22 13:07**MOT test number** 506428583818**Result** ✓ Passed**Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Brake disc worn, pitted or scored, but not seriously weakened All (1.1.14 (a) (ii))**Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #8** 2022-06-21 13:42**MOT test number** 391888251056**Result** ✗ Failed**Fail** Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))**Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Brake disc worn, pitted or scored, but not seriously weakened All (1.1.14 (a) (ii))**Fail** Offside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt Split (6.1.7 (g) (ii))**Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #7** 2021-07-13 11:39**MOT test number** 978147730327**Result** ✓ Passed**Minor** Central Windscreen damaged but not adversely affecting driver's view small stonechip (3.2 (a) (i))

**MOT #6** 2021-06-29 09:17**MOT test number** 149375373978**Result** ✗ Failed**Minor** Nearside Rear Registration plate lamp insecure (4.7.1 (c) (i))**Fail** Nearside Front Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Minor** Central Windscreen damaged but not adversely affecting driver's view small stonechip (3.2 (a) (i))**Fail** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))**MOT #5** 2020-10-19 10:43**MOT test number** 495625102572**Result** ✓ Passed**Advice** Offside Rear Brake hose has slight corrosion to ferrule axle (1.1.12 (f) (i))**Advice** Nearside Rear Brake hose has slight corrosion to ferrule axle (1.1.12 (f) (i))**MOT #4** 2019-10-24 14:01**MOT test number** 278660872080**Result** ✓ Passed**MOT #3** 2018-10-26 14:31**MOT test number** 396411804767**Result** ✓ Passed**MOT #2** 2017-10-12 10:04**MOT test number** 700717179119**Result** ✓ Passed



| | |
|-----------------|------------------|
| MOT #1 | 2016-10-31 10:38 |
| MOT test number | 614614484309 |
| Result | ✓ Passed |



Tax & MOT check

✓
Taxed
Tax due:
1 July 2024

✓
MOT
Expires:
12 July 2024

| | |
|-------------------------|---------------------------------|
| Tax status | Valid until 1 July |
| Days left | 62 |
| MOT expiry date | 12 July 2024 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|--|------------|
| Vehicle class | 49 |
| Band | D |
| Single payment (12 months) | £ 150,00,- |
| Single six month payment | £ 82,50,- |
| Total payable by 12 monthly instalments | £ 157,50,- |



Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra KIA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this KIA? How many owners did this KIA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|------------|
| Owner | Start date |
| Owner | Start date |
| Owner | Start date |
| Owner | Start date |
| Owner | Start date |
| Owner | Start date |
| Owner | Start date |

More info >

Plate changes

See in this check if this KIA had different number plates.

| | |
|----------------------|----------------|
| Number of plates | 1 |
| Current registration | YP63APK |
| Plate since | 2019-03-29 |
| Current registration | YP63APK |
| Plate since | 2019-03-29 |

More info >



Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this KIA is financed.

| | | |
|-------------------|------------|------|
| Finance company | XXXXXXXXXX | XXXX |
| Date of agreement | XXXXXXXXXX | XXXX |
| Agreement type | XXXXXXXXXX | XXXX |
| Agreement term | XXXXXXXXXX | XXXX |
| Agreement number | XXXXXXXXXX | XXXX |
| Contact info | XXXXXXXXXX | XXXX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 13 |
| First mileage registration | 2013-10-31 |
| Last registration | 2023-06-14 |
| Complete history | See info |



| | | |
|------------------|------------|-----------|
| Registration #1 | 2013-10-31 | 29 mi |
| Registration #2 | 2016-10-31 | 18.382 mi |
| Registration #3 | 2017-10-12 | 23.773 mi |
| Registration #4 | 2018-10-26 | 33.929 mi |
| Registration #5 | 2019-10-24 | 42.428 mi |
| Registration #6 | 2020-10-19 | 50.895 mi |
| Registration #7 | 2020-10-19 | 50.895 mi |
| Registration #8 | 2020-10-19 | 50.895 mi |
| Registration #9 | 2020-10-19 | 50.895 mi |
| Registration #10 | 2020-10-19 | 50.895 mi |
| Registration #11 | 2020-10-19 | 50.895 mi |
| Registration #12 | 2020-10-19 | 50.895 mi |
| Registration #13 | 2020-10-19 | 50.895 mi |

More info >



Car features

The KIA factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete KIA factory list for this vehicle [here](#).

More info >

Safety ratings

| | |
|----------------|---------------------------------|
| NCAP rating | ★★★★★ |
| Adult | 87% |
| Children | 86% |
| Pedestrian | 39% |
| Safety systems | 86% |
| Overall rating | 77% |
| Video | see crash video |



Dimensions & weight

| | |
|---------------------|---------|
| Width | 1785 mm |
| Height | 1610 mm |
| Length | 4120 mm |
| Wheel base | 2550 mm |
| Kerb weight | 1444 kg |
| Max. allowed weight | 1790 kg |

Additional information

| | |
|--------------------|------------------|
| Fuel tank capacity | 48 l |
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats | 5 |

| | |
|------------------------|--------------|
| Number of axles | 2 |
| Engine number | D4FBBH701633 |