





report date: 2024-03-28

General information

Make	MERCEDES
Model	ML ML 320 CDI EDITION 10
Colour	Silver
Year of manufacture	2008
Top speed	127 mph
Gearbox	7 speed automatic

Engine & fuel consumption

Power	221 BHP
Max. torque	510 Nm at 2.800 rpm
Engine capacity	2.987 сс
Cylinders	6
Fuel type	Diesel
Consumption city	22.1 mpg
Consumption extra urban	36.2 mpg
Consumption combined	29.4 mpg
CO2 emission	254 g/km
CO2 label	L



CarCheck.co.uk page 1/13



Internet history

Entry 1

Date 2021-08-21

Pictures 19

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/13



MOT history

MOT expiry date	2024-07-20
MOT pass rate	93 %
MOT passed	13
Failed MOT tests	1
Total advice items	22
Total items failed	0

MOT #14	2023-07-05 13:44
MOT test number	267819251713
Result	✓ Passed
Next expiry date	2024-07-20

MOT #13		2022-07-21 09:14
MOT test	number	336392356361
Result		✓ Passed
Advice	Front Brake disc worn, but not excessively offside/nearside (1.1.14 (a) (i))	
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))	
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Minor	Nearside Front Outer Drive shaft joint constant velocity boot severely deteriors	ated (6.1.7 (g) (i))
Advice	Nearside front tyre worn on edges	

CarCheck.co.uk page 3/13



MOT #12 2021-07-12 09:55

MOT test number 515439066531

Result ✓ Passed

Minor Nearside Rear Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt

Advice Nearside Front Brake hose slightly deteriorated (1.1.12 (b) (ii))

MOT #11 2020-07-20 14:07

MOT test number 555127021815

Result \square Passed

MOT #10 2020-07-20 10:23

MOT test number 915792121450

Result X Failed

MAJOR Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))

MOT #9 2019-04-02 09:16

MOT test number 543637697888

Result

Passed

Advice Front Items removed from driver's view prior to test

Minor

Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt

MOT #8 2018-04-20 13:51

MOT test number 908097916069

CarCheck.co.uk page 4/13



Result

EX08JVC report date: 2024-03-28

✓ Passed

MOT #7 2017-04-15 09:37

409735583064 **MOT** test number

✓ Passed Result

Advice Offside Front Shock absorber has a light misting of oil (2.7.3)

Advice Nearside Front Shock absorber has a light misting of oil (2.7.3)

Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt

2016-04-16 13:43 **MOT #6**

MOT test number 248310868240

Result ✓ Passed

MOT #5 2015-04-18 11:22

MOT test number 267638205463

Advice Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

Notice

Offside front tyre has cut on the inner sidewall

Notice Both front tyres are wearing on the inner edge

MOT #4 2014-03-01 12:00

MOT test number 507420764049

Result ✓ Passed

MOT #3 2013-03-04 13:10

MOT test number 699043563041

Result ✓ Passed

MOT #2 2012-03-30 10:00

788890392062 **MOT** test number

Result Passed

CarCheck.co.uk page 5/13



MOT #1

MOT test number

487850791094

Result

Advice Rear Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 6/13



Tax & MOT check



Tax status	Valid until 1 October
Days left	156
MOT expiry date	20 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	L
Single payment (12 months)	£ 675,00,-
Single six month payment	£ 371,25,-
Total payable by 12 monthly instalments	£ 708,75,-

CarCheck.co.uk page 7/13



Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report here for the results.

Damage 1

Date	
Category	
Туре	

Damage 2	
Date	
Category	



Extra MERCEDES salvage check



Type

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



Owner history

Owner History	
For how long did the current and previous owner(s) have this MERCEDES? How many own MERCEDES have? Check it in the premium report and see all owner registrations. Downlo here.	
2000000	
,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	

Plate changes	More info >
See in this check if this MERCEDES had different number plates.	
Number of plates	,
Current registration	NK NK
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 10/13



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MERCEDES is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 11/13



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2008-03-01
Last registration	2023-07-05
Complete history	See info



Registration #1	2008-03-01	25 mi
Registration #2	2011-03-31	36.821 mi
Registration #3	2012-03-30	50.644 mi
Registration #4	2013-03-04	61.374 mi
Registration #5	2014-03-01	67.259 mi
Registration #6	2015-04-18	73.682 mi
Registration #7	2016-04-16	80.258 mi
Registration #8	2017-04-15	87.892 mi
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		71.777 es
Registration #13		11.777 es
Registration #14		71.777 es
Deviatoration #15		
Registration #15		11.777-46

More info >

page 12/13 CarCheck.co.uk



Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1911 mm
Height	1815 mm
Length	4780 mm
Wheel base	2915 mm
Kerb weight	2185 kg
Max. allowed weight	2830 kg

Additional information

Fuel tank capacity	95 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	64294040672802

CarCheck.co.uk page 13/13