





report date: 2024-03-28

#### General information

Make	FORD
Model	MONDEO TITANIUM TDCI
Colour	Red
Year of manufacture	2015
Top speed	140 mph
0 - 60 mph	8.3 seconds
Gearbox	6 speed Manual

### Engine & fuel consumption

Power	177 BHP
Max. torque	400 Nm at 2.000 rpm
Engine capacity	1.997 сс
Cylinders	4
Fuel type	Diesel
Consumption city	55.4 mpg
Consumption extra urban	70.6 mpg
Consumption combined	64.2 mpg
CO2 emission	117 g/km
CO2 label	С



CarCheck.co.uk page 1/12



report date: 2024-03-28


# Internet history

#### Entry 1

Date 2021-12-03


Pictures 25

Listing price <u>View report</u>









source: yesauto.com

CarCheck.co.uk page 2/12



ST15ORS report date: 2024-03-28

MOT history

Fail

MOT expiry date	2024-11-16
MOT pass rate	50 %
MOT passed	6
Failed MOT tests	6
Total advice items	10
Total items failed	14

MOT #12	2023-11-01 13:32
MOT test number	558620956677
Result	✓ Passed
Next expiry date	2024-11-16
Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.	.1.14 (a) (ii))

MOT #11	2022-10-31 14:11
MOT test number	434323761443
Result	✓ Passed
MOT #10	2022-10-28 14:19
MOT test number	612139861700
Result	<b>×</b> Failed

MOT #9	2021-11-17 16:10
MOT test number	742968631008
Result	✓ Passed

Nearside Front Lower Suspension arm ball joint likely to become detached (5.3.4 (a) (ii))

CarCheck.co.uk page 3/12



**MOT #8** 

Result

ST15ORS

report date: 2024-03-28

2021-11-15 09:06

× Failed

MOT test number 831965595171

Result X Failed

Fail Offside Front Bonnet cannot be secured in the closed position catch not working (3.1 (b) (i))

**MOT #7** 2021-09-27 15:48

**MOT test number** 530841762844

**Fail** Registration plate lamp inoperative in the case of a single lamp or all lamps Both lamps (4.7.1 (b) (ii))

Fail Nearside Rear Tyre has a bulge, caused by separation or partial failure of its structure Out of shape (5.2.3 (d) (ii))

**Fail** Nearside Rear Upper Shock absorbers has an excessively worn bush (5.3.2 (c))

**Advice** Nearside Rear Inner Anti-roll bar linkage pin or bush worn but not resulting in excessive movement D bush (5.3.4 (a) (i))

Fail Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))

Fail Windscreen washer provides insufficient washer liquid (3.5 (a))

Advice Nearside Rear Lower Suspension component pin or bush slightly worn Rose/Hub bush (5.3.4 (a) (i))

Fail Nearside Front Position lamp not working (4.2.1 (a) (ii))

MOT #6 2020-09-24 14:37

MOT test number 331220513310

Result 

Passed

MOT #5 2020-09-23 13:12

MOT test number 243757525712

**Result** ★ Failed

Fail Nearside Front Lower Steering linkage ball joint has excessive play (2.1.3 (b) (i))

Fail Nearside Front Bumper damaged and likely to cause injury when grazed or contacted (6.1.4 (a) (i))

CarCheck.co.uk page 4/12



report date: 2024-03-28

MOT #4

MOT test number

711027145046

Result

Advice Upper engine cover fitted

**MOT** #3 2019-04-24 09:01 **MOT** test number 212863603416 Result **X** Failed Fail Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e)) **Advice** Upper engine cover fitted **Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) Fail Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e)) **Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) **Advice** Cable wiring to cat temp sensor insecure

MOT #2

MOT test number

170883879098

Result

Advice Front Brake pad(s) wearing thin (3.5.1g)

MOT #1

MOT test number

895337904653

Result

Pass with rectification

Nearside Front Headlamp aim too far to the right (1.8)

Advice

Front Brake pad(s) wearing thin (3.5.1g)

Pass with rectification

Offside Front Headlamp aim too far to the right (1.8)

CarCheck.co.uk page 5/12



report date: 2024-03-28

#### Tax & MOT check



Tax status	valid until 1 january
Days left	248
MOT expiry date	16 November 2024
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	49
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-

CarCheck.co.uk page 6/12



report date: 2024-03-28

#### Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-28

#### Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

ST15ORS

report date: 2024-03-28

# For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report <a href="here">here</a>. More info

## Plate changes

More info >

CarCheck.co.uk page 9/12



ST15ORS report date: 2024-03-28

Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-28

# Mileage check

Registration #14

Odometer	In miles
Mileage registrations	14
First mileage registration	2015-05-15
Last registration	2023-11-01
Complete history	See info



Registration #1	2015-05-15	14 mi
Registration #2	2018-04-30	61.301 mi
Registration #3	2018-04-30	61.301 mi
Registration #4	2019-04-24	82.364 mi
Registration #5	2019-04-24	82.367 mi
Registration #6	2020-09-23	113.173 mi
Registration #7	2020-09-24	113.175 mi
Registration #8		71.777 es
Registration #9		11.777 mi
Registration #10		11.777 es
Registration #11		9.77 es
Registration #12		0.00 44
Registration #13		11.777 mi

mn.n.n

More info >

77.777 86

CarCheck.co.uk page 11/12



report date: 2024-03-28

# Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

# Safety ratings

NCAP rating	****
Adult	86%
Children	82%
Pedestrian	66%
Safety systems	66%
Overall rating	77%
Video	see crash video



# Dimensions & weight

Width	1852 mm
Height	1482 mm
Length	4871 mm
Wheel base	2850 mm
Kerb weight	1578 kg
Max. allowed weight	2270 kg

# Additional information

Fuel tank capacity	62 I	
Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5	page 12/12

Number of axles 2

**Engine number** FK22521