





report date: 2024-03-28

## General information

Make	VOLVO
Model	C30 D DRIVE R-DESIGN
Colour	Red
Year of manufacture	2009
Top speed	118 mph
0 - 60 mph	10.7 seconds
Gearbox	5 speed Manual

## Engine & fuel consumption

Power	109 BHP
Max. torque	240 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	49.6 mpg
Consumption extra urban	74.3 mpg
Consumption combined	62.8 mpg
CO2 emission	119 g/km
CO2 label	С



CarCheck.co.uk page 1/12



## Internet history

## Entry 3

Date 2022-02-11

Pictures 6

Listing price <u>View report</u>









source: autotrader.co.uk

#### Entry 2

Date	2022-02-03
Pictures	13

11000100

Listing price <u>View report</u>









source: cargurus.co.uk

#### Entry 1

Date	2022-02-02
Pictures	1

Listing price <u>View report</u>



source: autotrader.co.uk

CarCheck.co.uk page 2/12



# MOT history

MOT expiry date	2024-12-22
MOT pass rate	100 %
MOT passed	12
Failed MOT tests	0
Total advice items	15
Total items failed	0

MOT #12	2023-12-15 10:54
MOT test number	945032098547
Result	<b>✓</b> Passed
Next expiry date	2024-12-22

MOT #11	2022-12-10 12:35
MOT test number	696229286374
Result	✓ Passed
Advice Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))	

MOT #10	2021-12-23 10:54
MOT test number	268606615769
Result	<b>✓</b> Passed
Advice Oil leak, but not excessive (8.4.1 (a) (i))	

MOT #9	2020-12-07 13:58
MOT test number	483942876546
Result	✓ Passed
Advice Oil leak, but not excessive (8.4.1 (a) (i))	

CarCheck.co.uk page 3/12



MOT #8 2019-05-24 16:22

**MOT test number** 232931391700

MOT #7 2018-06-04 14:56

**MOT test number** 751047390310

**Result** ✓ Passed

**MOT #6** 2017-06-13 07:52

MOT test number 438213386408

**Result** 
✓ Passed

Advice N/s front tyre wearing low and wearing on inner edge

**Advice** O/s rear rim slightly buckled

**Advice** O/s front tyre wearing on inner edge

MOT #5 2016-06-13 12:02

MOT test number 792430261138

Result \( \sqrt{Passed} \)

**Advice** O/s/r tyre 2.5mm

**Advice** O/s/r rim slightly buckled

MOT #4 2015-06-22 15:09

MOT test number 577893375103

**Result** ✓ Passed

Advice Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

**Notice** Damage to n/s/f road wheel inner rim

Advice Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

CarCheck.co.uk page 4/12



MOT #3

MOT test number

827851334364

Result

Notice Damage to o/s/r road wheel inner rim

 MOT #2
 2013-11-25 17:15

 MOT test number
 265729823323

 Result
 ✓ Passed

MOT #1 2012-11-05 09:17

MOT test number 367040712387

Result ✓ Passed

**Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)

**Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)

**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 5/12



# Tax & MOT check



Tax status	Valid until 1 April
Days left	336
MOT expiry date	22 December 2024
Full MOT history	See MOT history

### Tax calculation

Vehicle class	49
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-

CarCheck.co.uk page 6/12



### Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report <a href="here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



### Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



# Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners have? Check it in the premium report and see all owner registrations. Download the full r	
***************************************	
*******	
***************************************	
	More info >
Plate changes	
See in this check if this VOLVO had different number plates.	
Number of plates	,
Current registration	OK OK
Plate since	
Current registration	OK SIE
Plate since	
	More info >

CarCheck.co.uk page 9/12



### Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLVO is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >


CarCheck.co.uk page 10/12



# Mileage check

Registration #16

Odometer	In miles
Mileage registrations	16
First mileage registration	2009-11-04
Last registration	2023-12-15
Complete history	See info



Registration #1	2009-11-04	6 mi
Registration #2	2012-11-05	64.479 mi
Registration #3	2013-11-25	84.456 mi
Registration #4	2014-11-27	95.100 mi
Registration #5	2015-06-22	98.682 mi
Registration #6	2016-06-13	104.676 mi
Registration #7	2017-06-13	111.301 mi
Registration #8	2018-06-04	118.690 mi
Registration #9		11.177 es
Registration #10		11.777 es
Registration #11		9.70 es
Registration #12		77.777 es
Registration #13		9.777 es
Registration #14		11.777 es
Registration #15		11.777 es

7075.75.75

More info >

77. 777 mg

CarCheck.co.uk page 11/12



# Car features

S0225	Air conditioning
S0295	
50482	
S0501	
S0566	
S0567	
50569	

# Safety ratings

NCAP rating	****
Video	see crash video



# Dimensions & weight

Width	1782 mm
Height	1447 mm
Length	4252 mm
Wheel base	2640 mm
Kerb weight	1381 kg
Max. allowed weight	1780 kg

# Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats CarCheck.co.uk	4 page 12/12

Number of axles 2
Engine number 704037