





report date: 2024-03-28

General information

Make	AUDI
Model	Q7 TDI QUATTRO S LINE
Colour	Grey
Year of manufacture	2008
Top speed	134 mph
0 - 60 mph	8.5 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	240 BHP
Max. torque	550 Nm at 1.500 rpm
Engine capacity	2.967 сс
Cylinders	6
Fuel type	Diesel
Consumption city	21.9 mpg
Consumption extra urban	34.9 mpg
Consumption combined	28.8 mpg
CO2 emission	260 g/km
CO2 label	М



CarCheck.co.uk page 1/14



Internet history

Entry 2


Date 2022-12-23

Pictures 42

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 1

Date 2021-06-30

Pictures 13

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/14



MOT history

MOT expiry date	2024-07-19
MOT pass rate	67 %
MOT passed	12
Failed MOT tests	6
Total advice items	36
Total items failed	9

MOT #18		2023-07-20 15:11
MOT test	number	768681256674
Result		✓ Passed
Next exp	iry date	2024-07-19
Advice	Oil leak, but not excessive Gearbox (8.4.1 (a) (i))	
Advice	Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))	
Minor (i))	Offside Registration plate lamp inoperative in the case of multiple lamps or	light sources (4.7.1 (b)
Advice	Oil leak, but not excessive Engine (8.4.1 (a) (i))	
Advice	Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))	

MOT #17	2023-07-14 15:32
MOT test number	959255974870
Result	X Failed
Fail Nearside Front Upper Suspension arm ball joint excessively worn (5.3.4 (a) (i))	
Advice Oil leak, but not excessive Gearbox (8.4.1 (a) (i))	
Minor Nearside Registration plate lamp inoperative in the case of multiple lamps or (b) (i))	light sources (4.7.1
Advice Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))	
Advice Oil leak, but not excessive Engine (8.4.1 (a) (i))	
Advice Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))	

CarCheck.co.uk page 3/14



MOT #16 2023-07-12 09:59

MOT test number 491743315375

Result X Failed

Fail Nearside Front Upper Suspension arm ball joint excessively worn (5.3.4 (a) (i))

Advice Oil leak, but not excessive Gearbox (8.4.1 (a) (i))

Advice Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))

Minor Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1

(b) (i))

Advice Oil leak, but not excessive Engine (8.4.1 (a) (i))

Advice Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))

MOT #15 2022-07-08 09:13

MOT test number 150497814221

Result ✓ Passed

Advice Front brake discs in poor condition

Advice Suspension light on

Advice Eml light came on then went off during test

MOT #14 2022-07-07 11:14

MOT test number 978145326016

Result ★ Failed

Advice Eml light came on then went off during test

Advice Front brake discs in poor condition

Fail Offside Parking brake inoperative on one side (1.4.1 (a))

Advice Suspension light on

CarCheck.co.uk page 4/14



MOT #13 2021-05-14 10:13

MOT test number 722417414240

Advice Parking brake lever defective but can be satisfactorily operated (1.1.6 (d))

Advice Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #12 2021-05-08 10:02

MOT test number 523217454562

Result X Failed

Minor Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Fail Parking brake efficiency below requirements (1.4.2 (a) (i))

Advice Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Nearside Rear Service brake binding but not excessively (1.2.1 (f))

MOT #11 2019-04-05 09:12

MOT test number 437951499894

Result \(\sqrt{Passed} \)

Advice Nearside Front Suspension arm ball joint has slight play upper arm (5.3.4 (a) (i))

Advice Exhaust joint corroded between front and middle section

MOT #10 2018-04-25 14:03

MOT test number 890727449493

Result \rightarrow Passed

CarCheck.co.uk page 5/14



MOT #9

MOT test number

301293661166

Result

Fail Nearside Front Tyre has ply or cords exposed (4.1.D.1b)

Fail Parking brake: efficiency below requirements (3.7.C.1b)

MOT #8

MOT test number

Result

MOT #7

2016-04-12 08:11

MOT test number

117865920287

Result

Advice Front Tyre worn close to the legal limit (4.1.E.1)

MOT #6

MOT test number

129237305134

Result

Notice Nearside rear tyre damaged

MOT #5

MOT test number

Result

Notice Nearside rear tyre outer sidewall cut

2014-04-05 11:33

697735594018

✓ Passed

 MOT #4
 2013-04-19 14:18

 MOT test number
 199449303116

 Result
 ✓ Passed

CarCheck.co.uk page 6/14



MOT #3 2013-04-18 18:00

MOT test number 736408103194

Result X Failed

Fail Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)

Fail Nearside Rear Lower Stop lamp emits other than a steady red light (1.2.1e)

Fail Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)

MOT #2 2012-05-11 13:32

MOT test number 859972832126

Result ✓ Passed

MOT #1 2011-05-16 11:56

MOT test number 838196831177

Result \(\sqrt{Passed} \)

Advice Front Brake pad(s) wearing thin (3.5.1g)

Advice Front Tyre worn close to the legal limit (4.1.E.1)

Advice Rear Brake pad(s) wearing thin (3.5.1g)

CarCheck.co.uk page 7/14



Tax & MOT check



Tax status	Valid until 1 February
Days left	278
MOT expiry date	19 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	M
Single payment (12 months)	£ 695,00,-
Single six month payment	£ 382,25,-
Total payable by 12 monthly instalments	£ 729,75,-

CarCheck.co.uk page 8/14



Y3TOC

report date: 2024-03-28

Damage history

Check the damage history for this AUDI. See if, where and when this AUDI had damage and the car repair costs. We also check if this AUDI was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra AUDI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/14



Vehicle valuation

What is this car worth? See the vehicle value of this AUDI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 10/14



Owner history

Owner mistory		
For how long did the current and previous owner(s) have this AUDI? How many owners d Check it in the premium report and see all owner registrations. Download the full report		?
THE STATE OF THE S		

THE STREET STREET		

	More info >	
Plate changes		
See in this check if this AUDI had different number plates.		
Number of plates		
Current registration	OK NE	
Plate since		
Current registration	UK NE	
Plate since		
	More info >	>

CarCheck.co.uk page 11/14



Finance check

Check if this AUDI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this AUDI has been settled.

If not, and you buy this AUDI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this AUDI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Control info	

Contact info

More info >

CarCheck.co.uk page 12/14



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2008-03-12
Last registration	2023-07-20
Complete history	See info



Registration #1	2008-03-12	13 mi
Registration #2	2011-05-16	32.360 mi
Registration #3	2012-05-11	38.577 mi
Registration #4	2013-04-18	44.127 mi
Registration #5	2013-04-19	44.127 mi
Registration #6	2014-04-05	49.032 mi
Registration #7	2015-04-17	54.025 mi
Registration #8	2016-04-12	55.877 mi
Registration #9	2017-04-18	56.986 mi
Registration #10	2018-04-24	57.677 mi
Registration #11	2018-04-25	57.678 mi
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		11.777 es
Registration #19		11.777 es
Registration #20		11.777 es
Registration #21		11.777 esi

More info >

CarCheck.co.uk page 13/14



Car features

50225	Air conditionir
60295	
60482	
0501	
0566	
0567	
60569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1983 mm
Height	1737 mm
Length	5086 mm
Wheel base	3002 mm
Kerb weight	2325 kg
Max. allowed weight	3120 kg

Additional information

Fuel tank capacity	100
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	7 page 14/14

Number of axles 2

Engine number CAS 025689