





report date: 2024-03-28

General information

Make	MAZDA
Model	MX-5 SPORT NAV
Colour	Silver
Year of manufacture	2016
Top speed	133 mph
0 - 60 mph	7.3 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	158 BHP
Max. torque	200 Nm at 4.600 rpm
Engine capacity	1.998 сс
Cylinders	4
Fuel type	Petrol
Consumption city	30.4 mpg
Consumption extra urban	51.4 mpg
Consumption combined	40.9 mpg
CO2 emission	161 g/km
CO2 label	G



CarCheck.co.uk page 1/11



report date: 2024-03-28

Internet history

Entry 2

Date 2021-08-18

Pictures 25

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 1

Date 2021-08-18

Pictures 25

Listing price <u>View report</u>









source: heycar.co.uk

CarCheck.co.uk page 2/11



MOT #5

SS16MME

report date: 2024-03-28

2021-03-25 14:00

MOT history	
MOT expiry date	2024-12-13
MOT pass rate	75 %
MOT passed	6
Failed MOT tests	2
Total advice items	10
Total items failed	2
MOT #8	2023-12-12 09:54
MOT test number	959612254823
Result	✓ Passed
Next expiry date	2024-12-13
MOT #7	2022-11-30 10:29
MOT test number	895427953619
Result	✓ Passed
MOT #6	2021-12-14 16:38
MOT test number	673692520756
Result	✓ Passed

MOT test number	572434205073
Result	✓ Passed
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

CarCheck.co.uk page 3/11



MOT #4

Result

Result

SS16MME

report date: 2024-03-28

2021-03-25 14:00

✓ Passed

× Failed

MOT test number 987623436222

Result X Failed

Pass with rectification Windscreen washer not working (3.5 (a))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #3 2020-03-25 12:08

MOT test number 644217835679

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

Advice Nearside Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #2 2020-03-25 12:08

MOT test number 224341860064

Pass with rectification Windscreen washer provides insufficient washer liquid (3.5 (a))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #1 2019-03-25 14:34

MOT test number 598203142439

Result \(\sqrt{Passed} \)

CarCheck.co.uk page 4/11



SS16MME report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 December
Days left	216
MOT expiry date	13 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-

CarCheck.co.uk page 5/11



report date: 2024-03-28

Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	



Extra MAZDA salvage check



Type

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



SS16MME report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-28

Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners have? Check it in the premium report and see all owner registrations. Download the full report and see all owner registrations.	
······································	
2000000	
200000000	
	More info >
Plate changes	
See in this check if this MAZDA had different number plates.	
Number of plates	
Current registration	NK SIE
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 8/11



SS16MME report date: 2024-03-28

Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MAZDA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2016-04-28
Last registration	2023-12-12
Complete history	See info



Registration #1	2016-04-28	15 mi
Registration #2	2019-03-25	16.354 mi
Registration #3	2020-03-25	30.523 mi
Registration #4	2020-03-25	30.523 mi
Registration #5	2021-03-25	34.459 mi
Registration #6	2021-03-25	34.459 mi
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 esi
Registration #10		11.777 es
Registration #11		10.777 es

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-28

Safety ratings

NCAP rating	****
Adult	84%
Children	80%
Pedestrian	93%
Safety systems	64%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	1735 mm
Height	1230 mm
Length	3915 mm
Wheel base	2310 mm
Kerb weight	1000 kg
Max. allowed weight	1260 kg

Additional information

Fuel tank capacity	45 I
Fuel delivery	Direct Injection
Number of doors	2
Number of seats	2
Number of axles	2
Engine number	PE 30865366

CarCheck.co.uk page 11/11