





report date: 2024-03-29

General information

Make	RENAULT
Model	CLIO DYNAMIQUE MEDIANAV ENERGY TCE S/S
Colour	Red
Year of manufacture	2014
Top speed	113 mph
0 - 60 mph	12.2 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	90 BHP
Max. torque	135 Nm at 2.500 rpm
Engine capacity	899 cc
Cylinders	3
Fuel type	Petrol
Consumption city	51.4 mpg
Consumption extra urban	72.4 mpg
Consumption combined	62.8 mpg
CO2 emission	104 g/km
CO2 label	В



CarCheck.co.uk page 1/14



report date: 2024-03-29


Internet history

Entry 2

Date 2023-02-18

Pictures 20

Listing price <u>View report</u>









source: autotrader.co.uk

Entry 1

Date	2021-06-08
Pictures	20

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/14



report date: 2024-03-29

MOT history

MOT expiry date	2025-04-26
MOT pass rate	60 %
MOT passed	9
Failed MOT tests	6
Total advice items	32
Total items failed	14

MOT #15		2024-04-27 12:08
MOT test	number	731101109379
Result		✓ Passed
Next expi	ry date	2025-04-26
Advice	Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11	(c))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Rear Service brake binding but not excessively (1.2.1 (f))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #14		2024-04-25 13:40
MOT test	number	217916434632
Result		× Failed
Advice	Offside Rear Service brake binding but not excessively (1.2.1 (f))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Fail O	ffside Rear Parking brake inoperative on one side (1.4.1 (a))	
Advice	Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice	Items removed from driver's view prior to test	
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

CarCheck.co.uk page 3/14



report date: 2024-03-29

 MOT #13
 2023-04-19 10:22

 MOT test number
 543622207885

 Result
 ✓ Passed

Advice Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT test number

Result

Advice Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Fail Nearside Parking brake inoperative on one side (1.4.1 (a))

Fail Parking brake efficiency below requirements (1.4.2 (a) (i))

MOT #11 2022-06-25 12:45
MOT test number 336016905201
Result Passed

MOT #10

MOT test number

8 331198754063

Result

Fail Offside Stop lamp(s) not working (4.3.1 (a) (ii))

Fail Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))

Fail Brake lever has insufficient reserve travel (1.1.2 (a))

Fail Offside Front Road wheel fixing missing (5.2.1 (a) (i))

Fail Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))

Fail Parking brake efficiency below requirements (1.4.2 (a) (i))

CarCheck.co.uk page 4/14



Result

MOT test number

Result

SM63FVR

report date: 2024-03-29

Passed

220408150714

Passed

MOT #9 2021-06-23 12:00

MOT test number 639578281214

Result ✓ Passed

Advice Rear Seat belt webbing slightly damaged or frayed Middle section belt frayed (7.1.2 (b) (ii))

MOT #8 2021-01-04 16:11

MOT test number 438529965092

Advice Central Rear Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))

Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt

Advice Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

MOT #7 2021-01-04 11:47

MOT test number 968300781545

Result × Failed

Advice Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

Fail Nearside Rear Parking brake inoperative on one side (1.4.1 (a))

Advice Central Rear Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))

Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt

MOT #6 2020-02-12 13:11

·

Advice Brake disc worn, pitted or scored, but not seriously weakened both front (1.1.14 (a) (ii))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Rear Service brake binding but not excessively (1.2.1 (f))

CarCheck.co.uk page 5/14



report date: 2024-03-29

MOT #5 2020-02-08 15:52 399052054816 **MOT** test number Result **X** Failed Fail Offside Rear Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii)) **Advice** Nearside Rear Service brake binding but not excessively (1.2.1 (f)) Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Advice Advice Brake disc worn, pitted or scored, but not seriously weakened both front (1.1.14 (a) (ii)) Nearside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i)) **Fail Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #4

MOT test number

690916602889

Result

✓ Passed

Minor

Offside Rear Tyre obviously under inflated cracked and perished (5.2.3 (h) (i))

Advice

Offside Front Tyre worn close to legal limit/worn on edge worn inner edge (5.2.3 (e))

Advice

Nearside Front Tyre worn close to legal limit/worn on edge worn inner edge (5.2.3 (e))

MOT #3		2018-11-26 10:37
MOT test	number	190208419563
Result		X Failed
Advice	Offside Front Tyre worn close to legal limit/worn on edge worn inner ed	dge (5.2.3 (e))
Fail Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))		
Advice Nearside Front Tyre worn close to legal limit/worn on edge worn inner edge (5.2.3 (e))		
Minor	Offside Rear Tyre obviously under inflated cracked and perished (5.2.3	(h) (i))
Fail Nearside Front Windscreen wiper does not clear the windscreen effectively blade split (3.4 (b) (ii))		

CarCheck.co.uk page 6/14



report date: 2024-03-29

MOT #2	2017-11-27 13:20
MOT test number	791100842846
Result	✓ Passed
MOT #1	2017-02-07 12:07
MOT test number	744131113986
Result	✓ Passed

CarCheck.co.uk page 7/14



report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 May
Days left	1
MOT expiry date	26 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	В
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-

CarCheck.co.uk page 8/14



report date: 2024-03-29

Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/14



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 10/14



report date: 2024-03-29

Owner history

,	
For how long did the current and previous owner(s) have this RENAULT? How many owner have? Check it in the premium report and see all owner registrations. Download the full is	

THE REAL PROPERTY AND ADDRESS OF THE PERTY ADDRESS OF THE PERTY ADDRESS OF THE PERTY AND ADDRESS OF THE PERTY ADDR	

	More info >
Plate changes	
See in this check if this RENAULT had different number plates.	
Number of plates	
Current registration	NK NK
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 11/14



report date: 2024-03-29

Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this RENAULT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 12/14



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2014-02-19
Last registration	2024-04-27
Complete history	See info



Registration #1	2014-02-19	19 mi
Registration #2	2017-02-07	20.528 mi
Registration #3	2017-11-27	27.445 mi
Registration #4	2018-11-26	48.596 mi
Registration #5	2018-11-27	48.596 mi
Registration #6	2020-02-08	64.943 mi
Registration #7	2020-02-12	65.070 mi
Registration #8	2021-01-04	82.575 mi
Registration #9	2021-01-04	82.599 mi
Registration #10		71.777 es
Registration #11		11.777 es
Registration #12		71.777 es
Registration #13		9.70 es
Registration #14		11.777 es
Registration #15		9.70 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		11.777 es

More info >

CarCheck.co.uk page 13/14



report date: 2024-03-29

Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Adult	88%
Children	89%
Pedestrian	66%
Safety systems	99%
Overall rating	85%
Video	see crash video



Dimensions & weight

Width	1732 mm
Height	1488 mm
Length	4062 mm
Wheel base	2589 mm
Kerb weight	980 kg
Max. allowed weight	1588 kg

Additional information

Fuel tank capacity	45 I
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats CarCheck.co.uk	5 page 14/14

Number of axles 2
Engine number U165424