



 **DL60ELW**

report date: 2024-03-29

General information

Make	FORD
Model	TRANSIT CONNECT T200 LR P/V
Colour	White
Year of manufacture	2011
Gearbox	5 speed Manual

Engine & fuel consumption

Power	74 BHP
Max. torque	175 Nm at 1.800 rpm
Engine capacity	1.753 cc
Cylinders	4
Fuel type	Diesel



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-07-21
Pictures	10
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-07-19
MOT pass rate	59 %
MOT passed	10
Failed MOT tests	7
Total advice items	73
Total items failed	30

MOT #17	2023-07-20 13:42
MOT test number	343962624649
Result	✓ Passed
Next expiry date	2024-07-19
Advice	Nearside outer sill corroded
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Brake pipe corroded, covered in grease or other material 2 front to rear (1.1.11 (c))
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #16**

2022-06-13 14:56

MOT test number

186047972857

Result

✓ Passed

- Advice** Coolant leak
- Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Slight corrosion to all four suspension springs
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened Inner surface (1.1.14 (a) (ii))
- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Minor** Nearside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Advice** Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Damp around injectors
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Middle & Rear exhaust deteriorated/corroded
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing & wearing on inner edge (5.2.3 (d) (ii))
- Minor** Nearside Front Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #15**

2022-06-13 08:42

MOT test number

354283519235

Result**✗ Failed**

- Minor** Nearside Front Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Slight corrosion to all four suspension springs
- Advice** Coolant leak
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Damp around injectors
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened Inner surface (1.1.14 (a) (ii))
- Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing & wearing on inner edge (5.2.3 (d) (ii))
- Minor** Nearside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Fail** Reversing lamp inoperative (4.6.1 (a))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Coolant level low
- Advice** Middle & Rear exhaust deteriorated/corroded

**MOT #14** 2021-07-03 14:55**MOT test number** 217145459020**Result** ✓ Passed**Advice** Both outer sills corroded**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge on the limit (5.2.3 (e))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #13** 2020-02-18 14:49**MOT test number** 753825613899**Result** ✓ Passed**Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Covers obscuring some components**Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #12** 2020-02-18 14:49**MOT test number** 820888560353**Result** ✗ Failed**Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Pass with rectification** Offside Front Position lamp not working (4.2.1 (a) (ii))**Advice** Covers obscuring some components**Pass with rectification** Central Upper Stop lamp(s) not working (4.3.1 (a) (ii))**Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #11** 2019-02-11 10:33**MOT test number** 991070520117**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #10** 2019-02-11 09:34**MOT test number** 350160943401**Result** ✗ Failed**Fail** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #9** 2018-02-13 09:54**MOT test number** 568635902093**Result** ✓ Passed**Advice** Nearside Rear tyre worn on the inner edge**Advice** Nearside Front tyre worn on the inner edge**Advice** Front Registration plate cracked but not likely to be misread**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**MOT #8** 2017-02-16 10:09**MOT test number** 637584969526**Result** ✓ Passed**Advice** Nearside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)**Advice** Front registration plate cracked but not likely to be misread**Advice** Suspect rear pads wearing thin remove wheels to check asap

**MOT #7**

2016-02-20 11:43

MOT test number

992619508650

Result

✓ Passed

- Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)
- Advice** Offside Front Tyre worn close to the legal limit inner edge worn (4.1.E.1)
- Advice** Ball joint has slight play o/s/f inner rack joint (2.2.B.1f)
- Advice** Offside Rear Tyre worn close to the legal limit worn on edges (4.1.E.1)

MOT #6

2016-02-09 14:21

MOT test number

128873791329

Result

✗ Failed

- Fail** Nearside Front Anti-roll bar linkage has excessive play in a ball joint (2.4.G.2)
- Advice** Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Offside Front Tyre worn close to the legal limit inner edge worn (4.1.E.1)
- Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)
- Fail** Nearside Rear Tyre has ply or cords exposed inner edge (4.1.D.1b)
- Fail** Nearside Front Seat belt affected by a damaged seat frame (5.2.1b)
- Advice** Ball joint has slight play o/s/f inner rack joint (2.2.B.1f)
- Advice** Nearside Outer Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)
- Advice** Engine oil leak
- Fail** Front Brakes imbalanced across an axle (3.7.D.2c)
- Advice** Offside Rear Tyre worn close to the legal limit worn on edges (4.1.E.1)
- Fail** Brake pedal anti-slip provision incomplete (3.3.A.1b)



MOT #5	2015-02-24 16:25
MOT test number	985925955083
Result	✓ Passed
Advice	Nearside Outer Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)

MOT #4	2015-02-23 11:39
MOT test number	377624455012
Result	✗ Failed
Fail	Fuel pipe leaking (7.2.3)
Fail	Parking brake: efficiency below requirements (3.7.D.4)
Fail	Offside Registration plate lamp not working (1.1.C.1d)
Advice	Exhaust has a minor leak of exhaust gases (7.1.2)
Fail	Offside Rear Direction indicator incorrect colour (1.4.A.2f)
Fail	Fuel pipe leaking (7.2.3)
Fail	Offside Front Tyre has ply or cords exposed (4.1.D.1b)
Fail	Nearside Registration plate lamp not working (1.1.C.1d)
Fail	Brakes imbalanced across an axle (3.7.D.2c)
Fail	Nearside Rear Direction indicator incorrect colour (1.4.A.2f)
Advice	Nearside Outer Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)
Fail	Windscreen has damage to the swept area in excess of a 40mm circle outside zone 'A' (8.3.1d)



MOT #3 2015-02-20 12:23

MOT test number 458581655061

Result ✗ Failed

Fail Nearside Headlamp aim too high and too far to the right. (1.8)

Fail Rear Exhaust has a major leak of exhaust gases (7.1.2)

Advice Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

Fail Nearside Windscreen has damage to the swept area in excess of a 40mm circle outside zone 'A' (8.3.1d)

Advice Fuel pipe slightly damaged (7.2.2)

Fail Offside Headlamp aim too high and too far to the right. (1.8)

Fail Fuel pipe leaking (7.2.3)

Notice Centre stop light inop

Advice Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

Advice Rear Direction indicator slightly discoloured (1.4.A.2f)

Fail Registration plate lamp not working (1.1.C.1d)

MOT #2 2014-02-19 15:36

MOT test number 465320454021

Result ✓ Passed



MOT #12014-02-19 12:13

MOT test number187730454061

Result		✗ Failed
Fail	Nearside Outer Front constant velocity joint gaiter damaged to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)	
Fail	Nearside Parking brake recording little or no effort (3.7.D.3a)	
Fail	Brakes imbalanced across an axle (3.7.D.2c)	
Fail	Front Service brake application uneven across the axle (3.7.D.2b)	
Fail	Parking brake: efficiency below requirements (3.7.D.4)	



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
19 July 2024

Tax status	Valid until 1 August
-------------------	----------------------

Days left	93
------------------	----

MOT expiry date	19 July 2024
------------------------	--------------

Full MOT history	See MOT history
-------------------------	---------------------------------



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	DL60ELW
Plate since	2019-09-29
Current registration	DL60ELW
Plate since	2019-09-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2011-02-22
Last registration	2023-07-20
Complete history	See info



Registration #1	2011-02-22	21 mi
Registration #2	2014-02-19	82.554 mi
Registration #3	2014-02-19	82.554 mi
Registration #4	2015-02-20	104.912 mi
Registration #5	2015-02-23	105.041 mi
Registration #6	2015-02-24	105.041 mi
Registration #7	2016-02-09	126.632 mi
Registration #8	2016-02-20	126.655 mi
Registration #9	2017-02-16	138.454 mi
Registration #10	2018-02-13	158.092 mi
Registration #11	2019-02-20	178.731 mi
Registration #12	2020-02-19	199.370 mi
Registration #13	2021-02-18	220.009 mi
Registration #14	2022-02-17	240.648 mi
Registration #15	2023-02-16	261.287 mi
Registration #16	2024-02-15	281.926 mi
Registration #17	2025-02-14	302.565 mi
Registration #18	2026-02-13	323.204 mi
Registration #19	2027-02-12	343.843 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	2044 mm
Height	598 mm
Length	4278 mm
Kerb weight	1392 kg
Max. allowed weight	2040 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	4
Number of seats	2
Engine number	BD93214