




report date: 2024-11-08

General information

| | |
|---------------------|---------------------------------------|
| Make | MINI |
| Model | COOPER D LONDON 2012 EDITION COOPER D |
| Colour | Silver |
| Year of manufacture | 2012 |
| Top speed | 122 mph |
| 0 - 60 mph | 9.7 seconds |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 112 BHP |
| Max. torque | 270 Nm at 1.750 rpm |
| Engine capacity | 1.598 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 67.3 mpg |
| Consumption extra urban | 80.7 mpg |
| Consumption combined | 74.3 mpg |
| CO2 emission | 99 g/km |
| CO2 label | A |





Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2024-06-02 |
| Pictures | 47 |
| Listing price | View report |



source: cargurus.co.uk



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2025-12-12 |
| MOT pass rate | 77 % |
| MOT passed | 10 |
| Failed MOT tests | 3 |
| Total advice items | 26 |
| Total items failed | 5 |

MOT #13 2024-12-06 16:15

MOT test number 969204787989

Result ✓ Passed

Next expiry date 2025-12-12

- Advice** Offside Front Shock absorbers has light misting of oil (5.3.2 (b))
- Advice** Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))

MOT #12 2023-12-13 17:10

MOT test number 223270260826

Result ✓ Passed

- Advice** Front subframe corroded
- Minor** Offside Windscreen damaged but not adversely affecting driver's view stonechipped & slight scratches (3.2 (a) (i))

MOT #11 2023-12-11 12:58

MOT test number 686560664540

Result ✗ Failed

- Advice** Front subframe corroded
- Minor** Offside Windscreen damaged but not adversely affecting driver's view stonechipped & slight scratches (3.2 (a) (i))
- Fail** Offside Front Inner Suspension arm pin or bush excessively worn (5.3.4 (a) (i))
- Fail** Nearside Front Inner Suspension arm pin or bush excessively worn (5.3.4 (a) (i))



| | |
|------------------------|---|
| MOT #10 | 2022-10-28 14:31 |
| MOT test number | 856702560827 |
| Result | ✓ Passed |
| Advice | Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) |
| Advice | Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) |
| Minor | Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i)) |
| Advice | Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) |

| | |
|--------------------------------|---|
| MOT #9 | 2022-10-28 14:31 |
| MOT test number | 840544331732 |
| Result | ✗ Failed |
| Pass with rectification | Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c)) |
| Advice | Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) |
| Advice | Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) |
| Advice | Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) |
| Minor | Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i)) |

| | |
|------------------------|--|
| MOT #8 | 2021-11-02 12:21 |
| MOT test number | 232260432945 |
| Result | ✓ Passed |
| Minor | Windscreen damaged but not adversely affecting driver's view chipped (3.2 (a) (i)) |
| Advice | Nearside Rear tyre outer side wall damaged |

| | |
|------------------------|--|
| MOT #7 | 2020-11-03 15:09 |
| MOT test number | 529310334552 |
| Result | ✓ Passed |
| Advice | Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) |



| | |
|------------------------|---|
| MOT #6 | 2019-11-05 12:00 |
| MOT test number | 830875562750 |
| Result | ✓ Passed |
| Advice | Nearside front & rear tyres have side wall damage |
| Advice | Offside washer jet needs adjusting |

| | |
|------------------------|------------------|
| MOT #5 | 2018-10-31 08:38 |
| MOT test number | 281044859818 |
| Result | ✓ Passed |

| | |
|--------------------------------|---|
| MOT #4 | 2018-10-31 08:38 |
| MOT test number | 947241853049 |
| Result | ✗ Failed |
| Pass with rectification | Offside Headlamp aim too low (4.1.2 (a)) |
| Pass with rectification | Nearside Headlamp aim too low (4.1.2 (a)) |

| | |
|------------------------|---|
| MOT #3 | 2018-06-11 12:19 |
| MOT test number | 740862982725 |
| Result | ✓ Passed |
| Advice | Offside Front Tyre worn close to legal limit/worn on edge Outer shoulder (5.2.3 (e)) |
| Advice | Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) |
| Advice | Offside Front Inner Road wheel slightly distorted (5.2.2 (c) (i)) |
| Advice | Offside Rear Tyre worn close to legal limit/worn on edge Inner shoulder very worn (5.2.3 (e)) |
| Advice | Nearside Front Inner Road wheel slightly distorted (5.2.2 (c) (i)) |
| Minor | Tyre pressure monitoring system warning lamp indicates a fault (5.2.3 (h) (i)) |



MOT #2 2016-06-17 11:42

MOT test number 463887174604

Result ✓ Passed

Advice Nearside Rear Nail in tyre

MOT #1 2015-06-05 10:12

MOT test number 438036855145

Result ✓ Passed



Tax & MOT check

✓
Taxed

Tax due:
1 August 2025

✓
MOT

Expires:
12 December 2025

| | |
|-------------------------|---------------------------------|
| Tax status | Valid until 1 August |
| Days left | 235 |
| MOT expiry date | 12 December 2025 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|--|----------------|
| Vehicle class | 49 |
| Band | A |
| Single payment (12 months) | £ 0,00,- |
| Single six month payment | Not applicable |
| Total payable by 12 monthly instalments | Not applicable |




Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.


Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|------------------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

[More info >](#)



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | | |
|-------|-------|-----|
| Owner | Start | End |
| Owner | Start | End |
| Owner | Start | End |
| Owner | Start | End |
| Owner | Start | End |
| Owner | Start | End |
| Owner | Start | End |

More info >

Plate changes

See in this check if this MINI had different number plates.

| | |
|----------------------|--------------|
| Number of plates | 1 |
| Current registration | XXXXX |
| Plate since | 2024-01-01 |
| Current registration | XXXXX |
| Plate since | 2024-01-01 |

More info >



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.


| | |
|--------------------------|----------|
| Finance company | REDACTED |
| Date of agreement | REDACTED |
| Agreement type | REDACTED |
| Agreement term | REDACTED |
| Agreement number | REDACTED |
| Contact info | REDACTED |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 15 |
| First mileage registration | 2012-06-18 |
| Last registration | 2024-12-06 |
| Complete history | See info |



| | | |
|------------------|------------|-----------|
| Registration #1 | 2012-06-18 | 17 mi |
| Registration #2 | 2015-06-05 | 34.613 mi |
| Registration #3 | 2016-06-17 | 40.672 mi |
| Registration #4 | 2018-06-11 | 52.477 mi |
| Registration #5 | 2018-10-31 | 52.682 mi |
| Registration #6 | 2018-10-31 | 52.682 mi |
| Registration #7 | 2019-11-05 | 63.131 mi |
| Registration #8 | 2020-11-03 | 69.433 mi |
| Registration #9 | 2020-11-03 | 69.433 mi |
| Registration #10 | 2020-11-03 | 69.433 mi |
| Registration #11 | 2020-11-03 | 69.433 mi |
| Registration #12 | 2020-11-03 | 69.433 mi |
| Registration #13 | 2020-11-03 | 69.433 mi |
| Registration #14 | 2020-11-03 | 69.433 mi |
| Registration #15 | 2020-11-03 | 69.433 mi |

[More info >](#)



Car features

The MINI factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete MINI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

| | |
|---------------------|---------|
| Width | 1683 mm |
| Height | 1407 mm |
| Length | 3723 mm |
| Wheel base | 2467 mm |
| Kerb weight | 1090 kg |
| Max. allowed weight | 1540 kg |

Additional information

| | |
|--------------------|------------------|
| Fuel tank capacity | 40 l |
| Fuel delivery | Direct Injection |
| Number of doors | 3 |
| Number of seats | 4 |

Number of axles

2

Engine number

70817962