





report date: 2024-03-28

General information

Make	PEUGEOT
Model	EXPERT L2 H2 HDI LWB H/R P/V
Colour	White
Year of manufacture	2009
Top speed	87 mph
0 - 60 mph	18.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	90 BHP
Max. torque	180 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	32.8 mpg
Consumption extra urban	41.5 mpg
Consumption combined	37.7 mpg



CarCheck.co.uk page 1/13



report date: 2024-03-28

Internet history

Entry 1

Date 2021-06-19

Pictures 12

Listing price <u>View report</u>









source: autoonline.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-28

N/I	α		uc:	t۸	r\/
101	•		115	w	ıv
	•	Γh			. ,

Advice

MOT expiry date	2025-01-20
MOT pass rate	81 %
MOT passed	13
Failed MOT tests	3
Total advice items	22
Total items failed	4

MOT #16	2024-01-18 09:01
MOT test number	587975883170
Result	✓ Passed
Next expiry date	2025-01-20
Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #15	2023-01-09 14:28
MOT test number	689341949188
Result	✓ Passed
MOT #14	2022-01-21 17:46
MOT test number	913689675695
Result	✓ Passed
Advice ADVISE Slight Age related corrosion on suspension etc	

MOT #13	2021-06-25 14:58
MOT test number	285289437448
Result	✓ Passed

ADVISE Both front tyres worn close to 3mm of tread

CarCheck.co.uk page 3/13



report date: 2024-03-28

MOT #12 2021-06-24 11:25

MOT test number 192662088978

Result X Failed

Pass with rectification Offside Headlamp aim too high (4.1.2 (a))

Advice Offside Rear Nail in tyre

MAJOR Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

Pass with rectification Nearside Headlamp aim too high (4.1.2 (a))

MAJOR Rear fog lamp not working (4.5.1 (a) (ii))

MAJOR Parking brake efficiency below requirements (1.4.2 (a) (i))

MAJOR Hazard warning switch inoperative (4.4.2 (a) (ii))

MOT #11 2020-11-03 09:11

MOT test number 234918574403

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Nearside Rear Service brake binding but not excessively (1.2.1 (f))

Advice Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

CarCheck.co.uk page 4/13



(ii))

Result

ND09PHZ

report date: 2024-03-28

Passed

MOT test number

Result

Advice
(ii))

Advice
Nearside Front Brake disc worn, pitted or scored, but not seriously weakened inner face (1.1.14 (a)

Advice
Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice
Offside Front Brake disc worn, pitted or scored, but not seriously weakened inner face (1.1.14 (a)

MOT #9

MOT test number

Result

2018-11-15 17:09

356254235829

✓ Passed

MOT #8

MOT test number

665621255413

Result

✓ Passed

MOT #7 2016-11-11 12:46

MOT test number 690956342358

Advice Front Macpherson strut has slight movement at the upper attachment (2.5.A.1c)

MOT #6 2016-11-11 12:46

MOT test number 878304896728

Result × Failed

Pass with rectification Offside Front Anti-roll bar linkage has excessive play in a ball joint (2.4.G.2)

Advice Front Macpherson strut has slight movement at the upper attachment (2.5.A.1c)

 MOT #5
 2015-11-07 10:58

 MOT test number
 729572166816

 Result
 ✓ Passed

CarCheck.co.uk page 5/13



report date: 2024-03-28

Passed

MOT #4 2015-11-07 10:58
MOT test number 389300400450

Result × Failed

Pass with rectification

Result

Offside Headlamp aim beam image obviously incorrect (1.8.A.1b)

MOT #3

MOT test number

408200734455

Result

Notice Gear box noisey , cv gaitor , front anti roll link bar

MOT #2 2013-11-19 11:42

MOT test number 336813623355

MOT #1 2012-07-26 13:22

MOT test number 228258402267

Advice Front Brake pad(s) wearing thin (3.5.1g)

CarCheck.co.uk page 6/13



report date: 2024-03-28

Tax & MOT check



Tax status

Days left

MOT expiry date

Full MOT history

Valid until 1 June

20 January 2025

See MOT history

CarCheck.co.uk page 7/13



report date: 2024-03-28

Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report here for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-28

Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owner have? Check it in the premium report and see all owner registrations. Download the full is	

	More info >
Plate changes	
See in this check if this PEUGEOT had different number plates.	
Number of plates	
Current registration	NK SIE
Plate since	
Current registration	NK NK
Plate since	
	More info >

CarCheck.co.uk page 10/13



report date: 2024-03-28

Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Courts at info	

Contact info

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-28

Mileage check

Odometer	In kilometers
Mileage registrations	18
First mileage registration	2009-05-31
Last registration	2024-01-18
Complete history	See info



Registration #1	2009-05-31	6 mi
Registration #2	2012-07-26	41.607 mi
Registration #3	2013-11-19	46.889 mi
Registration #4	2014-11-26	52.502 mi
Registration #5	2015-11-07	56.900 mi
Registration #6	2015-11-07	56.900 mi
Registration #7	2016-11-11	59.632 mi
Registration #8	2016-11-11	59.632 mi
Registration #9	2017-11-03	61.904 mi
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		11.177 es

More info >

CarCheck.co.uk page 12/13



report date: 2024-03-28

Car features

S0225	Air conditioning
50295	
50482	
50501	
60566	
60567	
50569	

Dimensions & weight

Width	2194 mm
Height	2290 mm
Length	5135 mm
Kerb weight	1712 ka

Additional information

Fuel tank capacity	80
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	3
Engine number	JBAZ0049696

CarCheck.co.uk page 13/13