




report date: 2024-03-28

General information

Make	CITROEN
Model	GRAND C4 HDI VTR PLUS EGS GRAND PICASSO
Colour	Grey
Year of manufacture	2011
Top speed	113 mph
Gearbox	6 speed Semi-Automatic

Engine & fuel consumption

Power	110 BHP
Max. torque	285 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	47.1 mpg
Consumption extra urban	58.9 mpg
Consumption combined	54.3 mpg
CO2 emission	136 g/km
CO2 label	E





Internet history

Entry 1

Date	2021-01-29
Pictures	1
Listing price	<a href="#">View report</a>



source: [autoonline.co.uk](https://www.autoonline.co.uk)



## MOT history

MOT expiry date	2024-09-02
MOT pass rate	71 %
MOT passed	10
Failed MOT tests	4
Total advice items	14
Total items failed	7

MOT #14	2023-08-31 16:47
MOT test number	997387520648
Result	✓ Passed
Next expiry date	2024-09-02

MOT #13	2022-08-25 11:41
MOT test number	204488518891
Result	✓ Passed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #12	2022-08-25 08:52
MOT test number	477131363643
Result	✗ Failed
Advice	Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Fail	Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))
Fail	Offside Front Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #11** 2021-08-31 12:25**MOT test number** 103248688413**Result** ✓ Passed**MOT #10** 2021-08-31 09:18**MOT test number** 925466702221**Result** ✗ Failed**Fail** Offside Front Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**MOT #9** 2020-09-03 09:13**MOT test number** 927525804035**Result** ✓ Passed**MOT #8** 2020-01-18 10:51**MOT test number** 750128900552**Result** ✓ Passed**MOT #7** 2020-01-17 14:23**MOT test number** 283186197359**Result** ✗ Failed**Fail** Nearside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))**Fail** Offside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))**MOT #6** 2019-01-08 12:17**MOT test number** 946214078869**Result** ✓ Passed

**MOT #5** 2018-01-18 15:35**MOT test number** 883042647183**Result** ✓ Passed**Advice** Front Tyre worn close to the legal limit both 3mm sized 215 55 16 (4.1.E.1)**MOT #4** 2017-01-13 14:56**MOT test number** 693800068163**Result** ✓ Passed**MOT #3** 2016-01-13 16:40**MOT test number** 136952121686**Result** ✓ Passed**Advice** Both front tyres worn uneven**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' chip (8.3.1a)**Advice** Child seats obstructing inspection of rear seat belts**MOT #2** 2014-09-26 09:19**MOT test number** 907049364208**Result** ✓ Passed**Notice** Emissions tested but readings too low too register**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Tyre worn close to the legal limit (4.1.E.1)



MOT #12014-09-20 09:23

MOT test number635103964292

Result

Failed

Advice

Nearside Tyre worn close to the legal limit (4.1.E.1)

Fail

Parking brake: efficiency below requirements (3.7.B.7)

Advice

Offside Rear Tyre worn close to the legal limit (4.1.E.1)

Fail

Electronic parking brake control defective so that it cannot be satisfactorily operated (3.1.3c)

Notice

Emissions tested but readings too low too register



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 December 2024

✓  
**MOT**  
**Expires:**  
2 September 2024

<b>Tax status</b>	Valid until 1 December
<b>Days left</b>	216
<b>MOT expiry date</b>	2 September 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	E
<b>Single payment (12 months)</b>	£ 180,00,-
<b>Single six month payment</b>	£ 99,00,-
<b>Total payable by 12 monthly instalments</b>	£ 189,00,-



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	0
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2011-09-15
Last registration	2023-08-31
Complete history	<a href="#">See info</a>



Registration #1	2011-09-15	15 mi
Registration #2	2014-09-20	23.601 mi
Registration #3	2014-09-26	23.725 mi
Registration #4	2016-01-13	35.244 mi
Registration #5	2017-01-13	41.309 mi
Registration #6	2018-01-18	47.952 mi
Registration #7	2019-01-08	55.390 mi
Registration #8	2020-01-17	60.915 mi
Registration #9	2020-05-20	65.377 mi
Registration #10	2020-05-20	65.377 mi
Registration #11	2020-05-20	65.377 mi
Registration #12	2020-05-20	65.377 mi
Registration #13	2020-05-20	65.377 mi
Registration #14	2020-05-20	65.377 mi
Registration #15	2020-05-20	65.377 mi
Registration #16	2020-05-20	65.377 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	90%
Children	85%
Pedestrian	43%
Safety systems	97%
Overall rating	80%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1830 mm
Height	1710 mm
Length	4590 mm
Wheel base	2728 mm
Kerb weight	1520 kg
Max. allowed weight	2250 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7
Number of axles	2
Engine number	JBER3058745