



report date: 2024-03-29

General information

Make	FIAT
Model	PANDA ACTIVE
Colour	Blue
Year of manufacture	-
Top speed	93 mph
0 - 60 mph	15.0 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	54 BHP
Max. torque	87 Nm at 2.750 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	39.2 mpg
Consumption extra urban	58.9 mpg
Consumption combined	49.6 mpg



LABEL UNKNOWN

**MOT history****MOT #19**

2022-01-17 12:57

MOT test number

146534092844

Result**✗ Failed**

- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Fail** Rear Brakes imbalanced across an axle Axle 2 (1.2.1 (b) (i))
- Advice** Wiper mechanism worn
- Advice** Vehicles internal headlight adjuster altered to recheck lights
- Advice** Nearside Front Shock absorbers has a reduced damping effect (5.3.2 (d))
- Minor** Front Outer Drive shaft joint constant velocity boot severely deteriorated both (6.1.7 (g) (i))
- Advice** Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))
- Fail** Front Tyre(s) with different aspect ratios are fitted on the same axle. (5.2.3 (b))
- Fail** Exhaust carbon monoxide content after 2nd fast idle exceeds manufacturer's specified limits (8.2.1.2 (a))
- Advice** Items removed from driver's view prior to test
- Minor** Central Stop lamp(s) with a multiple light source up to 1/2 not functioning (4.3.1 (a) (i))
- Advice** Front brake pipes appear slightly damp
- Advice** Nearside Front Shock absorbers has a slightly worn bush (5.3.2 (c))

**MOT #18**

2021-02-08 10:17

MOT test number

883885985680

Result

✓ Passed

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Side repeater slightly discoloured (4.4.3 (a))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Rear exhaust box been repaired
- Advice** Offside Side repeater slightly discoloured (4.4.3 (a))

MOT #17

2021-02-05 16:39

MOT test number

195278080903

Result

✗ Failed

- Advice** Nearside Side repeater slightly discoloured (4.4.3 (a))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Rear Exhaust has a major leak of exhaust gases (6.1.2 (a))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Side repeater slightly discoloured (4.4.3 (a))
- Fail** Emissions not tested due to exhaust leak (8.2.1.2 (d))

**MOT #16** 2020-12-16 12:43**MOT test number** 869051588521**Result** ✗ Failed

- Fail** Offside Front Shock absorbers has a serious fluid leak (5.3.2 (b))
- Fail** Offside Front Lower Suspension arm pin or bush excessively worn (5.3.4 (a) (i))
- Fail** Brake performance not tested (1.2.1 (g))
- Fail** Nearside Front Lower Suspension arm pin or bush excessively worn (5.3.4 (a) (i))
- Fail** Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

MOT #15 2019-05-24 14:52**MOT test number** 127869107399**Result** ✓ Passed**MOT #14** 2018-05-17 11:47**MOT test number** 559464734953**Result** ✓ Passed**MOT #13** 2018-05-17 10:41**MOT test number** 583781512822**Result** ✗ Failed

- Fail** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)

MOT #12 2017-06-01 15:12**MOT test number** 222059480963**Result** ✓ Passed

**MOT #11** 2017-06-01 09:45**MOT test number** 904760871572**Result** ✗ Failed

- Fail** Offside rear brake recording little or no effort (3.7.B.5a)
- Fail** Offside Registration plate lamp not working (1.1.C.1d)
- Fail** Nearside rear brake recording little or no effort (3.7.B.5a)
- Fail** Rear brake application uneven (3.7.B.2)

MOT #10 2015-11-13 09:05**MOT test number** 106437066047**Result** ✓ Passed

- Advice** O/s front tyre worn inner edge and on limit

MOT #9 2014-11-21 10:12**MOT test number** 599335624341**Result** ✓ Passed

- Notice** Rear bumper damaged

MOT #8 2013-11-22 09:39**MOT test number** 875916823300**Result** ✓ Passed**MOT #7** 2012-11-16 09:19**MOT test number** 877821822302**Result** ✓ Passed

**MOT #6** 2011-11-18 10:58**MOT test number** 619192821317**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #5** 2010-11-19 09:21**MOT test number** 551263120384**Result** ✓ Passed**Notice** Offside front and nearside rear tyres worn and worn uneven possibly original tyres fitted from new**Notice** Wiper blades worn/noisey**MOT #4** 2009-11-27 13:57**MOT test number** 983331939316**Result** ✓ Passed**MOT #3** 2009-11-20 10:07**MOT test number** 234544329347**Result** ✗ Failed**Fail** Exhaust has a major leak of exhaust gases (7.1.2)**Advice** Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)**Notice** AS A RESULT OF NOT ATTENDING TO ITEMS ADVISED LAST YEAR FOR CUSTOMERS AWARENESS AND SAFETY VEHICLE HAS FAILED ON ADVISED ITEMS REAR BRAKE FAILURE (DANGEROUS)**Fail** Exhaust has part of the system excessively deteriorated (7.1.1a)**Fail** Nearside rear brake recording little or no effort (3.7.B.5a)**MOT #2** 2008-11-03 09:37**MOT test number** 283148508399**Result** ✓ Passed**Advice** Exhaust has part of the system slightly deteriorated (7.1.1a)




MOT #1	2007-11-24 11:50
MOT test number	451308527328
Result	✓ Passed



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	 
Plate since	2024-03-29
Current registration	 
Plate since	2024-03-29

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.


Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2004-11-30
Last registration	2022-01-17
Complete history	See info



Registration #1	2004-11-30	20 mi
Registration #2	2007-11-24	17.779 mi
Registration #3	2008-11-03	21.845 mi
Registration #4	2009-11-20	27.335 mi
Registration #5	2009-11-27	27.335 mi
Registration #6	2010-11-19	32.536 mi
Registration #7	2011-11-18	37.884 mi
Registration #8	2012-11-16	43.071 mi
Registration #9	2013-11-22	48.792 mi
Registration #10	2014-11-21	54.624 mi
Registration #11	2015-11-20	54.624 mi
Registration #12	2016-11-19	54.624 mi
Registration #13	2017-11-18	54.624 mi
Registration #14	2018-11-17	54.624 mi
Registration #15	2019-11-16	54.624 mi
Registration #16	2020-11-15	54.624 mi
Registration #17	2021-11-14	54.624 mi
Registration #18	2022-01-17	54.624 mi
Registration #19	2022-01-17	54.624 mi
Registration #20	2022-01-17	54.624 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1578 mm
Height	1540 mm
Length	3538 mm
Wheel base	2299 mm
Kerb weight	840 kg

Additional information

Fuel tank capacity	35 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of axles	2
Engine number	2216057