





General information

| Make | PEUGEOT |
|---------------------|-------------------|
| Model | 2008 S/S ALLURE |
| Colour | Black |
| Year of manufacture | 2017 |
| Top speed | 117 mph |
| 0 - 60 mph | 10.3 seconds |
| Gearbox | 6 speed automatic |

Engine & fuel consumption

| Power | 110 BHP |
|-------------------------|---------------------|
| Max. torque | 205 Nm at 1.500 rpm |
| Engine capacity | 1.200 cc |
| Cylinders | 3 |
| Fuel type | Petrol |
| Consumption city | 47.9 mpg |
| Consumption extra urban | 68.9 mpg |
| Consumption combined | 58.9 mpg |
| CO2 emission | 110 g/km |
| CO2 label | В |





| Internet history | |
|------------------|-------------|
| Entry 1 | |
| Date | 2021-02-03 |
| Pictures | 1 |
| Listing price | View report |



source: autoonline.co.uk



MOT history

| MOT expiry date | 2024-06-20 |
|--------------------|------------|
| MOT pass rate | 57 % |
| MOT passed | 4 |
| Failed MOT tests | 3 |
| Total advice items | 11 |
| Total items failed | 3 |

| MOT #7 | 2023-06-21 13:47 |
|---|------------------|
| MOT test number | 735052664024 |
| Result | ✓ Passed |
| Next expiry date | 2024-06-20 |
| Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt | |

| MOT #6 | 2023-06-21 09:26 |
|---|------------------|
| MOT test number | 701375500608 |
| Result | 🗙 Failed |
| Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt | |
| Fail Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii)) | |

| MOT #5 | | 2022-06-11 12:18 |
|----------|---|------------------|
| MOT test | number | 305105969439 |
| Result | | ✓ Passed |
| Advice | Rear Tyre worn close to legal limit/worn on edge both on 2mm (5.2.3 (e)) | |
| Advice | Nearside Front Tyre worn close to legal limit/worn on edge on 3mm (5.2.3 (e)) | |
| Advice | Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) | |





| MOT #4 | | 2022-06-11 12:18 |
|--|---|---------------------------------|
| MOT test number | | 907290448692 |
| Result | | 🗙 Failed |
| Advice Front Brake pad | s) wearing thin (1.1.13 (a) (ii)) | |
| Advice Rear Tyre worn close to legal limit/worn on edge both on 2mm (5.2.3 (e)) | | |
| Pass with rectification | Rear Registration plate lamp inoperative in the cas | e of a single lamp or all lamps |
| both (4.7.1 (b) (ii)) | | |
| Advice Nearside Front Tyre worn close to legal limit/worn on edge on 3mm (5.2.3 (e)) | | |
| | | |

| МОТ #3 | 2021-05-07 15:07 |
|-----------------|------------------|
| MOT test number | 581427602575 |
| Result | ✓ Passed |

| MOT #2 | 2021-05-07 08:04 |
|---|------------------|
| MOT test number | 644181112527 |
| Result | 🗙 Failed |
| Fail Brake disc significantly and obviously worn Both rear (1.1.14 (a) (i)) | |
| Advice Tyre worn close to legal limit/worn on edge Both front (5.2.3 (e)) | |

| MOT #1 | | 2020-06-23 10:00 |
|----------|--|------------------|
| MOT test | number | 532010405323 |
| Result | | ✓ Passed |
| Advice | Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |
| Advice | Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |



Tax & MOT check

| ✓ Taxed | ✓ MOT |
|-------------------------|--------------------------|
| Tax due: 1 June 2024 | Expires: 20 June 2024 |
| Tax status | Valid until 1 June |
| Days left | 34 |
| MOT expiry date | 20 June 2024 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 48 |
|-------------------------------|------------|
| Band | F |
| First licence fee (12 months) | £ 185,00,- |
| Standard rate (12 months) | £ 180,00,- |
| Standard rate (6 months) | £ 99,00,- |
| Premium rate (12 months) | £ 570,00,- |
| Premium rate (6 months) | £ 313,50,- |





Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 | |
|----------|---|
| Date | |
| Category | 4. DEM PE |
| Туре | |
| Damage 2 | Annet |
| Date | No. Contraction of the second |
| Category | AMP |
| Туре | |

Extra PEUGEOT salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info \rightarrow





Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| Trade retail value | 4 10.000 |
|-----------------------------|----------|
| Auction value | 4 10.000 |
| Average private trade value | 4 |

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

| And a second sec | |
|--|-------------|
| ************ | |
| ******** | |
| ******* | |
| *********** | |
| ******** | |
| | More info > |
| Plate changes | |
| See in this check if this PEUGEOT had different number plates. | |
| Number of plates | , |
| Current registration | |
| Plate since | |
| Current registration | |
| Plate since | |
| | More info > |





Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |


More info \rightarrow





Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 9 |
| First mileage registration | 2017-08-25 |
| Last registration | 2023-06-21 |
| Complete history | See info |



| Registration #1 | 2017-08-25 | 26 mi |
|-----------------|------------|------------|
| Registration #2 | 2020-06-23 | 26.941 mi |
| Registration #3 | | 11.777 esi |
| Registration #4 | 2021-05-07 | 28.809 mi |
| Registration #5 | 2021-05-07 | 28.809 mi |
| Registration #6 | | 11.117 esi |
| Registration #7 | | 11.777 esi |
| Registration #8 | | 11.777 esi |
| Registration #9 | | 11.777 esi |

More info >





Car features

| 50225 | Air conditioning |
|-------|------------------|
| 50295 | |
| 60482 | |
| 0501 | |
| 0566 | |
| 0567 | |
| 0569 | |

Safety ratings

| NCAP rating | **** |
|----------------|-----------------|
| Adult | 88% |
| Children | 77% |
| Pedestrian | 72% |
| Safety systems | 70% |
| Overall rating | 81% |
| Video | see crash video |



| Dimensions & weight | |
|-----------------------------------|------------------|
| Width | 1829 mm |
| Height | 1556 mm |
| Length | 4159 mm |
| Wheel base | 2538 mm |
| Kerb weight | 1140 kg |
| Max. allowed weight | 1690 kg |
| Additional information | |
| Fuel tank capacity | 50 |
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats CarCheck.co.uk | 5 page 11/11 |

| Number of axles | 2 |
|-----------------|-------------|
| Engine number | XK012219309 |