



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	JETTA SE TDI
Colour	Blue
Year of manufacture	2009
Top speed	129 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	140 BHP
Max. torque	320 Nm at 1.750 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	7.1 mpg
Consumption combined	5.5 mpg
CO2 emission	143 g/km
CO2 label	F






Internet history

Entry 2


Date	2021-07-02
Pictures	7
Listing price	View report



source: [autotrader.co.uk](#)

Entry 1

Date	2021-06-26
Pictures	7
Listing price	View report



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2025-02-22
MOT pass rate	76 %
MOT passed	13
Failed MOT tests	4
Total advice items	16
Total items failed	6

MOT #17	2024-02-12 17:17
MOT test number	902630326359
Result	✓ Passed
Next expiry date	2025-02-22

MOT #16	2024-02-05 12:55
MOT test number	127727018421
Result	✗ Failed
Fail	Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))
Fail	Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
Fail	Offside Front Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

MOT #15	2023-02-09 09:25
MOT test number	698373199818
Result	✓ Passed
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

**MOT #14**

2023-02-06 13:15

MOT test number

581784729348

Result

✗ Failed

Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Fail** Nearside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))**MOT #13**

2022-02-08 15:45

MOT test number

867393144465

Result

✓ Passed

Advice Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Minor** Nearside Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Rear Brake disc worn, but not excessively both. (1.1.14 (a) (i))**MOT #12**

2022-02-08 13:50

MOT test number

420772302508

Result

✗ Failed

Minor Nearside Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Rear Brake disc worn, but not excessively both. (1.1.14 (a) (i))**Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Fail** Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #11** 2021-02-20 09:29**MOT test number** 564924735955**Result** ✓ Passed**MOT #10** 2020-02-15 14:55**MOT test number** 100918105968**Result** ✓ Passed**MOT #9** 2019-02-23 12:35**MOT test number** 731737671484**Result** ✓ Passed**MOT #8** 2018-03-16 17:01**MOT test number** 777703924637**Result** ✓ Passed**Advice** Offside Headlamp deteriorated. Beam image is only just OK for MoT.**MOT #7** 2017-03-07 10:00**MOT test number** 668202621049**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Headlamp deteriorated but light output not reduced (1.7.5a)**MOT #6** 2016-04-01 11:34**MOT test number** 785068745334**Result** ✓ Passed**MOT #5** 2015-05-05 12:24**MOT test number** 588525125166**Result** ✓ Passed

**MOT #4** 2014-05-12 17:13**MOT test number** 165452034134**Result** ✓ Passed**MOT #3** 2014-05-12 15:39**MOT test number** 855252834187**Result** ✗ Failed

Fail Nearside Front constant velocity joint gaiter damaged to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)

MOT #2 2013-05-13 09:59**MOT test number** 526223933115**Result** ✓ Passed

Notice Unable to see rear inner brake pads

MOT #1 2012-05-03 10:19**MOT test number** 448984822155**Result** ✓ Passed



Tax & MOT check

✓

Taxed

Tax due:
1 April 2025

✓

MOT

Expires:
22 February 2025

Tax status	Valid until 1 April
Days left	338
MOT expiry date	22 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-



Damage history


Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 GF09KUB
Plate since	2024-03-28
Current registration	 GF09KUB
Plate since	2024-03-28

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2009-05-26
Last registration	2024-02-12
Complete history	See info



Registration #1	2009-05-26	7 mi
Registration #2	2012-05-03	31.834 mi
Registration #3	2013-05-13	43.668 mi
Registration #4	2014-05-12	58.529 mi
Registration #5	2014-05-12	58.529 mi
Registration #6	2015-05-05	78.832 mi
Registration #7	2016-04-01	91.642 mi
Registration #8	2017-03-07	93.696 mi
Registration #9	2018-03-16	96.554 mi
Registration #10	2019-02-23	98.000 mi
Registration #11	2020-05-20	98.000 mi
Registration #12	2021-05-20	98.000 mi
Registration #13	2022-05-20	98.000 mi
Registration #14	2023-05-20	98.000 mi
Registration #15	2024-05-20	98.000 mi
Registration #16	2025-05-20	98.000 mi
Registration #17	2026-05-20	98.000 mi
Registration #18	2027-05-20	98.000 mi
Registration #19	2028-05-20	98.000 mi
Registration #20	2029-05-20	98.000 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	97%
Children	84%
Pedestrian	61%
Safety systems	71%
Overall rating	85%
Video	see crash video



Dimensions & weight

Width	1781 mm
Height	1459 mm
Length	4554 mm
Wheel base	2578 mm
Kerb weight	1411 kg
Max. allowed weight	2000 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	4

Number of seats	5
Number of axles	2
Engine number	CBD 011735