



Mercedes-Benz



D7HOR


report date: 2024-03-28

General information

Make	MERCEDES
Model	SL SL 500
Colour	Black
Year of manufacture	2005
Top speed	155 mph
0 - 60 mph	6.1 seconds
Gearbox	7 speed automatic

Engine & fuel consumption

Power	302 BHP
Max. torque	460 Nm at 2.700 rpm
Engine capacity	4.966 cc
Cylinders	8
Fuel type	Petrol
Consumption city	15.4 mpg
Consumption extra urban	32.8 mpg
Consumption combined	23.3 mpg
CO2 emission	292 g/km
CO2 label	M





Internet history

Entry 2

Date	2021-09-05
Pictures	2
Listing price	View report



source: cargurus.co.uk

Entry 1

Date	2021-09-04
Pictures	2
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-07-22
MOT pass rate	88 %
MOT passed	15
Failed MOT tests	2
Total advice items	18
Total items failed	3

MOT #17	2023-07-08 12:08
MOT test number	882668905523
Result	✓ Passed
Next expiry date	2024-07-22
Advice	Front Brake pipe corroded, covered in grease or other material Both sides (1.1.11 (c))

MOT #16	2022-07-14 12:48
MOT test number	540803174293
Result	✓ Passed
Advice	Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #15	2021-07-06 12:26
MOT test number	682933664399
Result	✓ Passed
Advice	Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #14	2020-07-23 14:37
MOT test number	229421333179
Result	✓ Passed
Advice	Covers & Trays obstructing view
Advice	Offside Front Brake pipe corroded, covered in grease or other material Corroded (1.1.11 (c))

**MOT #13** 2020-07-22 12:32**MOT test number** 310477942182**Result** ✗ Failed**Fail** Front Registration plate does not conform to the specified requirements (0.1 (d))**Advice** Offside Front Brake pipe corroded, covered in grease or other material Corroded (1.1.11 (c))**Fail** Rear Registration plate does not conform to the specified requirements (0.1 (d))**Advice** Covers & Trays obstructing view**MOT #12** 2019-04-02 09:28**MOT test number** 115873236309**Result** ✓ Passed**Advice** Engine covers under trays fitted**MOT #11** 2018-04-03 11:26**MOT test number** 591741373059**Result** ✓ Passed**Advice** Engine covers under trays fitted**MOT #10** 2017-03-20 10:21**MOT test number** 438437956544**Result** ✓ Passed**Advice** Engine covers and under trays fitted obscuring view**MOT #9** 2016-03-23 09:30**MOT test number** 984052958338**Result** ✓ Passed

**MOT #8** 2015-03-31 08:55**MOT test number** 386210095084**Result** ✓ Passed**Notice** Engine covers fitted obscuring some components in the engine bay**Notice** Under-trays fitted obscuring some underside components**MOT #7** 2014-04-01 13:28**MOT test number** 869041594002**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**Notice** Engine covers fitted obscuring some components in the engine bay**MOT #6** 2014-03-31 10:03**MOT test number** 229130594056**Result** ✗ Failed**Notice** Under-trays fitted obscuring some underside components**Fail** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**Notice** Engine covers fitted obscuring some components in the engine bay**MOT #5** 2013-03-26 14:18**MOT test number** 906605283052**Result** ✓ Passed**MOT #4** 2012-02-15 10:46**MOT test number** 968236042044**Result** ✓ Passed



MOT #3	2010-09-07 13:29
MOT test number	131550550298
Result	✓ Passed

MOT #2	2009-08-26 12:50
MOT test number	512188939288
Result	✓ Passed
<div><div>Advice</div>Offside Rear Tyre worn close to the legal limit (4.1.E.1)</div>	
<div><div>Advice</div>Nearside Rear Tyre worn close to the legal limit (4.1.E.1)</div>	

MOT #1	2008-09-12 14:45
MOT test number	673606758242
Result	✓ Passed



Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,200
Auction value	£ 19,200
Average private trade value	£ 19,200

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

Number of plates	7
Current registration	 *****
Plate since	2019-06-29
Current registration	 *****
Plate since	2019-06-29

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2005-09-01
Last registration	2023-07-08
Complete history	See info



Registration #1	2005-09-01	28 mi
Registration #2	2008-09-12	16.253 mi
Registration #3	2009-08-26	20.148 mi
Registration #4	2010-09-07	23.406 mi
Registration #5	2012-02-15	26.733 mi
Registration #6	2013-03-26	29.197 mi
Registration #7	2014-03-31	32.201 mi
Registration #8	2014-04-01	32.235 mi
Registration #9	2015-03-31	34.380 mi
Registration #10	2016-03-23	36.433 mi
Registration #11	2016-03-23	36.433 mi
Registration #12	2016-03-23	36.433 mi
Registration #13	2016-03-23	36.433 mi
Registration #14	2016-03-23	36.433 mi
Registration #15	2016-03-23	36.433 mi
Registration #16	2016-03-23	36.433 mi
Registration #17	2016-03-23	36.433 mi
Registration #18	2016-03-23	36.433 mi
Registration #19	2016-03-23	36.433 mi
Registration #20	2016-03-23	36.433 mi

More info >



Dimensions & weight

Width	2045 mm
Height	1317 mm
Length	4535 mm
Wheel base	2515 mm
Kerb weight	1845 kg
Max. allowed weight	2140 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	2
Number of axles	2
Engine number	11396330679052