



**F J56AVR**

report date: 2024-03-28

General information

Make	FIAT
Model	DUCATO 18 JTD BACK TO BACK C/C
Colour	White
Year of manufacture	2006
Gearbox	5 speed Manual

Engine & fuel consumption

Engine capacity	2.800 cc
Cylinders	4
Fuel type	Diesel



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-12-05
Pictures	20
Listing price	<a href="#">View report</a>



source: cargurus.co.uk

**MOT history**

<b>MOT expiry date</b>	2025-03-31
<b>MOT pass rate</b>	71 %
<b>MOT passed</b>	12
<b>Failed MOT tests</b>	5
<b>Total advice items</b>	30
<b>Total items failed</b>	7

**MOT #17** 2024-03-21 09:14**MOT test number** 780001007416**Result** ✓ Passed**Next expiry date** 2025-03-31**Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))**Advice** Power steering pipe/hose slightly corroded (2.1.5 (g) (i))**MOT #16** 2023-03-16 16:00**MOT test number** 271250152728**Result** ✓ Passed**Minor** Electrical wiring slightly deteriorated negative battery clamp - non standard constuction (4.11 (b) (i))**Advice** Power steering pipe/hose slightly corroded (2.1.5 (g) (i))**MOT #15** 2022-03-30 15:09**MOT test number** 935335937102**Result** ✓ Passed**Minor** Offside Rear fog lamp insecure partially obscured (4.5.1 (c) (i))**Advice** Power steering pipe/hose slightly corroded (2.1.5 (g) (i))**Advice** Note : parking brake efficiency low - passed on lockout only**Advice** Vehicles internal headlight adjuster altered to recheck lights

**MOT #14**

2022-03-30 15:09

**MOT test number**

395937438519

**Result****✗ Failed****Advice**

Power steering pipe/hose slightly corroded (2.1.5 (g) (i))

**Advice**

Note : parking brake efficiency low - passed on lockout only

**Advice**

Vehicles internal headlight adjuster altered to recheck lights

**Pass with rectification**

Offside Rear Direction indicator not working (4.4.1 (a) (ii))

**Minor**

Offside Rear fog lamp insecure partially obscured (4.5.1 (c) (i))

**MOT #13**

2021-04-01 16:00

**MOT test number**

918585211055

**Result****✓ Passed****Advice**

Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))

**Advice**

Front radiator crossmember slightly corroded

**Advice**

Rear Tyre slightly damaged/cracking or perishing all 4 rear tyres slightly perished and over 10 years old (5.2.3 (d) (ii))

**Advice**

Offside Rear Direction indicator slightly discoloured (4.4.3 (a))

**Advice**

Exhaust system slightly corroded

**MOT #12**

2019-06-22 07:09

**MOT test number**

909221515398

**Result****✓ Passed**

**MOT #11** 2018-06-21 14:41**MOT test number** 924297450998**Result** ✓ Passed

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Off side rear front axle hand brake now has a reading but still appears to be on the low side as do the others but they all lock out ?

**MOT #10** 2018-06-20 10:15**MOT test number** 980303437148**Result** ✗ Failed

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- MAJOR** Rear Rear fog lamp obviously incorrectly positioned (4.5.4 (a))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- MAJOR** Offside Rear Parking brake inoperative on one side front axle (1.4.1 (a))

**MOT #9** 2017-06-05 10:01**MOT test number** 383440950259**Result** ✓ Passed

- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #8** 2016-05-09 14:00**MOT test number** 644617886453**Result** ✓ Passed

**MOT #7** 2016-05-09 10:42**MOT test number** 778569600352**Result** ✗ Failed**Fail** Brakes imbalanced across an axle axle 2 (3.7.B.5b)**MOT #6** 2013-04-12 11:13**MOT test number** 678292203137**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #5** 2013-04-12 10:34**MOT test number** 198052403123**Result** ✗ Failed**Fail** Offside Rear Rear fog lamp not working (1.3.2b)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Offside Rear Registration plate lamp not working (1.1.C.1d)**Fail** Battery insecure (1.9.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2012-04-02 10:26**MOT test number** 695343992057**Result** ✓ Passed



MOT #3	2012-04-02 10:26
MOT test number	119983392038
Result	✗ Failed
Pass with rectification	Rear fog lamp not working (1.3.2b)
Pass with rectification	Offside Rear Registration plate lamp not working (1.1.C.1d)

MOT #2	2011-04-18 10:45
MOT test number	209668801176
Result	✓ Passed

MOT #1	2009-10-12 10:26
MOT test number	964065489290
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 December 2024

✓  
**MOT**  
**Expires:**  
31 March 2025

Tax status		Valid until 1 December
Days left		216
MOT expiry date		31 March 2025
Full MOT history		<a href="#">See MOT history</a>






Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	
Plate since	2019-09-29
Current registration	
Plate since	2019-09-29

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2006-10-13
Last registration	2024-03-21
Complete history	<a href="#">See info</a>



Registration #1	2006-10-13	23 mi
Registration #2	2009-10-12	16.311 mi
Registration #3	2011-04-18	19.251 mi
Registration #4	2012-04-02	19.255 mi
Registration #5	2013-04-12	19.419 mi
Registration #6	2013-04-12	19.419 mi
Registration #7	2016-05-09	19.423 mi
Registration #8	2016-05-09	19.423 mi
Registration #9	2017-06-05	19.616 mi
Registration #10	2024-03-21	23.000 mi
Registration #11	2024-03-21	23.000 mi
Registration #12	2024-03-21	23.000 mi
Registration #13	2024-03-21	23.000 mi
Registration #14	2024-03-21	23.000 mi
Registration #15	2024-03-21	23.000 mi
Registration #16	2024-03-21	23.000 mi
Registration #17	2024-03-21	23.000 mi
Registration #18	2024-03-21	23.000 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1998 mm
Kerb weight	1750 kg
Max. allowed weight	3500 kg

Additional information

Number of seats	2
Number of axles	2
Engine number	4163831