



General information

|                     |                      |
|---------------------|----------------------|
| Make                | FIAT                 |
| Model               | GRANDE PUNTO DYNAMIC |
| Colour              | Grey                 |
| Year of manufacture | 2009                 |
| Top speed           | 103 mph              |
| 0 - 60 mph          | 13.2 seconds         |
| Gearbox             | 5 speed Manual       |

Engine & fuel consumption

|                         |                     |
|-------------------------|---------------------|
| Power                   | 77 BHP              |
| Max. torque             | 115 Nm at 3.000 rpm |
| Engine capacity         | 1.368 cc            |
| Cylinders               | 4                   |
| Fuel type               | Petrol              |
| Consumption city        | 41.5 mpg            |
| Consumption extra urban | 56.5 mpg            |
| Consumption combined    | 49.6 mpg            |
| CO2 emission            | 134 g/km            |
| CO2 label               | E                   |





## MOT history

|                    |            |
|--------------------|------------|
| MOT expiry date    | 2021-03-30 |
| MOT pass rate      | 69 %       |
| MOT passed         | 9          |
| Failed MOT tests   | 4          |
| Total advice items | 9          |
| Total items failed | 5          |

|                  |  |
|------------------|--|
| MOT #13          | 2020-03-12 17:11                                       |
| MOT test number  | 726539765592   |
| Result           | ✓ Passed   |
| Next expiry date | 2021-03-30   |
| Advice           | Rear exhaust box deteriorated and heat shield insecure |

|                 |   |
|-----------------|---|
| MOT #12         | 2020-03-12 12:07  |
| MOT test number | 388054774505  |
| Result          | ✗ Failed  |
| Advice          | Rear exhaust box deteriorated and heat shield insecure        |
| Fail            | Offside Front Coil spring fractured or broken (5.3.1 (b) (i)) |

|                 |                             |
|-----------------|-----------------------------|
| MOT #11         | 2019-03-13 14:14            |
| MOT test number | 925296758010                |
| Result          | ✓ Passed                    |
| Advice          | Exhaust rearbox is corroded |

**MOT #10** 2019-03-13 12:13**MOT test number** 509401868533**Result** ✗ Failed**Advice** Exhaust rearbox is corroded**Fail** Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Fail** Offside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))**MOT #9** 2018-03-14 14:22**MOT test number** 218093559804**Result** ✓ Passed**MOT #8** 2018-03-14 11:04**MOT test number** 150074947883**Result** ✗ Failed**Fail** Offside Front coil spring broken (2.4.C.1a)**MOT #7** 2017-03-31 07:55**MOT test number** 962437273410**Result** ✓ Passed**MOT #6** 2016-02-18 11:24**MOT test number** 197003177582**Result** ✓ Passed**Advice** Nearside Rear Shock absorber has a light misting of oil (2.7.3)**MOT #5** 2015-03-12 08:21**MOT test number** 485291875001**Result** ✓ Passed

**MOT #4** 2014-07-03 09:39**MOT test number** 206674984121**Result** ✓ Passed**Notice** Slight corrosion on exhaust back box.**Notice** Both rear tyres worn slightly on outer edges of tread,treads are stepped design so edges not classed as part of central 3/4 of tread.**Advice** Offside Front Anti-roll bar linkage ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)**Notice** Both front tyres worn slightly on edges of tread,treads are stepped design so edges not classed as part of central 3/4 of tread.**MOT #3** 2013-06-12 17:43**MOT test number** 368763663152**Result** ✓ Passed**MOT #2** 2013-06-12 17:43**MOT test number** 238833863488**Result** ✗ Failed**Pass with rectification** Front coil spring fractured (2.4.C.1a)**MOT #1** 2012-07-14 12:34**MOT test number** 619186792193**Result** ✓ Passed



Tax & MOT check

✕  
Untaxed

Tax expired:  
21 November 2020

✕  
MOT

Expired:  
30 March 2021

Tax status

Expired at 21 November 2020

Days left

1255 days too late

MOT expiry date

30 March 2021

Full MOT history

[See MOT history](#)

Tax calculation

|   |            |
|---|------------|
| Vehicle class                           | 48         |
| Band                                    | E          |
| Single payment (12 months)              | £ 180,00,- |
| Single six month payment                | £ 99,00,-  |
| Total payable by 12 monthly instalments | £ 189,00,- |



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

|          |  |
|----------|--|
| Date     |  |
| Category |  |
| Type     |  |

Damage 2

|          |  |
|----------|--|
| Date     |  |
| Category |  |
| Type     |  |



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

|                             |          |
|-----------------------------|----------|
| Trade retail value          | £ 19,299 |
| Auction value               | £ 19,299 |
| Average private trade value | £ 19,299 |

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

|       |              |
|-------|--------------|
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |

More info >

Plate changes

See in this check if this FIAT had different number plates.

|                      |               |
|----------------------|---------------|
| Number of plates     | 1             |
| Current registration | <b>XXXXXX</b> |
| Plate since          | 2024-03-28    |
| Current registration | <b>XXXXXX</b> |
| Plate since          | 2024-03-28    |

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

|                   |            |      |
|-------------------|------------|------|
| Finance company   | XXXXXXXXXX | XXXX |
| Date of agreement | XXXXXXXXXX | XXXX |
| Agreement type    | XXXXXXXXXX | XXXX |
| Agreement term    | XXXXXXXXXX | XXXX |
| Agreement number  | XXXXXXXXXX | XXXX |
| Contact info      | XXXXXXXXXX | XXXX |

More info >



Mileage check

|                            |                          |
|----------------------------|--------------------------|
| Odometer                   | In miles                 |
| Mileage registrations      | 13                       |
| First mileage registration | 2009-07-16               |
| Last registration          | 2020-03-12               |
| Complete history           | <a href="#">See info</a> |



|                  |            |           |
|------------------|------------|-----------|
| Registration #1  | 2009-07-16 | 22 mi     |
| Registration #2  | 2012-07-14 | 25.062 mi |
| Registration #3  | 2013-06-12 | 30.984 mi |
| Registration #4  | 2014-07-03 | 42.241 mi |
| Registration #5  | 2015-03-12 | 47.109 mi |
| Registration #6  | 2016-02-18 | 50.922 mi |
| Registration #7  | 2017-03-31 | 55.251 mi |
| Registration #8  | 2018-03-20 | 59.277 mi |
| Registration #9  | 2019-03-20 | 63.277 mi |
| Registration #10 | 2020-03-12 | 67.277 mi |
| Registration #11 | 2021-03-12 | 71.277 mi |
| Registration #12 | 2022-03-12 | 75.277 mi |
| Registration #13 | 2023-03-12 | 79.277 mi |

More info >



Car features

The FIAT factory car options list is only available in the premium report.

|       |                  |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 |                  |
| S0482 |                  |
| S0501 |                  |
| S0566 |                  |
| S0567 |                  |
| S0569 |                  |

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

|                     |         |
|---------------------|---------|
| Width               | 1687 mm |
| Height              | 1490 mm |
| Length              | 4030 mm |
| Wheel base          | 2510 mm |
| Kerb weight         | 1025 kg |
| Max. allowed weight | 1585 kg |

Additional information

|                    |                       |
|--------------------|-----------------------|
| Fuel tank capacity | 45 l                  |
| Fuel delivery      | Multi-Point Injection |
| Number of doors    | 3                     |
| Number of seats    | 5                     |

|                 |         |
|-----------------|---------|
| Number of axles | 2       |
| Engine number   | 4924076 |