



RENAULT



report date: 2024-03-28

General information

Make	RENAULT
Model	TRAFIC SL27 DCI 115 SWB P/V
Colour	White
Year of manufacture	2007
Top speed	99 mph
0 - 60 mph	15.0 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	115 BHP
Max. torque	240 Nm at 1.600 rpm
Engine capacity	1.995 cc
Cylinders	4
Fuel type	Diesel
Consumption city	28.8 mpg
Consumption extra urban	40.4 mpg
Consumption combined	35.8 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-08-27
Pictures	9
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-09-07
MOT pass rate	67 %
MOT passed	14
Failed MOT tests	7
Total advice items	60
Total items failed	26

MOT #21 2023-08-31 08:10

MOT test number 809958335259

Result ✓ Passed

Next expiry date 2024-09-07

- Advice** Play in steering rack inner joint(s)
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Emissions limits were tested and met but the Diesel smoke meter couldn't register the reading due to the low levels of smoke produced
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Spare tyre defective

MOT #20 2022-08-09 11:24

MOT test number 162136917213

Result ✓ Passed

- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Spare tyre defective sidewall damaged
- Advice** Emissions limits were tested and met but the Diesel smoke meter couldn't register the reading due to the low levels of smoke produced

**MOT #19**

2022-08-08 10:02

MOT test number

521217912532

Result

✗ Failed

Fail Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))**Advice** Spare tyre defective sidewall damaged**Advice** Emissions limits were tested and met but the Diesel smoke meter couldn't register the reading due to the low levels of smoke produced**Fail** Offside Rear Direction indicator incorrect colour (4.4.3 (a))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MOT #18**

2021-09-08 14:46

MOT test number

930031107547

Result

✓ Passed

MOT #17

2021-03-30 08:10

MOT test number

417820966881

Result

✓ Passed

**MOT #16**

2020-03-09 14:30

MOT test number

841799542065

Result

✓ Passed

- Advice** Exhaust flexi slight leak
- Advice** Windscreen cracked
- Advice** Suspension bushes slightly deteriorating
- Advice** Oil leak
- Advice** Nearside seat belt slow retracting
- Advice** Slight play steering rack ram

MOT #15

2020-03-09 11:20

MOT test number

521296837102

Result

✗ Failed

- Advice** Suspension bushes slightly deteriorating
- Advice** Oil leak
- Advice** Nearside seat belt slow retracting
- Advice** Slight play steering rack ram
- Pass with rectification** Nearside Headlamp aim too high (4.1.2 (a))
- Advice** Exhaust flexi slight leak
- Advice** Windscreen cracked
- Fail** Offside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

**MOT #14**

2019-02-26 15:24

MOT test number

521562747025

Result

✓ Passed

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Rear Nail in tyre

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #13

2019-02-19 14:57

MOT test number

712993750607

Result

✗ Failed

Advice Offside Rear Nail in tyre

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Fail Oil leaking excessively from engine (8.4.1 (a) (i))

Fail Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail Offside Front Upper Macpherson strut pin or bush excessively worn (5.3.4 (a) (i))

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Fail Nearside Front Position lamp not working (4.2.1 (a))

Fail Offside Track rod end ball joint has excessive play (2.1.3 (b) (i))

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Fail Lower Engine mounting damaged or deteriorated resulting in excessive movement (6.1.8 (a) (i))

Fail Offside Headlamp aim too low (4.1.2 (a))

Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

**MOT #12** 2018-02-10 15:33**MOT test number** 184480403413**Result** ✓ Passed

- Advice** Oil leak
- Advice** Front brake discs worn
- Advice** Minor play front anti roll links
- Advice** Rear brake pads low

MOT #11 2018-02-10 15:33**MOT test number** 643321180851**Result** ✗ Failed

- Advice** Front brake discs worn
- Advice** Minor play front anti roll links
- Pass with rectification** Registration plate lamp not working (1.1.C.1d)
- Advice** Rear brake pads low
- Advice** Oil leak
- Pass with rectification** Windscreen wiper does not clear the windscreen effectively both (8.2.2)

MOT #10 2016-09-02 08:00**MOT test number** 390583117894**Result** ✓ Passed

**MOT #9** 2015-08-21 08:14**MOT test number** 225525865965**Result** ✓ Passed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Front Track rod end ball joint has slight play (2.2.B.1f)**Advice** Slight play in nearside front steering arm**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #8** 2014-07-31 13:35**MOT test number** 539832114208**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Oil leak**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #7** 2014-07-31 08:01**MOT test number** 659702714236**Result** ✗ Failed**Notice** Oil leak**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #6** 2013-08-02 11:36**MOT test number** 266514913232**Result** ✓ Passed

**MOT #5** 2013-08-01 13:24**MOT test number** 498473513255**Result** ✗ Failed

- Fail** Offside Front Track rod end ball joint has excessive play (2.2.B.1f)
- Fail** Front registration plate character(s) incorrectly spaced (6.3.4a)
- Fail** Nearside Front Track rod end ball joint has excessive play (2.2.B.1f)
- Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Fail** Rear registration plate character(s) incorrectly spaced (6.3.4a)
- Fail** Registration plate lamp not working (1.1.C.1d)

MOT #4 2013-01-30 11:28**MOT test number** 495140233076**Result** ✓ Passed**MOT #3** 2012-08-24 14:56**MOT test number** 398147332444**Result** ✓ Passed

- Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Notice** Play in steering rack inner joint(s)



MOT #2	2012-08-23 13:17
MOT test number	436236732235
Result	✗ Failed
Fail	Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
Notice	Play in steering rack inner joint(s)
Fail	Offside Front Track rod end ball joint has excessive play (2.2.B.1f)
Fail	Offside Front Suspension arm has excessive play in a ball joint (2.4.G.2)
Advice	Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
Fail	Nearside Front Track rod end ball joint has excessive play (2.2.B.1f)
Fail	Nearside Front Suspension arm has excessive play in a ball joint (2.4.G.2)

MOT #1	2011-08-23 11:39
MOT test number	387105231419
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 January 2025

✓
MOT
Expires:
7 September 2024

Tax status		Valid until 1 January
Days left		247
MOT expiry date		7 September 2024
Full MOT history		See MOT history



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-06-29
Current registration	*****
Plate since	2019-06-29

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	RENAULT FINANCE
Date of agreement	01/01/2024
Agreement type	FINANCE
Agreement term	36 months
Agreement number	123456789
Contact info	0123 456789

More info >



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2007-04-16
Last registration	2023-08-31
Complete history	See info



Registration #1	2007-04-16	29 mi
Registration #2	2011-08-23	67.227 mi
Registration #3	2012-08-23	81.651 mi
Registration #4	2012-08-24	81.651 mi
Registration #5	2013-01-30	86.248 mi
Registration #6	2013-08-01	91.251 mi
Registration #7	2013-08-02	91.254 mi
Registration #8	2014-07-31	101.855 mi
Registration #9	2014-07-31	101.859 mi
Registration #10	2015-08-21	115.561 mi
Registration #11	2016-09-02	124.734 mi
Registration #12	2018-02-10	135.638 mi
Registration #13	2019-05-20	151.557 mi
Registration #14	2019-05-20	151.557 mi
Registration #15	2019-05-20	151.557 mi
Registration #16	2019-05-20	151.557 mi
Registration #17	2019-05-20	151.557 mi
Registration #18	2019-05-20	151.557 mi
Registration #19	2019-05-20	151.557 mi
Registration #20	2019-05-20	151.557 mi
Registration #21	2019-05-20	151.557 mi
Registration #22	2019-05-20	151.557 mi
Registration #23	2019-05-20	151.557 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	2232 mm
Height	1944 mm
Length	4782 mm

Additional information

Fuel tank capacity	90 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	3
Engine number	C100792