





General information

| Make | VOLKSWAGEN | |
|---------------------|--------------------------------------|--|
| Model | TRANSPORTER T30 TDI P/V HIGHLINE BMT | |
| Colour | White | |
| Year of manufacture | 2017 | |
| Top speed | 98 mph | |
| 0 - 100 km/h | 11.2 seconds | |
| 0 - 60 mph | 15.3 seconds | |
| Gearbox | 5 speed Manual | |

Engine & fuel consumption

| Power | 110 kW / 150 HP / 101 BHP |
|-------------------------|---------------------------|
| Max. torque | 340 Nm at 1.500 rpm |
| Engine capacity | 1.968 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 34.0 mpg |
| Consumption extra urban | 48.7 mpg |
| Consumption combined | 42.2 mpg |
| CO2 emission | 159 g/km |
| CO2 label | G |







Internet history

Entry 1

Date

2021-06-08


Pictures

8

Listing price

View report









source: autotrader.co.uk



MOT history

| MOT expiry date | 2024-05-22 |
|--------------------|------------|
| MOT pass rate | 67 % |
| MOT passed | 4 |
| Failed MOT tests | 2 |
| Total advice items | 5 |
| Total items failed | 4 |

| MOT #6 | 2023-05-23 07:39 |
|---|------------------|
| MOT test number | 137464087053 |
| Result | ✓ Passed |
| Next expiry date | 2024-05-22 |
| Advice Under trays fitted | |
| Advice Rear Lower Engine mounting damaged but not to excess (6.1.8 (a) (i)) | |

| MOT #5 | 2023-05-19 08:46 |
|---|------------------|
| MOT test number | 926991728430 |
| Result | 🗙 Failed |
| Fail Offside Rear Coil spring fractured or broken (5.3.1 (b) (i)) | |
| Advice Under trays fitted | |
| Pass with rectification Windscreen washer provides insufficient washer liquid (3.5 (a)) |)) |
| Advice Rear Lower Engine mounting damaged but not to excess (6.1.8 (a) (i)) | |

| МОТ #4 | 2022-05-23 16:25 |
|-----------------|------------------|
| MOT test number | 692248175222 |
| Result | ✓ Passed |





| MOT #3 | 2022-05-19 12:02 |
|---|------------------|
| MOT test number | 394185637806 |
| Result | 🗙 Failed |
| Fail Offside Rear Brake disc significantly and obviously worn (1.1.14 (a) (i)) | |
| Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |
| Fail Service brake efficiency below requirements (1.2.2 (a) (i)) | |
| | |

| MOT #2 | 2021-11-03 14:20 |
|-----------------|------------------|
| MOT test number | 865384099969 |
| Result | ✓ Passed |
| | |
| MOT #1 | 2020-11-18 15:08 |

| MOT test number | 801529678057 |
|-----------------|--------------|
| Result | ✓ Passed |



Tax & MOT check

| ✓ Taxed | ✓ MOT Expires: |
|--------------------------|----------------------------------|
| 1 May 2025 Tax status | 22 May 2024 Valid until 1 May |
| Days left | 366 |
| MOT expiry date | 22 May 2024 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 39 |
|---------------------------|------------|
| Standard rate (12 months) | £ 320,00,- |
| Standard rate (6 months) | £ 176,00,- |





Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 | |
|----------|--------------|
| Date | FEIDER |
| Category | Lamp |
| Туре | |
| Damage 2 | AMPLE |
| Damage 2 | E CONTROL ON |
| Date | S. |
| Category | AMPY |
| Туре | |

Extra VOLKSWAGEN salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| Trade retail value | 4 10.700 |
|-----------------------------|----------|
| Auction value | 4 10.000 |
| Average private trade value | 4 10 700 |





Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

| And a second sec | |
|--|-------------|
| ********** | |
| ********* | |
| | |
| | |
| ********** | |
| ********* | |
| | |
| | More info > |
| Plate changes | |
| See in this check if this VOLKSWAGEN had different number plates. | |
| Number of plates | , |
| Current registration | |
| Plate since | |
| Format maintration | |
| Carrient registration | |
| Parla since | |





Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |





Mileage check

| Odometer | In miles |
|----------------------------|-----------------|
| Mileage registrations | 8 |
| First mileage registration | 2017-11-27 |
| Last registration | 2023-05-23 |
| Complete history | <u>See info</u> |



| Registration #1 | 2017-11-27 | 12 mi |
|-----------------|------------|------------|
| Registration #2 | 2020-11-18 | 30.143 mi |
| Registration #3 | | 11.777 esi |
| Registration #4 | 2021-11-03 | 37.930 mi |
| Registration #5 | | 11.777 esi |
| Registration #6 | | 11.777 est |
| Registration #7 | | 11.777 mi |
| Registration #8 | | 11.317 esi |





Car features

| S0225 | Air conditioning |
|--------|------------------|
| \$0295 | |
| \$0482 | |
| \$0501 | |
| 50566 | |
| \$0567 | |
| S0569 | |

Safety ratings

| NCAP rating | |
|----------------|-----------------|
| Adult | 79% |
| Children | 74% |
| Pedestrian | 32% |
| Safety systems | 57% |
| Overall rating | 66% |
| Video | see crash video |



| Dimensions & weight | |
|------------------------|------------------|
| Width | 2283 mm |
| Height | 1990 mm |
| Length | 4892 mm |
| Wheel base | 3000 mm |
| Kerb weight | 1916 kg |
| Max. allowed weight | 3000 kg |
| Additional information | |
| Fuel tank capacity | 80 |
| Fuel delivery | Direct Injection |
| Number of doors | 5 |

| Number of seats | 6 |
|-----------------|------------|
| Number of axles | 2 |
| Engine number | CXGA042804 |