



TOYOTA



report date: 2024-03-28

General information

Make	TOYOTA
Model	COROLLA T180 D-CAT
Colour	Blue
Year of manufacture	-
Top speed	109 mph
0 - 60 mph	8.1 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	174 BHP
Max. torque	400 Nm at 2.000 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	40.4 mpg
Consumption extra urban	61.4 mpg
Consumption combined	52.3 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-05-22
Pictures	19
Listing price	View report



source: autotrader.co.uk

**MOT history****MOT #15** 2021-01-04 14:37**MOT test number** 999394660966**Result** ✓ Passed**Next expiry date** 2022-01-25

- Advice** Rear Coil spring corroded Both (5.3.1 (b) (i))
- Advice** Offside Rear Outer Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** Rear chassis/sills corroded.
- Advice** Offside Front shock absorber corroded at spring platform.
- Advice** Rear axle pivot bushes poor condition.

MOT #14 2021-01-04 13:06**MOT test number** 854798518067**Result** ✗ Failed

- Advice** Rear axle pivot bushes poor condition.
- MAJOR** Parking brake lever has excessive movement indicating incorrect adjustment (1.1.6 (c))
- MAJOR** Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))
- Advice** Offside Rear Outer Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** Rear chassis/sills corroded.
- Advice** Offside Front shock absorber corroded at spring platform.
- Advice** Rear Coil spring corroded Both (5.3.1 (b) (i))

**MOT #13**

2019-07-09 14:28

MOT test number

278004359802

Result

✓ Passed

- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Handbrake has little reserve travel
- Advice** Offside Rear Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))
- Advice** Nearside Rear Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))
- Advice** Rear Axle swivel pins and bushes swivel pin and/or bush slightly worn (5.1.2 (b) (i))

MOT #12

2018-06-29 08:44

MOT test number

928354946976

Result

✓ Passed

- Advice** Nearside Rear axle bush slightly perished.
- Advice** Offside Rear Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))
- Advice** Nearside Rear Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))
- Advice** Handbrake lever has little reserve travel.
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**MOT #11**

2018-06-29 08:44

MOT test number

986505339750

Result**✗ Failed**

- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Offside Rear Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))
- Advice** Handbrake lever has little reserve travel.
- Pass with rectification** Windscreen wiper does not clear the windscreen effectively Both (3.4 (b) (ii))
- Advice** Nearside Rear Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))
- Advice** Nearside Rear axle bush slightly perished.

MOT #10

2017-07-11 15:52

MOT test number

720294399085

Result**✓ Passed**

- Advice** Nearside Rear coil spring corroded (2.4.C.1b)
- Advice** Wipers poor
- Advice** Nearside Rear Nail in tyre
- Advice** Parking brake lever has little reserve travel (3.1.6b)
- Advice** Offside Rear coil spring corroded (2.4.C.1b)

MOT #9

2016-07-26 11:46

MOT test number

187145246053

Result**✓ Passed****MOT #8**

2015-07-23 16:51

MOT test number

706734305236

Result**✓ Passed**

**MOT #7** 2015-07-23 16:51**MOT test number** 489624005299**Result** ✗ Failed**Pass with rectification** Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #6** 2014-08-27 09:44**MOT test number** 878869934237**Result** ✓ Passed**MOT #5** 2013-09-06 09:35**MOT test number** 667459743223**Result** ✓ Passed**Notice** Passenger seat(s) missing at time of test**Advice** Parking brake lever has little reserve travel (3.1.6b)**Notice** Under-trays fitted obscuring some underside components**Advice** Offside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)**Notice** Child seat fitted not allowing full inspection of adult belt

**MOT #4** 2013-09-06 09:35**MOT test number** 267589943254**Result** ✗ Failed**Pass with rectification** Nearside Headlamp aim too high (1.8)**Advice** Parking brake lever has little reserve travel (3.1.6b)**Notice** Child seat fitted not allowing full inspection of adult belt**Notice** Passenger seat(s) missing at time of test**Pass with rectification** Nearside Registration plate lamp not working (1.1.C.1d)**Pass with rectification** Offside Headlamp aim too high (1.8)**Advice** Offside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)**Notice** Under-trays fitted obscuring some underside components**MOT #3** 2012-09-08 09:01**MOT test number** 139802252282**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**MOT #2** 2011-08-23 16:25**MOT test number** 828755831267**Result** ✓ Passed**MOT #1** 2011-08-23 16:25**MOT test number** 899825631221**Result** ✗ Failed**Pass with rectification** Nearside Headlamp aim too low (1.8)**Pass with rectification** Offside Headlamp aim too low (1.8)



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	RK58UZA
Plate since	2019-09-28
Current registration	RK58UZA
Plate since	2019-09-28

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2008-09-01
Last registration	2021-01-04
Complete history	See info



Registration #1	2008-09-01	28 mi
Registration #2	2011-08-23	76.346 mi
Registration #3	2012-09-08	84.678 mi
Registration #4	2013-09-06	93.989 mi
Registration #5	2014-08-27	103.537 mi
Registration #6	2015-07-23	110.842 mi
Registration #7	2016-07-26	118.888 mi
Registration #8	2016-07-26	118.888 mi
Registration #9	2016-07-26	118.888 mi
Registration #10	2016-07-26	118.888 mi
Registration #11	2016-07-26	118.888 mi
Registration #12	2016-07-26	118.888 mi
Registration #13	2016-07-26	118.888 mi
Registration #14	2016-07-26	118.888 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

★★★★★

Video

[see crash video](#)



Dimensions & weight

Width	1760 mm
Height	1515 mm
Length	4220 mm
Wheel base	2600 mm
Kerb weight	1470 kg
Max. allowed weight	1920 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	4405305329