



report date: 2024-03-28

General information

Make	CITROEN
Model	DISPATCH 1000 L1H1 ENTERPRISE P/V HDI
Colour	Grey
Year of manufacture	2016
Top speed	90 mph
0 - 60 mph	16.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	90 BHP
Max. torque	180 Nm at 1.500 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	35.8 mpg
Consumption extra urban	45.6 mpg
Consumption combined	42.2 mpg
CO2 emission	177 g/km
CO2 label	I





MOT history

MOT expiry date	2025-04-09
MOT pass rate	67 %
MOT passed	6
Failed MOT tests	3
Total advice items	23
Total items failed	14

MOT #9	2024-04-10 14:17
MOT test number	425355532301
Result	✓ Passed
Next expiry date	2025-04-09
Minor	Offside Suspension component ball joint dust cover severely deteriorated (5.3.4 (b) (i))
Advice	Offside Front Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Minor	Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated leaking grease (6.1.7 (g) (i))

**MOT #8**

2024-03-27 16:41

MOT test number

912206163712

Result**✗ Failed**

- Fail** Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))
- Minor** Offside Suspension component ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))
- Fail** Power steering component leaking (2.1.5 (a))
- Fail** Windscreen washer provides insufficient washer liquid (3.5 (a))
- Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))
- Minor** Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated leaking grease (6.1.7 (g) (i))
- Fail** Rear Exhaust system insecure (6.1.2 (a))
- Advice** Offside Front Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #7

2023-02-13 16:41

MOT test number

699805495760

Result**✓ Passed**

- Minor** Nearside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #6**

2023-02-13 09:15

MOT test number

475196019259

Result**✗ Failed****Fail** Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Fail** Rear Direction indicator incorrect colour Both (4.4.3 (a))**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Fail** Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))**Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Fail** Windscreen washer not working (3.5 (a))**Minor** Nearside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Rear Exhaust system insecure (6.1.2 (a))**MOT #5**

2022-02-11 16:44

MOT test number

950024307275

Result**✓ Passed****MOT #4**

2021-05-14 09:13

MOT test number

120106587268

Result**✓ Passed****Advice** Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))

**MOT #3** 2021-05-14 09:13**MOT test number** 982450632973**Result** ✗ Failed**Advice** Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))**Pass with rectification** Nearside Front Headlamp aim too low (4.1.2 (a))**MOT #2** 2020-06-20 11:28**MOT test number** 240940112573**Result** ✓ Passed**Advice** Rear Tyre slightly damaged/cracking or perishing both (5.2.3 (d) (ii))**MOT #1** 2019-05-21 13:40**MOT test number** 275038382778**Result** ✓ Passed**Advice** Nearside Rear Outer Tyre slightly damaged/cracking or perishing tyre wall beginning to perish (5.2.3 (d) (ii))**Advice** Nearside Front Outer Tyre slightly damaged/cracking or perishing tyre wall beginning to perish (5.2.3 (d) (ii))



Tax & MOT check

✓
Taxed
Tax due:
1 April 2025

✓
MOT
Expires:
9 April 2025

Tax status	Valid until 1 April
Days left	337
MOT expiry date	9 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	
Plate since	2019-09-29
Current registration	
Plate since	2019-09-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2016-05-27
Last registration	2024-04-10
Complete history	See info



Registration #1	2016-05-27	24 mi
Registration #2	2019-05-21	24.605 mi
Registration #3	2020-06-20	30.511 mi
Registration #4	2021-05-14	34.698 mi
Registration #5	2021-05-14	34.698 mi
Registration #6	2022-05-20	35.277 mi
Registration #7	2022-05-20	35.277 mi
Registration #8	2022-05-20	35.277 mi
Registration #9	2022-05-20	35.277 mi
Registration #10	2024-04-10	35.277 mi

More info >



Additional information

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	3
Engine number	JBDF0094545