



PEUGEOT



report date: 2024-03-28

General information

| | |
|---------------------|----------------|
| Make | PEUGEOT |
| Model | 307 SPORT HDI |
| Colour | Red |
| Year of manufacture | 2006 |
| Top speed | 117 mph |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 107 BHP |
| Max. torque | 240 Nm at 1.750 rpm |
| Engine capacity | 1.560 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 46.3 mpg |
| Consumption extra urban | 65.7 mpg |
| Consumption combined | 57.7 mpg |
| CO2 emission | 129 g/km |
| CO2 label | D |





Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-10-25 |
| Pictures | 31 |
| Listing price | View report |



source: [autotrader.co.uk](https://www.autotrader.co.uk)

**MOT history**

| | |
|---------------------------|------------|
| MOT expiry date | 2024-05-16 |
| MOT pass rate | 74 % |
| MOT passed | 14 |
| Failed MOT tests | 5 |
| Total advice items | 26 |
| Total items failed | 6 |

MOT #19 2023-05-17 15:03**MOT test number** 260466640484**Result** Passed**Next expiry date** 2024-05-16**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #18** 2023-05-17 15:03**MOT test number** 868646174516**Result** Failed**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Pass with rectification** Windscreen washer provides insufficient washer liquid (3.5 (a))**MOT #17** 2022-03-03 13:27**MOT test number** 191924657682**Result** Passed

**MOT #16**

2022-03-02 10:49

MOT test number

177629486758

Result**✗ Failed****MAJOR** Rear Tyre(s) with different aspect ratios are fitted on the same axle. (5.2.3 (b))**DANGEROUS** Nearside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Advice** Offside Front Nail in tyre**DANGEROUS** Offside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**MOT #15**

2021-02-04 10:49

MOT test number

172078552966

Result**✓ Passed****Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Play in steering rack inner joint(s)**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Minor** Nearside Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))

**MOT #14**

2021-02-04 10:49

MOT test number

229378223721

Result**✗ Failed****Minor** Nearside Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Pass with rectification** Windscreen washer not working (3.5 (a))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Pass with rectification** Offside Stop lamp(s) not working (4.3.1 (a) (ii))**Advice** Play in steering rack inner joint(s)**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Pass with rectification** Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))**MOT #13**

2019-11-01 11:28

MOT test number

160338746091

Result**✓ Passed****Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Rear Service brake binding but not excessively (1.2.1 (f))**Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))**MOT #12**

2018-09-19 12:55

MOT test number

628027436637

Result**✓ Passed**

**MOT #11** 2018-09-19 12:55**MOT test number** 471159646458**Result** ✗ Failed**Pass with rectification** Nearside Headlamp aim too low (4.1.2 (a))**MOT #10** 2017-09-20 09:37**MOT test number** 523009310580**Result** ✓ Passed**MOT #9** 2016-10-07 13:08**MOT test number** 795094171636**Result** ✓ Passed**MOT #8** 2016-10-07 11:52**MOT test number** 738398165462**Result** ✗ Failed**Fail** Offside Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)**MOT #7** 2015-10-06 12:44**MOT test number** 893399142370**Result** ✓ Passed**MOT #6** 2014-10-06 09:35**MOT test number** 107289374230**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)



| | |
|---------------|------------------|
| MOT #5 | 2013-10-09 14:36 |
|---------------|------------------|

| | |
|------------------------|--------------|
| MOT test number | 305072783445 |
|------------------------|--------------|

| | |
|---------------|----------|
| Result | ✓ Passed |
|---------------|----------|

| | |
|---------------|--|
| Advice | Nearside Rear Tyre worn close to the legal limit (4.1.E.1) |
|---------------|--|

| | |
|---------------|------------------|
| MOT #4 | 2012-10-03 09:25 |
|---------------|------------------|

| | |
|------------------------|--------------|
| MOT test number | 628347372246 |
|------------------------|--------------|

| | |
|---------------|----------|
| Result | ✓ Passed |
|---------------|----------|

| | |
|---------------|--|
| Advice | Offside Front Tyre worn close to the legal limit (4.1.E.1) |
|---------------|--|

| | |
|---------------|------------------|
| MOT #3 | 2011-10-10 17:39 |
|---------------|------------------|

| | |
|------------------------|--------------|
| MOT test number | 579433381289 |
|------------------------|--------------|

| | |
|---------------|----------|
| Result | ✓ Passed |
|---------------|----------|

| | |
|---------------|------------------|
| MOT #2 | 2010-09-16 12:54 |
|---------------|------------------|

| | |
|------------------------|--------------|
| MOT test number | 690499550223 |
|------------------------|--------------|

| | |
|---------------|----------|
| Result | ✓ Passed |
|---------------|----------|

| | |
|---------------|------------------|
| MOT #1 | 2009-09-18 15:12 |
|---------------|------------------|

| | |
|------------------------|--------------|
| MOT test number | 131061569257 |
|------------------------|--------------|

| | |
|---------------|----------|
| Result | ✓ Passed |
|---------------|----------|



Tax & MOT check

✓
Taxed
Tax due:
1 July 2024

✓
MOT
Expires:
16 May 2024

| | |
|-------------------------|---------------------------------|
| Tax status | Valid until 1 July |
| Days left | 63 |
| MOT expiry date | 16 May 2024 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|--|------------|
| Vehicle class | 49 |
| Band | D |
| Single payment (12 months) | £ 150,00,- |
| Single six month payment | £ 82,50,- |
| Total payable by 12 monthly instalments | £ 157,50,- |



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|--------------|
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

| | |
|----------------------|----------------|
| Number of plates | 1 |
| Current registration | FL56UBC |
| Plate since | 2019-03-28 |
| Current registration | FL56UBC |
| Plate since | 2019-03-28 |

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

| | | |
|-------------------|----------|----------|
| Finance company | REDACTED | REDACTED |
| Date of agreement | REDACTED | REDACTED |
| Agreement type | REDACTED | REDACTED |
| Agreement term | REDACTED | REDACTED |
| Agreement number | REDACTED | REDACTED |
| Contact info | REDACTED | REDACTED |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 21 |
| First mileage registration | 2006-09-20 |
| Last registration | 2023-05-17 |
| Complete history | See info |



| | | |
|------------------|------------|-----------|
| Registration #1 | 2006-09-20 | 26 mi |
| Registration #2 | 2009-09-18 | 7.127 mi |
| Registration #3 | 2010-09-16 | 9.325 mi |
| Registration #4 | 2011-10-10 | 15.421 mi |
| Registration #5 | 2012-10-03 | 24.129 mi |
| Registration #6 | 2013-10-09 | 31.443 mi |
| Registration #7 | 2014-10-06 | 35.667 mi |
| Registration #8 | 2015-10-06 | 37.747 mi |
| Registration #9 | 2016-10-07 | 38.920 mi |
| Registration #10 | 2016-10-07 | 38.920 mi |
| Registration #11 | 2017-09-20 | 39.688 mi |
| Registration #12 | 2018-05-20 | 40.377 mi |
| Registration #13 | 2019-05-20 | 41.077 mi |
| Registration #14 | 2020-05-20 | 41.777 mi |
| Registration #15 | 2021-05-20 | 42.477 mi |
| Registration #16 | 2022-05-20 | 43.177 mi |
| Registration #17 | 2023-05-17 | 43.877 mi |
| Registration #18 | 2023-05-17 | 43.877 mi |
| Registration #19 | 2023-05-17 | 43.877 mi |
| Registration #20 | 2023-05-17 | 43.877 mi |
| Registration #21 | 2023-05-17 | 43.877 mi |

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video [see crash video](#)



Dimensions & weight

| | |
|---------------------|---------|
| Width | 1757 mm |
| Height | 1530 mm |
| Length | 4211 mm |
| Wheel base | 2608 mm |
| Kerb weight | 1335 kg |
| Max. allowed weight | 1770 kg |

Additional information

| | |
|--------------------|------------------|
| Fuel tank capacity | 60 l |
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats | 5 |

| | |
|------------------------|-------------|
| Number of axles | 2 |
| Engine number | JB603078898 |