



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	POLO S
Colour	Red
Year of manufacture	2010
Top speed	98 mph
0 - 60 mph	16.1 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	59 BHP
Max. torque	108 Nm at 3.000 rpm
Engine capacity	1.198 cc
Cylinders	3
Fuel type	Petrol
Consumption city	38.7 mpg
Consumption extra urban	62.8 mpg
Consumption combined	51.4 mpg
CO2 emission	128 g/km
CO2 label	D



**MOT history**

<b>MOT expiry date</b>	2021-01-04
<b>MOT pass rate</b>	70 %
<b>MOT passed</b>	7
<b>Failed MOT tests</b>	3
<b>Total advice items</b>	30
<b>Total items failed</b>	4

<b>MOT #10</b>	2019-07-05 14:25
----------------	------------------

<b>MOT test number</b>	351375769305
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>Next expiry date</b>	2021-01-04
-------------------------	------------

**Advice** Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

**Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**Advice** Under shield fitted obscuring some underside components

**Advice** Child Seat fitted not allowing full inspection of adult belt

**Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

**MOT #9**

2019-06-25 15:55

**MOT test number**

872275196155

**Result****✗ Failed****Advice** Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**MAJOR** Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))**MAJOR** Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))**Advice** Under shield fitted obscuring some underside components**Advice** Child Seat fitted not allowing full inspection of adult belt**MAJOR** Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**MOT #8**

2018-06-21 11:08

**MOT test number**

462029274064

**Result****✓ Passed****Advice** Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Advice** Front Flexi exhaust joint/bend slightly blowing**MOT #7**

2018-06-21 11:08

**MOT test number**

922984709936

**Result****✗ Failed****Pass with rectification** Nearside Rear Registration plate lamp does not illuminate simultaneously with the position lamps (4.7.2 (a))**Advice** Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Advice** Front Flexi exhaust joint/bend slightly blowing



<b>MOT #6</b>	2017-06-28 10:29
<b>MOT test number</b>	930889515901
<b>Result</b>	✓ Passed
<b>Advice</b>	Large under trays fitted

<b>MOT #5</b>	2016-06-29 14:05
<b>MOT test number</b>	128327307557
<b>Result</b>	✓ Passed
<b>Advice</b>	Offside Rear Shock absorber has a light misting of oil (2.7.3)
<b>Advice</b>	Parking brake lever has little reserve travel (3.1.6b)
<b>Advice</b>	Nearside Front Upper Anti-roll bar linkage ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)

<b>MOT #4</b>	2015-06-26 09:11
<b>MOT test number</b>	645967675173
<b>Result</b>	✓ Passed
<b>Advice</b>	Offside Rear Shock absorber has a light misting of oil (2.7.3)

<b>MOT #3</b>	2014-06-27 16:12
<b>MOT test number</b>	257298674170
<b>Result</b>	✓ Passed
<b>Notice</b>	Items removed from driver's view prior to test
<b>Advice</b>	Offside Rear Tyre worn close to the legal limit (4.1.E.1)
<b>Notice</b>	Nail in offside rear tyre
<b>Advice</b>	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)



MOT #2 2013-06-17 15:16

MOT test number 625898563149

Result ✓ Passed

**Notice** Offside rear tyre perishing at tread area

**Notice** Nearside rear tyre perishing at tread area

MOT #1 2013-06-17 09:54

MOT test number 495598063137

Result ✗ Failed

**Notice** Nearside rear tyre perishing at tread area

**Fail** Offside Front Track rod end ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.2.C.1c)

**Fail** Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)

**Notice** Offside rear tyre perishing at tread area

**Fail** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	7
Current registration	*****
Plate since	2019-06-29
Current registration	*****
Plate since	2019-06-29

More info >





Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2010-06-21
Last registration	2019-07-05
Complete history	<a href="#">See info</a>



Registration #1	2010-06-21	12 mi
Registration #2	2013-06-17	18.773 mi
Registration #3	2013-06-17	18.773 mi
Registration #4	2014-06-27	31.518 mi
Registration #5	2015-06-26	48.689 mi
Registration #6	2016-06-29	67.413 mi
Registration #7	2017-06-29	86.137 mi
Registration #8	2018-06-29	104.861 mi
Registration #9	2019-06-29	123.585 mi
Registration #10	2020-06-29	142.309 mi
Registration #11	2021-06-29	161.033 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	90%
Children	86%
Pedestrian	41%
Safety systems	71%
Overall rating	78%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1682 mm
Height	1462 mm
Length	3970 mm
Wheel base	2470 mm
Kerb weight	1067 kg
Max. allowed weight	1550 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5

Number of seats	5
Engine number	CGP 038843