



report date: 2024-03-29

General information

| | |
|---------------------|------------------------|
| Make | VOLVO |
| Model | C30 D SE |
| Colour | Red |
| Year of manufacture | 2010 |
| Top speed | 127 mph |
| 0 - 60 mph | 9.0 seconds |
| Gearbox | 6 speed Semi-Automatic |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 136 BHP |
| Max. torque | 320 Nm at 2.000 rpm |
| Engine capacity | 1.997 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 37.2 mpg |
| Consumption extra urban | 57.7 mpg |
| Consumption combined | 47.9 mpg |
| CO2 emission | 156 g/km |
| CO2 label | G |





Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2022-03-31 |
| Pictures | 20 |
| Listing price | View report |



source: cargurus.co.uk



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2024-05-18 |
| MOT pass rate | 82 % |
| MOT passed | 9 |
| Failed MOT tests | 2 |
| Total advice items | 14 |
| Total items failed | 7 |

| | |
|---------|------------------|
| MOT #11 | 2023-05-03 10:32 |
|---------|------------------|

| | |
|-----------------|--------------|
| MOT test number | 130492787528 |
|-----------------|--------------|

| | |
|--------|----------|
| Result | ✓ Passed |
|--------|----------|

| | |
|------------------|------------|
| Next expiry date | 2024-05-18 |
|------------------|------------|

- Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

**MOT #10** 2023-05-03 08:50**MOT test number** 228429966549**Result** ✗ Failed

- Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt
- Fail** Emissions unable to be completed (8.2.2.2 (e))
- Fail** Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
- Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Offside Rear Direction indicator incorrect colour (4.4.3 (a))
- Advice** Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Fail** Exhaust on a vehicle fitted with a diesel particulate filter emits visible smoke of any colour (8.2.2.2 (d))
- Fail** Nearside Rear Direction indicator incorrect colour (4.4.3 (a))
- Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

MOT #9 2022-05-19 10:15**MOT test number** 688446268004**Result** ✓ Passed**MOT #8** 2022-05-17 12:59**MOT test number** 720870563015**Result** ✗ Failed

- Fail** Nearside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))
- Fail** Offside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))

MOT #7 2021-08-18 16:57**MOT test number** 680289925881**Result** ✓ Passed



| | |
|------------------------|--|
| MOT #6 | 2019-02-27 16:10 |
| MOT test number | 294433017504 |
| Result | ✓ Passed |
| Advice | Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) |
| Advice | Front Registration plate deteriorated but not likely to be misread (0.1 (b)) |
| Advice | Rear Brake pad(s) wearing thin (1.1.13 (a) (ii)) |
| MOT #5 | 2018-03-12 17:12 |
| MOT test number | 650671295276 |
| Result | ✓ Passed |
| MOT #4 | 2017-03-28 17:00 |
| MOT test number | 342083280004 |
| Result | ✓ Passed |
| MOT #3 | 2016-02-06 15:30 |
| MOT test number | 643928913285 |
| Result | ✓ Passed |
| MOT #2 | 2015-01-12 17:15 |
| MOT test number | 825872915052 |
| Result | ✓ Passed |
| MOT #1 | 2013-05-14 16:15 |
| MOT test number | 706704833158 |
| Result | ✓ Passed |



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
18 May 2024

| | |
|-------------------------|---------------------------------|
| Tax status | Valid until 1 February |
| Days left | 278 |
| MOT expiry date | 18 May 2024 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|--|------------|
| Vehicle class | 49 |
| Band | G |
| Single payment (12 months) | £ 240,00,- |
| Single six month payment | £ 132,00,- |
| Total payable by 12 monthly instalments | £ 252,00,- |



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 10,000 |
| Auction value | £ 10,000 |
| Average private trade value | £ 10,000 |

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|------------|
| Owner | Start date |
| Owner | Start date |
| Owner | Start date |
| Owner | Start date |
| Owner | Start date |
| Owner | Start date |
| Owner | Start date |

More info >

Plate changes

See in this check if this VOLVO had different number plates.

| | |
|----------------------|----------------|
| Number of plates | 1 |
| Current registration | DN10WWD |
| Plate since | 2019-09-29 |
| Current registration | DN10WWD |
| Plate since | 2019-09-29 |

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

| | | |
|-------------------|------------|------|
| Finance company | XXXXXXXXXX | XXXX |
| Date of agreement | XXXXXXXXXX | XXXX |
| Agreement type | XXXXXXXXXX | XXXX |
| Agreement term | XXXXXXXXXX | XXXX |
| Agreement number | XXXXXXXXXX | XXXX |
| Contact info | XXXXXXXXXX | XXXX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 13 |
| First mileage registration | 2010-06-07 |
| Last registration | 2023-05-03 |
| Complete history | See info |



| | | |
|------------------|------------|------------|
| Registration #1 | 2010-06-07 | 26 mi |
| Registration #2 | 2013-05-14 | 36.191 mi |
| Registration #3 | 2015-01-12 | 60.395 mi |
| Registration #4 | 2016-02-06 | 75.757 mi |
| Registration #5 | 2017-03-28 | 80.023 mi |
| Registration #6 | 2018-03-12 | 83.540 mi |
| Registration #7 | 2019-02-27 | 87.000 mi |
| Registration #8 | 2020-05-20 | 91.277 mi |
| Registration #9 | 2021-05-20 | 95.277 mi |
| Registration #10 | 2022-05-20 | 99.277 mi |
| Registration #11 | 2023-05-03 | 103.277 mi |
| Registration #12 | 2024-03-29 | 107.277 mi |
| Registration #13 | 2025-03-29 | 111.277 mi |

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

| | |
|----------------|---------------------------------|
| NCAP rating | ★★★★★ |
| Adult | 91% |
| Children | 78% |
| Pedestrian | 26% |
| Safety systems | 71% |
| Overall rating | 73% |
| Video | see crash video |



Dimensions & weight

| | |
|---------------------|---------|
| Width | 1782 mm |
| Height | 1447 mm |
| Length | 4252 mm |
| Wheel base | 2640 mm |
| Kerb weight | 1450 kg |
| Max. allowed weight | 1840 kg |

Additional information

| | |
|--------------------|------------------|
| Fuel tank capacity | 52 l |
| Fuel delivery | Direct Injection |
| Number of doors | 3 |
| Number of seats | 4 |

| | |
|------------------------|--------|
| Number of axles | 2 |
| Engine number | 768432 |