



report date: 2024-03-28

General information

Make	VOLVO
Model	C30 D DRIVE R-DESIGN
Colour	Grey
Year of manufacture	-
Top speed	118 mph
0 - 60 mph	10.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	109 BHP
Max. torque	240 Nm at 1.750 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	49.6 mpg
Consumption extra urban	74.3 mpg
Consumption combined	62.8 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-12-16
Pictures	0
Listing price	View report

source: cargurus.co.uk

**MOT history**

MOT #11	2021-10-12 08:40
MOT test number	123342748761
Result	✓ Passed
Next expiry date	2022-11-04
Advice	Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
Advice	Front Registration plate deteriorated but not likely to be misread (0.1 (b))

MOT #10	2020-11-05 10:03
MOT test number	388319980049
Result	✓ Passed

MOT #9	2020-11-05 10:03
MOT test number	772791554036
Result	✗ Failed
Pass with rectification	Nearside Position lamp not working (4.2.1 (a) (ii))

MOT #8	2019-04-25 12:07
MOT test number	270691064810
Result	✓ Passed
Advice	Rear Inner Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))

MOT #7	2018-04-09 10:29
MOT test number	387124562082
Result	✓ Passed
Advice	Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
Advice	Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #6** 2018-04-09 10:29**MOT test number** 505468207753**Result** ✗ Failed**Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Pass with rectification** Front Windscreen washer provides insufficient washer liquid (8.2.3)**Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Pass with rectification** Offside Rear Registration plate lamp not working (1.1.C.1d)**MOT #5** 2017-04-12 09:01**MOT test number** 826471246402**Result** ✓ Passed**MOT #4** 2016-04-15 15:21**MOT test number** 778109902058**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2015-04-23 15:11**MOT test number** 939883015196**Result** ✓ Passed**Notice** Cut in nearside front tyre**Notice** Engine covers fitted obscuring some components in the engine bay**Notice** Nearside/offside front tyres worn on inner edges**Notice** Under-trays fitted obscuring some underside components



MOT #2	2014-04-25 14:51
MOT test number	285815314429
Result	✓ Passed
MOT #1	2013-04-23 10:59
MOT test number	366733513162
Result	✓ Passed



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2010-04-30
Last registration	2021-10-12
Complete history	See info



Registration #1	2010-04-30	23 mi
Registration #2	2013-04-23	39.726 mi
Registration #3	2014-04-25	52.562 mi
Registration #4	2015-04-23	64.733 mi
Registration #5	2016-04-15	76.393 mi
Registration #6	2017-04-12	88.026 mi
Registration #7	2018-04-09	96.288 mi
Registration #8	2019-05-20	105.277 mi
Registration #9	2020-05-20	115.277 mi
Registration #10	2021-05-20	125.277 mi
Registration #11	2022-05-20	135.277 mi
Registration #12	2023-05-20	145.277 mi
Registration #13	2024-05-20	155.277 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	91%
Children	78%
Pedestrian	26%
Safety systems	71%
Overall rating	73%
Video	see crash video



Dimensions & weight

Width	1770 mm
Height	1457 mm
Length	4522 mm
Wheel base	2640 mm
Kerb weight	1442 kg
Max. allowed weight	1900 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	957553