





report date: 2024-03-28

## General information

| Make                | CITROEN          |
|---------------------|------------------|
| Model               | DS3 E-HDI DSTYLE |
| Colour              | White            |
| Year of manufacture | 2015             |
| Top speed           | 113 mph          |
| 0 - 60 mph          | 12.5 seconds     |
| Gearbox             | 5 speed Manual   |

## Engine & fuel consumption

| Power                   | 90 BHP              |
|-------------------------|---------------------|
| Max. torque             | 230 Nm at 1.750 rpm |
| Engine capacity         | 1.560 cc            |
| Cylinders               | 4                   |
| Fuel type               | Diesel              |
| Consumption city        | 64.2 mpg            |
| Consumption extra urban | 85.6 mpg            |
| Consumption combined    | 76.4 mpg            |
| CO2 emission            | 95 g/km             |
| CO2 label               | A                   |



CarCheck.co.uk page 1/12



SL15XGA

report date: 2024-03-28

## Internet history

#### Entry 3

| Date | 2022-11-14 |
|------|------------|
|      |            |

Pictures 0

Listing price <u>View report</u>

#### source: carcraft.co.uk

#### Entry 2

| Date | 2022-09-21 |
|------|------------|
|      |            |

Pictures 12

Listing price <u>View report</u>









source: cargurus.co.uk


#### Entry 1

| Date | 2021-08-19 |
|------|------------|
|      |            |


Pictures 13

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/12



MOT history

| MOT expiry date    | 2024-10-16 |
|--------------------|------------|
| MOT pass rate      | 64 %       |
| MOT passed         | 7          |
| Failed MOT tests   | 4          |
| Total advice items | 14         |
| Total items failed | 6          |

| MOT #11  | 2023-10-12 11:59              |
|--|-------------------------------|
| MOT test number  | 707905052681                  |
| Result   | <b>✓</b> Passed               |
| Next expiry date   | 2024-10-16                    |
| Advice TPS on indicating low pressure  |                               |
| Minor  (i))  Offside Registration plate lamp inoperative in the case of multiple lamps | s or light sources (4.7.1 (b) |

| MOT #10                    |  | 2023-10-09 12:33              |
|----------------------------|--|-------------------------------|
| MOT test number            |  | 440277526278                  |
| Result                     |  | <b>X</b> Failed               |
| Advice Nearside Rear Ty    | re worn close to legal limit/worn on edge Also | o cracked (5.2.3 (e))         |
| Advice TPS on indicating   | low pressure                                   |                               |
| Fail Registration plate la | mp inoperative in the case of a single lamp o  | or all lamps (4.7.1 (b) (ii)) |
| Fail Offside Front Tyre tr | ead depth below requirements of 1.6mm (5.2     | 2.3 (e))                      |

| MOT #9   |   | 2022-10-17 09:46 |
|----------|---|------------------|
| MOT test | number  | 507793598966     |
| Result   |   | <b>✓</b> Passed  |
| Advice   | Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) |                  |
| Advice   | Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) |                  |

CarCheck.co.uk page 3/12



.

MOT #8 2022-10-17 09:46

**MOT test number** 275754183006

**Result** X Failed

**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Pass with rectification** Offside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #7 2021-08-23 09:09

**MOT test number** 565303982788

Result \( \sqrt{Passed} \)

MOT #6 2021-05-04 08:11

**MOT test number** 948635311325

**Result** 
✓ Passed

**Advice** Nearside Rear Tyre slightly damaged cracking (5.2.3 (d) (ii))

Advice Offside Rear Tyre slightly damaged cracking (5.2.3 (d) (ii))

**MOT #5** 2020-05-06 08:28

MOT test number 385833700810

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

CarCheck.co.uk page 4/12



MOT #4

MOT test number

204193751033

Result

Pass with rectification

Offside Front Position Jamp not working (4.2.1 (a) (ii))

Pass with rectification Offside Front Position lamp not working (4.2.1 (a) (ii))

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Pass with rectification Nearside Front Position lamp not working (4.2.1 (a) (ii))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #3 2019-04-16 09:11

**MOT test number** 725369235974

MOT #2 2018-04-18 09:58

**MOT test number** 395630913120

**Result** ✓ Passed

MOT #1 2018-04-18 09:15

**MOT test number** 533662014806

**Result** X Failed

Fail Nearside Front Headlamp not working on dipped beam (1.7.5a)

CarCheck.co.uk page 5/12



## Tax & MOT check



| Tax status       | Valid until 1 January |
|------------------|-----------------------|
| Days left        | 248                   |
| MOT expiry date  | 16 October 2024       |
| Full MOT history | See MOT history       |

## Tax calculation

| Vehicle class                           | 49             |
|---|----------------|
| Band                                    | A              |
| Single payment (12 months)              | £ 0,00,-       |
| Single six month payment                | Not applicable |
| Total payable by 12 monthly instalments | Not applicable |

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report <a href="https://example.com/here">here</a> for the results.

| Damage 1 |  |
|----------|--|
| Date     |  |
| Category |  |
| Туре     |  |
| Damage 2 |  |
| Date     |  |
| Category |  |
| Туре     |  |



#### Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

| *  |           |        |
|--|-----------|--------|
| For how long did the current and previous owner(s) have this CITROEN? How many owner have? Check it in the premium report and see all owner registrations. Download the full respectively. |           | OEN    |
| ***************************************  |           |        |
| ***************************************  |           |        |
| *************  |           |        |
|  |           |        |
|  |           |        |
|  |           |        |
|  |           |        |
|  | More info | >      |
| Plate changes  See in this check if this CITROEN had different number plates.  |           |        |
| Number of plates   |           | ,      |
| Current registration   | UK UK     |        |
| Plate since  |           | 0.00.0 |
| Current registration   | UK UK     |        |
| Plate since  |           | 0.00   |
|  | More info | >      |
|  |           |        |

CarCheck.co.uk page 9/12



#### Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

**Contact info** 

More info >

CarCheck.co.uk page 10/12



Mileage check

| Odometer                   | In miles   |
|----------------------------|------------|
| Mileage registrations      | 15         |
| First mileage registration | 2015-06-01 |
| Last registration          | 2023-10-12 |
| Complete history           | See info   |



| Registration #1  | 2015-06-01 | 10 mi     |
|------------------|------------|-----------|
| Registration #2  | 2018-04-18 | 40.723 mi |
| Registration #3  | 2018-04-18 | 40.723 mi |
| Registration #4  | 2019-04-16 | 48.362 mi |
| Registration #5  | 2020-05-06 | 55.571 mi |
| Registration #6  | 2020-05-06 | 55.571 mi |
| Registration #7  | 2021-05-04 | 60.946 mi |
| Registration #8  |            | 11.777 es |
| Registration #9  |            | 9.777 es  |
| Registration #10 |            | 11.777 es |
| Registration #11 |            | 9.777 es  |
| Registration #12 |            | 11.777 es |
| Registration #13 |            | 9.777 es  |
| Registration #14 |            | 11.777 es |
| Registration #15 |            | 11,117 es |

More info >

CarCheck.co.uk page 11/12



# Safety ratings

| NCAP rating    | ****            |
|----------------|-----------------|
| Adult          | 87%             |
| Children       | 71%             |
| Pedestrian     | 35%             |
| Safety systems | 83%             |
| Overall rating | 73%             |
| Video          | see crash video |



# Dimensions & weight

| Width               | 1728 mm |
|---------------------|---------|
| Height              | 1524 mm |
| Length              | 3941 mm |
| Wheel base          | 2464 mm |
| Kerb weight         | 1085 kg |
| Max. allowed weight | 1602 kg |

# Additional information

| Fuel tank capacity | 48 I             |
|--------------------|------------------|
| Fuel delivery      | Direct Injection |
| Number of doors    | 3                |
| Number of seats    | 5                |
| Number of axles    | 2                |
| Engine number      | JBFM0107961      |

CarCheck.co.uk page 12/12