





report date: 2024-03-29

General information

| Make | MINI |
|---------------------|--------------------|
| Model | MINI COOPER D ALL4 |
| Colour | Grey |
| Year of manufacture | 2012 |
| Top speed | 109 mph |
| 0 - 60 mph | 11.9 seconds |
| Gearbox | 6 speed automatic |

Engine & fuel consumption

| Power | 110 BHP |
|-------------------------|---------------------|
| Max. torque | 270 Nm at 1.750 rpm |
| Engine capacity | 1.995 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 37.2 mpg |
| Consumption extra urban | 56.5 mpg |
| Consumption combined | 47.1 mpg |
| CO2 emission | 158 g/km |
| CO2 label | G |



CarCheck.co.uk page 1/12



report date: 2024-03-29

Internet history

Entry 1

| Date | 2021-05-20 |
|---------------|-------------|
| Pictures | 1 |
| Listing price | View report |



source: autotrader.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-29

MOT history

Advice

| MOT expiry date | 2023-08-21 |
|--------------------|------------|
| MOT pass rate | 80 % |
| MOT passed | 8 |
| Failed MOT tests | 2 |
| Total advice items | 10 |
| Total items failed | 2 |

| MOT #10 | 2022-08-08 12:18 |
|------------------|------------------|
| MOT test number | 245791237455 |
| Result | ✓ Passed |
| Next expiry date | 2023-08-21 |

| MOT #9 | 2021-07-22 15:02 |
|-----------------|------------------|
| MOT test number | 414514486656 |
| Result | ✓ Passed |

| MOT #8 | 2020-08-20 10:56 |
|--|--|
| MOT test number | 179502297145 |
| Result | ✓ Passed |
| Minor Offside Registration plate lamp inoperative in the case of multi | iple lamps or light sources (4.7.1 (b) |

| MOT #7 | 2020-08-19 12:5 | 9 |
|--------|-----------------|---|

Offside Rear Child Seat fitted not allowing full inspection of adult belt

| MOT test | t number 342779173850 |
|------------|---|
| Result | ▼ Failed |
| | Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords cuts (5.2.3 (d) (i)) |
| Advice | Offside Rear Child Seat fitted not allowing full inspection of adult belt |
| Minor (i)) | Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) |

CarCheck.co.uk page 3/12



report date: 2024-03-29

MOT #6

MOT test number

420357516830

Result

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #5

MOT test number

Result

Advice Offside Rear Road wheel slightly distorted (5.2.2 (c) (i))

MOT test number

830370663622

Result

Advice Offside Front Wheel bearing slightly noisy (5.1.3 (b) (i))

Advice Offside Rear Road wheel slightly distorted (5.2.2 (c) (i))

Fail Offside Front Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (i))

MOT test number

Result

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

 MOT #2
 2016-09-08 10:54

 MOT test number
 248252443976

 Result
 ✓ Passed

CarCheck.co.uk page 4/12



report date: 2024-03-29

MOT #1 2015-09-23 09:01

MOT test number 425833709591

CarCheck.co.uk page 5/12



report date: 2024-03-29

Tax & MOT check

Tax expired: 10 August 2023



X MOT

Expired: 21 August 2023

Tax status Expired at 10 August 2023

Days left 263 days too late

MOT expiry date 21 August 2023

Full MOT history See MOT history

Tax calculation

| Vehicle class | 49 |
|---|------------|
| Band | G |
| Single payment (12 months) | £ 240,00,- |
| Single six month payment | £ 132,00,- |
| Total payable by 12 monthly instalments | £ 252,00,- |

CarCheck.co.uk page 6/12



report date: 2024-03-29

Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



faste since

LC620EO

report date: 2024-03-29

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report here. More info > Plate changes See in this check if this MINI had different number plates.

More info >

CarCheck.co.uk page 9/12



LC620E0 report date: 2024-03-29

Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MINI is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |

Contact info

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-29

Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 12 |
| First mileage registration | 2012-11-09 |
| Last registration | 2022-08-08 |
| Complete history | See info |



| Registration #1 | 2012-11-09 | 27 mi |
|------------------|------------|-----------|
| Registration #2 | 2015-09-23 | 29.242 mi |
| Registration #3 | 2016-09-08 | 36.222 mi |
| Registration #4 | 2017-08-15 | 42.305 mi |
| Registration #5 | 2018-08-14 | 49.319 mi |
| Registration #6 | 2018-08-15 | 49.316 mi |
| Registration #7 | | 11.777 es |
| Registration #8 | | 11.777 es |
| Registration #9 | | 11.777 es |
| Registration #10 | | 11.777 es |
| Registration #11 | | 11.777 es |
| Registration #12 | | |

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-29

Car features

| 50225 | Air conditioning |
|-------|------------------|
| 50295 | |
| 50482 | |
| 60501 | |
| 60566 | |
| 60567 | |
| 50569 | |

Safety ratings

| NCAP rating | **** |
|-------------|-----------------|
| Video | see crash video |



Dimensions & weight

| Width | 1789 mm |
|---------------------|---------|
| Height | 1561 mm |
| Length | 4097 mm |
| Wheel base | 2595 mm |
| Kerb weight | 1405 kg |
| Max. allowed weight | 1915 kg |

Additional information

| Fuel tank capacity | 47 | |
|-----------------------------------|------------------|------------|
| Fuel delivery | Direct Injection | |
| Number of doors | 5 | |
| Number of seats CarCheck.co.uk | 5 | page 12/12 |

Number of axles 2
Engine number 72318136