



report date: 2024-03-28

General information

| | |
|---------------------|------------------------|
| Make | VOLVO |
| Model | S40 D S |
| Colour | Blue |
| Year of manufacture | 2010 |
| Top speed | 127 mph |
| 0 - 60 mph | 9.1 seconds |
| Gearbox | 6 speed Semi-Automatic |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 136 BHP |
| Max. torque | 320 Nm at 2.000 rpm |
| Engine capacity | 1.997 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 36.2 mpg |
| Consumption extra urban | 56.5 mpg |
| Consumption combined | 47.1 mpg |
| CO2 emission | 153 g/km |
| CO2 label | G |





Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-11-06 |
| Pictures | 0 |
| Listing price | View report |

source: [autotrader.co.uk](#)



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2023-11-28 |
| MOT pass rate | 69 % |
| MOT passed | 11 |
| Failed MOT tests | 5 |
| Total advice items | 32 |
| Total items failed | 4 |

| | |
|------------------|--|
| MOT #16 | 2022-11-29 08:55 |
| MOT test number | 604836762903 |
| Result | ✓ Passed |
| Next expiry date | 2023-11-28 |
| Advice | Rear Exhaust has a minor leak of exhaust gases silencer (6.1.2 (a)) |
| Advice | Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e)) |

| | |
|-----------------|------------------|
| MOT #15 | 2021-11-29 15:01 |
| MOT test number | 864844566210 |
| Result | ✓ Passed |

| | |
|-----------------|--|
| MOT #14 | 2021-11-25 15:59 |
| MOT test number | 504848230727 |
| Result | ✗ Failed |
| MAJOR | Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i)) |
| MAJOR | Nearside Front Position lamp not working (4.2.1 (a) (ii)) |
| DANGEROUS | Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e)) |
| MAJOR | Offside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i)) |
| DANGEROUS | Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e)) |



MOT #13 2020-07-02 16:34

MOT test number 101311825376

Result ✓ Passed

- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge Worn on inside edge (5.2.3 (e))
- Advice** Central Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge Worn on inside edge (5.2.3 (e))

MOT #12 2020-07-02 09:27

MOT test number 272905381432

Result ✗ Failed

- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge Worn on inside edge (5.2.3 (e))
- MAJOR** Nearside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge Worn on inside edge (5.2.3 (e))
- MAJOR** Offside Front Headlamp aim too high (4.1.2 (a))
- Advice** Central Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))

**MOT #11** 2019-07-02 08:54**MOT test number** 294730147809**Result** ✓ Passed

- Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))
- Advice** Offside Rear Inner Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Minor** Nearside Rear Brake hose slightly damaged (1.1.12 (b) (i))
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Service brake requirements only just met. It would appear that the braking system requires adjustment or repair (1.2.1 (c))
- Advice** Nearside Rear Inner Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Minor** Offside Front Headlamp cleaning device inoperative (4.1.6 (a) (i))
- Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Minor** Offside Rear Brake hose slightly damaged (1.1.12 (b) (i))

MOT #10 2018-05-21 15:16**MOT test number** 676535962791**Result** ✓ Passed

- Minor** Offside Front Headlamp cleaning device inoperative Damaged (4.1.6 (a) (i))

MOT #9 2017-05-08 13:01**MOT test number** 541205338287**Result** ✓ Passed

**MOT #8** 2017-05-08 11:37**MOT test number** 410478089209**Result** ✗ Failed**Fail** Offside Rear Anti-roll bar linkage worn and seriously weakened (2.4.G.1)**MOT #7** 2017-01-19 08:24**MOT test number** 218631808814**Result** ✓ Passed**Advice** Rear Anti-roll bar linkage has slight play in a ball joint N/S AND O/S (2.4.G.2)**MOT #6** 2017-01-14 08:35**MOT test number** 197096668433**Result** ✗ Failed**Fail** Offside Front coil spring broken (2.4.C.1a)**Advice** Rear Anti-roll bar linkage has slight play in a ball joint N/S AND O/S (2.4.G.2)**MOT #5** 2016-01-15 12:24**MOT test number** 589007554498**Result** ✓ Passed**MOT #4** 2016-01-15 11:31**MOT test number** 322491067952**Result** ✗ Failed**Fail** Centre Rear registration plate character(s) laid out in an incorrect format (6.3.4f)**Advice** Nearside Front side marker light inop.**Fail** Centre Front registration plate character(s) laid out in an incorrect format (6.3.4f)



| | |
|-----------------|------------------|
| MOT #3 | 2015-01-19 12:57 |
| MOT test number | 188469515405 |
| Result | ✓ Passed |

| | |
|--|------------------|
| MOT #2 | 2014-01-22 09:29 |
| MOT test number | 985342124091 |
| Result | ✓ Passed |
| <div><div>Advice</div>Rear Brake pad(s) wearing thin (3.5.1g)</div> <div><div>Advice</div>Front Brake pad(s) wearing thin (3.5.1g)</div> | |

| | |
|-----------------|------------------|
| MOT #1 | 2013-01-17 09:13 |
| MOT test number | 187327613026 |
| Result | ✓ Passed |



Tax & MOT check

X

Untaxed

Tax expired:
12 July 2023

X

MOT

Expired:
28 November 2023

| | |
|------------------|---------------------------------|
| Tax status | Expired at 12 July 2023 |
| Days left | 291 days too late |
| MOT expiry date | 28 November 2023 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|---|------------|
| Vehicle class | 49 |
| Band | G |
| Single payment (12 months) | £ 240,00,- |
| Single six month payment | £ 132,00,- |
| Total payable by 12 monthly instalments | £ 252,00,- |




Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,299 |
| Auction value | £ 19,299 |
| Average private trade value | £ 19,299 |

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|-------|
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |

More info >

Plate changes

See in this check if this VOLVO had different number plates.

| | |
|----------------------|------------|
| Number of plates | 1 |
| Current registration | |
| Plate since | 2019-09-29 |
| Current registration | |
| Plate since | 2019-09-29 |

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.


| | | |
|-------------------|------------|------|
| Finance company | XXXXXXXXXX | XXXX |
| Date of agreement | XXXXXXXXXX | XXXX |
| Agreement type | XXXXXXXXXX | XXXX |
| Agreement term | XXXXXXXXXX | XXXX |
| Agreement number | XXXXXXXXXX | XXXX |
| Contact info | XXXXXXXXXX | XXXX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 18 |
| First mileage registration | 2010-03-25 |
| Last registration | 2022-11-29 |
| Complete history | See info |



| | | |
|------------------|------------|-----------|
| Registration #1 | 2010-03-25 | 14 mi |
| Registration #2 | 2013-01-17 | 38.864 mi |
| Registration #3 | 2014-01-22 | 53.644 mi |
| Registration #4 | 2015-01-19 | 67.509 mi |
| Registration #5 | 2016-01-15 | 79.623 mi |
| Registration #6 | 2016-01-15 | 79.623 mi |
| Registration #7 | 2017-01-14 | 88.958 mi |
| Registration #8 | 2017-01-19 | 89.046 mi |
| Registration #9 | 2017-05-08 | 89.766 mi |
| Registration #10 | 2018-05-29 | 95.377 mi |
| Registration #11 | 2019-05-29 | 95.377 mi |
| Registration #12 | 2020-05-29 | 95.377 mi |
| Registration #13 | 2021-05-29 | 95.377 mi |
| Registration #14 | 2022-05-29 | 95.377 mi |
| Registration #15 | 2023-05-29 | 95.377 mi |
| Registration #16 | 2024-05-29 | 95.377 mi |
| Registration #17 | 2025-05-29 | 95.377 mi |
| Registration #18 | 2026-05-29 | 95.377 mi |

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

| | |
|---------------------|---------|
| Width | 1770 mm |
| Height | 1454 mm |
| Length | 4476 mm |
| Wheel base | 2640 mm |
| Kerb weight | 1446 kg |
| Max. allowed weight | 1940 kg |

Additional information

| | |
|--------------------|------------------|
| Fuel tank capacity | 52 l |
| Fuel delivery | Direct Injection |
| Number of doors | 4 |
| Number of seats | 5 |

Engine number

727050