





report date: 2024-03-28

General information

Make	RENAULT
Model	SCENIC DYNAMIQUE TOMTOM ENERGY DCI S/S
Colour	Black
Year of manufacture	2014
Top speed	112 mph
0 - 60 mph	12.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	110 BHP
Max. torque	260 Nm at 1.750 rpm
Engine capacity	1.461 cc
Cylinders	4
Fuel type	Diesel
Consumption city	62.8 mpg
Consumption extra urban	72.4 mpg
Consumption combined	68.9 mpg
CO2 emission	105 g/km
CO2 label	В



CarCheck.co.uk page 1/11



Internet history


Entry 3

Date 2021-11-17

Pictures 4

Listing price View report









source: cargurus.co.uk


Entry 2

Date 2021-06-23

Pictures 4

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 1

Date 2021-06-22

Pictures

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/11



MOT history

MOT expiry date	2024-12-01
MOT pass rate	78 %
MOT passed	7
Failed MOT tests	2
Total advice items	5
Total items failed	4

MOT #9	2023-11-20 09:40
MOT test number	119261382223
Result	✓ Passed
Next expiry date	2024-12-01

MOT #8	2023-11-20 09:40
MOT test number	683382833590
Result	▼ Failed
Pass with rectification lamps (4.7.1 (b) (ii))	Offside Registration plate lamp inoperative in the case of a single lamp or all
Pass with rectification	Offside Rear Position lamp not working (4.2.1 (a) (ii))

MOT #7		2022-11-16 11:04
MOT test	number	197841261722
Result		✓ Passed
Minor	Registration plate lamp inoperative in the case of multiple lamps or ligh	t sources (4.7.1 (b) (i))

MOT #6	2021-12-02 11:29
MOT test number	208575788697
Result	✓ Passed

CarCheck.co.uk page 3/11



MOT #5 2020-11-19 10:06

MOT test number 448677320782

Result ✓ Passed

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #4 2020-11-18 15:01

MOT test number 329468239941

Result X Failed

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail Nearside Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

Fail Nearside Front Tyre has a lump, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

MOT #3 2019-05-08 12:40

MOT test number 664219916019

Result
✓ Passed

Advice Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Offside Rear Nail in tyre

MOT #2 2018-05-10 11:56

MOT test number 365109042532

Result ✓ Passed

MOT #1 2017-05-10 15:20

MOT test number 194216782013

Result
✓ Passed

CarCheck.co.uk page 4/11





Tax & MOT check



Tax status	Valid until 1 December
Days left	217
MOT expiry date	1 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	В
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-

CarCheck.co.uk page 5/11



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report here for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owner have? Check it in the premium report and see all owner registrations. Download the full report and see all owner registrations.	

	More info >
Plate changes	
See in this check if this RENAULT had different number plates.	
Number of plates	
Current registration	OK SIE
Plate since	
Current registration	NK SIE
Plate since	
	More info >

CarCheck.co.uk page 8/11



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this RENAULT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
0.1.116	

Contact info

More info >

CarCheck.co.uk page 9/11



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2014-05-29
Last registration	2023-11-20
Complete history	See info



Registration #1	2014-05-29	25 mi
Registration #2	2017-05-10	19.396 mi
Registration #3	2018-05-10	26.818 mi
Registration #4	2019-05-08	34.547 mi
Registration #5	2020-11-18	45.299 mi
Registration #6	2020-11-19	45.299 mi
Registration #7		11.777 ms
Registration #8		11.777 es
Registration #9		11.777 ms
Registration #10		11.777 es
Registration #11		11.777 mi
Registration #12		11.777 es
Registration #13		0.77 66

More info >

CarCheck.co.uk page 10/11



Car features

S0225	Air conditioning
S0295	
S0482	
50501	
50566	
S0567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1845 mm
Height	1640 mm
Length	4366 mm
Wheel base	2702 mm
Kerb weight	1434 kg
Max. allowed weight	1967 kg

Additional information

Fuel tank capacity	60 I	
Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5	page 11/11

Number of axles 2

Engine number D467345