





report date: 2024-03-29

General information

Make	BMW
Model	120 120D M SPORT
Colour	Black
Year of manufacture	-
Top speed	137 mph
0 - 60 mph	7.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	161 BHP
Max. torque	340 Nm at 2.000 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	36.7 mpg
Consumption extra urban	61.4 mpg
Consumption combined	49.6 mpg



CarCheck.co.uk page 1/13



Internet history

Entry 1

Date 2021-05-23

Pictures 10

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/13



MOT history

MOT #17	2021-01-30 13:20
MOT test number	205631280964
Result	✓ Passed
Next expiry date	2022-02-17

Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i)	417978488839 ✓ Passed
	·
)
Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Nearside Front Brake hose slightly deteriorated perished (1.1.12 (b) (ii))	
Parking brake efficiency only just met. It would appear that the braking system at or repair. efficiency at 20% (1.4.2 (a) (i))	n requires
Front Registration plate deteriorated but not likely to be misread (0.1 (b))	
Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.	1.14 (a) (ii))
Rear Child Seat fitted not allowing full inspection of adult belt	
Offside Front Brake hose slightly deteriorated perished (1.1.12 (b) (ii))	
ıt	for repair. efficiency at 20% (1.4.2 (a) (i)) Front Registration plate deteriorated but not likely to be misread (0.1 (b)) Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.) Rear Child Seat fitted not allowing full inspection of adult belt

CarCheck.co.uk page 3/13



MOT #15

Advice

Advice

Advice

KC56ZTU

report date: 2024-03-29

2019-02-18 18:41

MOT test number

Result

✓ Passed

Advice (0.1 (b))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt

Minor Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

Both sides front & both sides rear flexible brake hoses are perished

Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #14 2019-02-18 18:41 **MOT** test number 393852966966 Result Failed **Advice** Front Registration plate deteriorated but not likely to be misread number plate is delaminated (0.1(b))Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) **Advice** Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b)) Pass with rectification Bonnet seriously at risk of opening inadvertently (3.1 (b) (ii)) Nearside Rear Child Seat fitted not allowing full inspection of adult belt Advice **Advice** Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b)) **Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Minor Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i)) **Advice** Both sides front & both sides rear flexible brake hoses are perished

CarCheck.co.uk page 4/13



KC56ZTU

report date: 2024-03-29

MOT #13

MOT test number

123671139368

Result

Advice Front windscreen is damaged covers impede parts of the inspection

MOT #12

MOT test number

564851873090

Result

Advice Front windscreen is damaged

Advice Covers impede parts of the inspection

MOT test number

Result

Advice Nearside Front Shock absorber has a light misting of oil (2.7.3)

Advice Parking brake performance just meets the pass standard

Advice Front windscreen is damaged

MOT #10

MOT test number

897288808800

Result

Advice Nearside Front Shock absorber has a light misting of oil (2.7.3)

Advice Parking brake performance just meets the pass standard

Pass with rectification Offside Rear Registration plate lamp not working (1.1.C.1d)

Advice Front windscreen is damaged

CarCheck.co.uk page 5/13



KC56ZTU

report date: 2024-03-29

MOT test number

Result

Advice

Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Advice

Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice

Offside Front Tyre worn close to the legal limit (4.1.E.1)

Advice

Offside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #8

MOT test number

676558244023

Result

Advice

Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

 MOT #7
 2013-02-12 09:27

 MOT test number
 617393743010

 Result
 ✓ Passed

 MOT #6
 2013-02-12 09:27

 MOT test number
 988533843090

 Result
 X Failed

 Pass with rectification
 Exhaust system not adequately supported (7.1.1)

MOT #5

MOT test number

Result

Notice Child seat fitted not allowing full inspection of adult belt

2012-12-07 10:31

835582242300

✓ Passed

CarCheck.co.uk page 6/13



MOT #4 2012-12-07 10:31

MOT test number 325792142344

Result X Failed

Pass with rectification Nearside Headlamp aim beam image obviously incorrect (1.8.A.1b)

Notice Child seat fitted not allowing full inspection of adult belt

MOT #3 2011-09-07 12:56

MOT test number 805730951244

Result ✓ Passed

MOT #2 2010-11-30 13:17

MOT test number 373724930378

Result
✓ Passed

MOT #1 2010-01-11 16:04

MOT test number 221781410006

Result ✓ Passed

CarCheck.co.uk page 7/13



Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	



Extra BMW salvage check



Type

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



Owner history

e mier metery	
For how long did the current and previous owner(s) have this BMW? How many owners defect it in the premium report and see all owner registrations. Download the full report	
manage of the same	

	More info >
Plate changes	
See in this check if this BMW had different number plates.	
Number of plates	,
Current registration	NK NK
Plate since	
Current registration	UK NE
Plate since	
	More info >

CarCheck.co.uk page 10/13



Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this BMW is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info >

CarCheck.co.uk page 11/13



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2007-01-26
Last registration	2021-01-30
Complete history	See info



Registration #1	2007-01-26	21 mi
Registration #2	2010-01-11	43.912 mi
Registration #3	2010-11-30	59.301 mi
Registration #4	2011-09-07	69.612 mi
Registration #5	2012-12-07	79.327 mi
Registration #6	2013-02-12	80.486 mi
Registration #7	2014-02-17	91.431 mi
Registration #8	2015-02-14	101.618 mi
Registration #9	2016-02-17	111.608 mi
Registration #10		71.777 es
Registration #11		11.177 es
Registration #12		
		11.777 46
Registration #13		11.77 es
Registration #13 Registration #14		11.777 es
		11.777 es 11.777 es 11.777 es
Registration #14		11.777 es 11.777 es 11.777 es

More info >

CarCheck.co.uk page 12/13



Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1751 mm
Height	1430 mm
Length	4227 mm
Wheel base	2660 mm
Kerb weight	1340 kg
Max. allowed weight	1840 kg

Additional information

Fuel tank capacity	50 I	
Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5	page 13/13

Number of axles 2

Engine number 84886445