





report date: 2024-03-28

General information

Make	PEUGEOT
Model	107 ACTIVE
Colour	Grey
Year of manufacture	2013
Top speed	100 mph
0 - 60 mph	14.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	68 BHP
Max. torque	93 Nm at 3.600 rpm
Engine capacity	998 cc
Cylinders	3
Fuel type	Petrol
Consumption city	55.4 mpg
Consumption extra urban	74.3 mpg
Consumption combined	65.7 mpg
CO2 emission	99 g/km
CO2 label	A



CarCheck.co.uk page 1/12



report date: 2024-03-28

Internet history

Ent	- 100	1
EIII	. I V	-

Lifety 1	
Date	2021-12-19
Pictures	0
Listing price	View report

source: autotrader.co.uk

CarCheck.co.uk page 2/12



SH63MKF report date: 2024-03-28

MOT history

MOT expiry date	2024-10-03
MOT pass rate	80 %
MOT passed	8
Failed MOT tests	2
Total advice items	19
Total items failed	1

MOT #10	2023-10-01 08:50
MOT test number	822339348244
Result	✓ Passed
Next expiry date	2024-10-03

MOT #9	2022-10-04 08:44
MOT test number	973248073465
Result	✓ Passed
Minor Offside Rear Registration plate lamp inoperative in the case of multiple (4.7.1 (b) (i))	e lamps or light sources

MOT #8		2021-11-02 10:07
MOT test	number	670675988589
Result		✓ Passed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Rear Brake pipe corroded, covered in grease or other material to	flexi (1.1.11 (c))
Minor Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))		
Advice	Offside Front Macpherson strut corroded but not seriously weakened spri	ng seat (5.3.3 (b) (i))
Advice	Front Oil leak, but not excessive sump corroded (8.4.1 (a) (i))	

CarCheck.co.uk page 3/12



report date: 2024-03-28

MOT #7 2020-11-05 16:02

MOT test number 479324411238

Result
✓ Passed

Advice Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Advice Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #6 2019-11-05 16:12

MOT test number 172291027915

Result ✓ Passed

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #5 2019-11-04 12:47

MOT test number 379629704319

Result X Failed

MAJOR Offside Rear Position lamp not working (4.2.1 (a) (ii))

MAJOR Nearside Front Service brake excessively binding (1.2.1 (f))

DANGEROUS Nearside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

MAJOR Nearside Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1

(b) (ii))

MAJOR Front Exhaust has a major leak of exhaust gases (6.1.2 (a))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #4 2018-11-05 14:37

MOT test number 190339590889

Result \(\sqrt{Passed} \)

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

CarCheck.co.uk page 4/12



report date: 2024-03-28

MOT test number
946389246373

Result

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Pass with rectification | Nearside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

MOT #2

MOT test number

S82276683979

Result

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

 MOT #1
 2016-10-28 11:54

 MOT test number
 993198596188

 Result
 ✓ Passed

CarCheck.co.uk page 5/12



report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 October
Days left	156
MOT expiry date	3 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable

CarCheck.co.uk page 6/12



report date: 2024-03-28

Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report here for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-28

Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owner have? Check it in the premium report and see all owner registrations. Download the full report and see all owner registrations.	
THE STATE OF THE S	

	More info >
Plate changes	
See in this check if this PEUGEOT had different number plates.	
Number of plates	,
Current registration	EK UK
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 9/12



report date: 2024-03-28

Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

Contact info

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2013-10-31
Last registration	2023-10-01
Complete history	See info



Registration #1	2013-10-31	14 mi
Registration #2	2016-10-28	61.776 mi
Registration #3	2017-10-27	81.384 mi
Registration #4	2018-11-05	102.115 mi
Registration #5	2018-11-05	102.115 mi
Registration #6	2019-11-04	125.350 mi
Registration #7		9.70 es
Registration #8		11.777 es
Registration #9		9.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		D.777-es

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-28

Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
50569	

Safety ratings

NCAP rating	***
Adult	68%
Children	73%
Pedestrian	53%
Safety systems	71%
Overall rating	66%
Video	see crash video



Dimensions & weight

Width	1855 mm
Height	1470 mm
Length	3430 mm
Wheel base	2340 mm
Kerb weight	900 kg
Max. allowed weight	1180 kg

Additional information

Fuel tank capacity	35 I
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats CarCheck.co.uk	4 page 12/12