



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	FOX URBAN FOX
Colour	Blue
Year of manufacture	2009
Top speed	92 mph
0 - 60 mph	17.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	55 BHP
Max. torque	108 Nm at 3.000 rpm
Engine capacity	1.198 cc
Cylinders	3
Fuel type	Petrol
Consumption city	36.2 mpg
Consumption extra urban	55.4 mpg
Consumption combined	46.3 mpg
CO2 emission	139 g/km
CO2 label	E





Internet history

Entry 1

Date	2021-10-27
Pictures	11
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-08-17
MOT pass rate	75 %
MOT passed	12
Failed MOT tests	4
Total advice items	32
Total items failed	4

MOT #16	2023-08-18 15:26
MOT test number	164191905129
Result	✓ Passed
Next expiry date	2024-08-17
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #15	2023-08-18 11:06
MOT test number	174138793326
Result	✗ Failed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Fail	Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Minor	Nearside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

**MOT #14** 2022-07-20 09:20**MOT test number** 118884546449**Result** ✓ Passed

Minor Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice Rear exhaust corroded

Minor Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

MOT #13 2021-10-23 10:26**MOT test number** 472530293760**Result** ✓ Passed

Advice Rear axle coated in underseal

Advice Both front lower suspension arms coated in underseal

MOT #12 2021-10-22 11:19**MOT test number** 248806427140**Result** ✗ Failed

Advice Rear axle coated in underseal

Fail Nearside Front Shock absorbers has a serious fluid leak (5.3.2 (b))

Advice Both front lower suspension arms coated in underseal

MOT #11 2021-01-27 15:34**MOT test number** 597834267292**Result** ✓ Passed

**MOT #10**

2019-07-27 10:27

MOT test number

660582293261

Result

✓ Passed

Minor Front Anti-roll bar ball joint dust cover severely deteriorated both (5.3.4 (b) (i))**Advice** Offside Front Service brake binding but not excessively (1.2.1 (f))**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Front Service brake fluctuating, but not excessively (1.2.1 (e))**MOT #9**

2019-07-24 10:57

MOT test number

636970185331

Result

✗ Failed

Fail Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Front Service brake binding but not excessively (1.2.1 (f))**Minor** Front Anti-roll bar ball joint dust cover severely deteriorated both (5.3.4 (b) (i))**Advice** Offside Front Service brake fluctuating, but not excessively (1.2.1 (e))**MOT #8**

2018-07-21 13:32

MOT test number

139308647782

Result

✓ Passed

Advice Offside Rear tyre perished and cracked**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #7** 2018-07-21 12:01**MOT test number** 861087418753**Result** ✗ Failed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Nearside Headlamp aim too low (4.1.2 (a))**Advice** Offside Rear tyre perished and cracked**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**MOT #6** 2017-07-21 13:18**MOT test number** 583474182028**Result** ✓ Passed**Advice** Exhaust has a minor leak of exhaust gases flexi (7.1.2)**MOT #5** 2016-07-23 07:58**MOT test number** 883774647604**Result** ✓ Passed**MOT #4** 2015-07-11 11:36**MOT test number** 497772295152**Result** ✓ Passed**MOT #3** 2014-07-16 13:26**MOT test number** 298677994142**Result** ✓ Passed**Notice** Nail in nearside rear tyre



MOT #2	2013-07-17 11:16
MOT test number	738128993136
Result	✓ Passed
<div><div>Advice</div>Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)</div>	

MOT #1	2012-07-26 14:09
MOT test number	829248202263
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
17 August 2024

Tax status	Valid until 1 October
Days left	155
MOT expiry date	17 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history


Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	7
Current registration	 *****
Plate since	2023-03-29
Current registration	 *****
Plate since	2023-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.


Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2009-07-31
Last registration	2023-08-18
Complete history	See info



Registration #1	2009-07-31	17 mi
Registration #2	2012-07-26	24.362 mi
Registration #3	2013-07-17	34.062 mi
Registration #4	2014-07-16	39.607 mi
Registration #5	2015-07-11	44.117 mi
Registration #6	2016-07-23	49.288 mi
Registration #7	2017-07-21	54.010 mi
Registration #8	2018-07-21	61.184 mi
Registration #9	2018-07-21	61.184 mi
Registration #10	2019-07-21	61.184 mi
Registration #11	2019-07-21	61.184 mi
Registration #12	2019-07-21	61.184 mi
Registration #13	2019-07-21	61.184 mi
Registration #14	2019-07-21	61.184 mi
Registration #15	2019-07-21	61.184 mi
Registration #16	2019-07-21	61.184 mi
Registration #17	2019-07-21	61.184 mi
Registration #18	2019-07-21	61.184 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1660 mm
Height	1544 mm
Length	3828 mm
Wheel base	2465 mm
Kerb weight	1069 kg
Max. allowed weight	1480 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	3

Number of seats	4
Number of axles	2
Engine number	CHF 004629