



Mercedes-Benz



report date: 2024-03-28

General information

Make	MERCEDES-BENZ
Model	ML ML250 BLUETEC AMG SPORT
Colour	Silver
Year of manufacture	2014
Top speed	130 mph
0 - 100 km/h	9.0 seconds
0 - 60 mph	9.0 seconds
Gearbox	7 speed automatic

Engine & fuel consumption

Power	150 kW / 204 HP / 204 BHP
Max. torque	500 Nm at 1.800 rpm
Engine capacity	2.143 cc
Cylinders	4
Fuel type	Diesel
Consumption city	38.7 mpg
Consumption extra urban	50.4 mpg
Consumption combined	44.8 mpg
CO2 emission	163 g/km
CO2 label	G






Internet history

Entry 1

Date	2021-10-30
Pictures	12
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2025-01-22
MOT pass rate	67 %
MOT passed	8
Failed MOT tests	4
Total advice items	38
Total items failed	4

MOT #122024-01-23 10:12

MOT test number326187320345

Result✓ Passed

Next expiry date2025-01-22

- MinorOffside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- AdviceOffside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- AdviceOFFSIDE DIP BEAM OUTPUT REDUCED...
- AdviceBrake pedal wearing smooth PEDAL RUBBER WORN TO METAL.. (1.1.2 (c))
- MinorWindscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- MinorNearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- AdviceNearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- AdviceOil leak, but not excessive (8.4.1 (a) (i))

**MOT #11**

2024-01-17 16:10

MOT test number

247218786373

Result**✗ Failed**

- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Brake pedal wearing smooth PEDAL RUBBER WORN TO METAL.. (1.1.2 (c))
- Minor** Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- MAJOR** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** OFFSIDE DIP BEAM OUTPUT REDUCED...
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Minor** Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

MOT #10

2023-01-05 11:45

MOT test number

746906983615

Result**✓ Passed**

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge 265 45r20 (5.2.3 (e))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** Undertrays and engine covers fitted
- Minor** Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Minor** Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

**MOT #9** 2023-01-03 17:36**MOT test number** 767390676092**Result** ✗ Failed**Minor** Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**DANGEROUS** Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge 265 45r20 (5.2.3 (e))**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Minor** Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**Advice** Undertrays and engine covers fitted**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**MOT #8** 2021-12-31 10:17**MOT test number** 914532237822**Result** ✓ Passed**MOT #7** 2021-01-15 09:32**MOT test number** 938504523874**Result** ✓ Passed**MOT #6** 2020-03-05 08:12**MOT test number** 800863748462**Result** ✓ Passed

**MOT #5** 2020-03-04 16:29**MOT test number** 678661255929**Result** ✗ Failed

DANGEROUS Nearside Rear Outer Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

Pass with rectification Nearside Front Headlamp aim too high (4.1.2 (a))

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Pass with rectification Offside Front Headlamp aim too high (4.1.2 (a))

MOT #4 2019-03-18 12:25**MOT test number** 367910626712**Result** ✓ Passed**MOT #3** 2018-03-22 12:59**MOT test number** 457495319162**Result** ✓ Passed**MOT #2** 2018-03-21 14:40**MOT test number** 964055335499**Result** ✗ Failed

Fail Nearside Front Tyre has a bulge, caused by separation or partial failure of its structure inner sidewall (4.1.D.1b)

Fail Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)

MOT #1 2017-03-07 09:08**MOT test number** 449318192425**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 January 2025

✓
MOT
Expires:
22 January 2025

Tax status	Valid until 1 January
Days left	246
MOT expiry date	22 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this MERCEDES-BENZ. See if, where and when this MERCEDES-BENZ had damage and the car repair costs. We also check if this MERCEDES-BENZ was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MERCEDES-BENZ salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES-BENZ in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES-BENZ? How many owners did this MERCEDES-BENZ have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MERCEDES-BENZ had different number plates.

Number of plates	1
Current registration	 KN14ZVW
Plate since	2019-06-29
Current registration	 KN14ZVW
Plate since	2019-06-29

More info >



Finance check

Check if this MERCEDES-BENZ is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES-BENZ has been settled.

If not, and you buy this MERCEDES-BENZ then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES-BENZ is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2014-04-01
Last registration	2024-01-23
Complete history	See info



Registration #1	2014-04-01	12 mi
Registration #2	2017-03-07	38.595 mi
Registration #3	2018-03-21	41.901 mi
Registration #4	2018-03-22	41.966 mi
Registration #5	2019-03-18	49.170 mi
Registration #6	2020-03-04	54.187 mi
Registration #7	2020-03-05	54.187 mi
Registration #8	2020-03-05	54.187 mi
Registration #9	2020-03-05	54.187 mi
Registration #10	2020-03-05	54.187 mi
Registration #11	2020-03-05	54.187 mi
Registration #12	2020-03-05	54.187 mi
Registration #13	2020-03-05	54.187 mi
Registration #14	2020-03-05	54.187 mi

More info >



Car features

The MERCEDES-BENZ factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MERCEDES-BENZ factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1998 mm
Height	1796 mm
Length	4804 mm
Wheel base	2915 mm
Kerb weight	2150 kg
Max. allowed weight	2950 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	65196032261542