



report date: 2024-03-28

General information

Make	CITROEN
Model	DISPATCH 1200 L2H1 ENTERPRISE HDI
Colour	White
Year of manufacture	2015
Top speed	106 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	126 BHP
Max. torque	320 Nm at 2.000 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	37.2 mpg
Consumption extra urban	48.7 mpg
Consumption combined	44.1 mpg
CO2 emission	168 g/km
CO2 label	H





Internet history

Entry 1

Date	2021-10-14
Pictures	0
Listing price	View report

source: cargurus.co.uk



MOT history

MOT expiry date	2024-12-12
MOT pass rate	86 %
MOT passed	6
Failed MOT tests	1
Total advice items	11
Total items failed	3

MOT #7 2023-12-11 14:31

MOT test number 212539994013

Result ✓ Passed

Next expiry date 2024-12-12

- Minor** Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** Nearside Front Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Minor** Offside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Minor** Offside Obligatory mirror slightly damaged (3.3 (b) (i))

MOT #6 2022-12-08 12:29

MOT test number 126564653369

Result ✓ Passed

- Minor** Offside Obligatory mirror slightly damaged (3.3 (b) (i))
- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** Offside Rear ABS sensor bracket bent stressing sensor cable

MOT #5 2021-12-13 13:25

MOT test number 714731348136

Result ✓ Passed

**MOT #4** 2021-12-11 15:52**MOT test number** 947121456601**Result** ✗ Failed**Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))**Fail** Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))**Minor** Offside Obligatory mirror slightly damaged (3.3 (b) (i))**Advice** Rear Brake pad(s) wearing thin both side (1.1.13 (a) (ii))**Fail** Offside Stop lamp(s) not working (4.3.1 (a) (ii))**Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**MOT #3** 2020-10-02 08:34**MOT test number** 986092545972**Result** ✓ Passed**MOT #2** 2019-10-25 09:30**MOT test number** 715193025229**Result** ✓ Passed**MOT #1** 2018-11-05 10:13**MOT test number** 587733198621**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 December 2024

✓
MOT
Expires:
12 December 2024

Tax status	Valid until 1 December
Days left	217
MOT expiry date	12 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	LD65VUW
Plate since	2019-09-29
Current registration	LD65VUW
Plate since	2019-09-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2015-12-10
Last registration	2023-12-11
Complete history	See info



Registration #1	2015-12-10	21 mi
Registration #2	2018-11-05	40.535 mi
Registration #3	2019-10-25	47.759 mi
Registration #4	2020-10-02	54.512 mi
Registration #5	2021-09-29	55.277 mi
Registration #6	2022-09-29	55.277 mi
Registration #7	2023-09-29	55.277 mi
Registration #8	2024-03-28	55.277 mi
Registration #9	2024-03-28	55.277 mi

More info >



Dimensions & weight

Width	1895 mm
Height	1942 mm
Length	5135 mm
Kerb weight	1732 kg
Max. allowed weight	2932 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	3
Number of axles	2
Engine number	DYZG4158506