



report date: 2024-03-28

General information

Make	VOLVO
Model	C30 D DRIVE R-DESIGN
Colour	Blue
Year of manufacture	2010
Top speed	118 mph
0 - 60 mph	10.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	109 BHP
Max. torque	240 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	49.6 mpg
Consumption extra urban	74.3 mpg
Consumption combined	62.8 mpg
CO2 emission	119 g/km
CO2 label	C






Internet history

Entry 1

Date	2022-03-23
Pictures	7
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2025-02-24
MOT pass rate	63 %
MOT passed	12
Failed MOT tests	7
Total advice items	34
Total items failed	7

MOT #19 2024-02-23 10:20

MOT test number 386220326875

Result ✓ Passed

Next expiry date 2025-02-24

- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Road wheel slightly distorted inner rim bead (5.2.2 (c) (i))
- Advice** Front Suspension arm pin or bush worn but not resulting in excessive movement rear arm bushes (5.3.4 (a) (i))
- Advice** Rear Coil spring corroded both rears (5.3.1 (b) (i))

MOT #18 2023-02-23 14:38

MOT test number 404828823140

Result ✓ Passed

MOT #17 2023-02-23 11:28

MOT test number 157345466401

Result ✗ Failed

- Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- DANGEROUS** Nearside Rear Anti-roll bar linkage fractured (5.3.3 (b) (ii))

**MOT #16** 2022-02-17 12:02**MOT test number** 807128433749**Result** ✓ Passed**MOT #15** 2021-02-25 14:47**MOT test number** 179964562603**Result** ✓ Passed**Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #14** 2021-02-24 13:27**MOT test number** 408950401751**Result** ✗ Failed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MAJOR** Nearside Front Wheel bearing rough when rotated (5.1.3 (b) (i))**Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #13** 2020-03-18 15:26**MOT test number** 514046597553**Result** ✓ Passed**Advice** Offside Front Wheel bearing slightly noisy (5.1.3 (b) (i))**Advice** Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #12** 2019-03-07 13:47**MOT test number** 270253995174**Result** ✓ Passed**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #11** 2019-03-06 14:31**MOT test number** 655674492660**Result** ✗ Failed**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**DANGEROUS** Offside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #10** 2018-03-26 10:35**MOT test number** 578516589068**Result** ✓ Passed**MOT #9** 2018-03-22 14:39**MOT test number** 777110855476**Result** ✗ Failed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Front coil spring broken (2.4.C.1a)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #8** 2017-03-03 13:27**MOT test number** 554372874498**Result** ✓ Passed**Advice** Nearside Rear tyre worn inside edge**Advice** Offside Rear tyre cracked**MOT #7** 2017-03-03 12:08**MOT test number** 225488557844**Result** ✗ Failed**Fail** Nearside Front Tyre has ply or cords exposed (4.1.D.1b)**Advice** Nearside Rear tyre worn inside edge**Fail** Offside Front Tyre has ply or cords exposed (4.1.D.1b)**Advice** Offside Rear tyre cracked**MOT #6** 2017-02-01 09:07**MOT test number** 521308010642**Result** ✗ Failed**Fail** Nearside Front Tyre has ply or cords exposed (4.1.D.1b)**Fail** Front brake application uneven (3.7.B.2)**Advice** Offside Rear wearing inner edge**Fail** Offside Front Tyre has ply or cords exposed (4.1.D.1b)**Advice** Nearside Rear Road wheel with a slightly distorted bead rim (4.2.A.1a)**Advice** Nearside Rear wearing inner edge + flatspots in tread

**MOT #5** 2016-02-12 10:05**MOT test number** 810783142330**Result** ✓ Passed**Advice** Front tyres worn inside edge**MOT #4** 2015-02-13 13:56**MOT test number** 805354545045**Result** ✓ Passed**MOT #3** 2014-02-27 12:49**MOT test number** 575378854064**Result** ✓ Passed**Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #2** 2014-02-27 09:02**MOT test number** 488468654005**Result** ✗ Failed**Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Notice** Front tyre inside edges worn smooth**Fail** Rear Direction indicators incorrect colour (1.4.A.2f)**MOT #1** 2013-02-26 09:07**MOT test number** 457767053073**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
24 February 2025

Tax status	Valid until 1 September
Days left	125
MOT expiry date	24 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history


Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	SY10PGV
Plate since	2019-03-28
Current registration	SY10PGV
Plate since	2019-03-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2010-03-01
Last registration	2024-02-23
Complete history	See info



Registration #1	2010-03-01	23 mi
Registration #2	2013-02-26	27.663 mi
Registration #3	2014-02-27	32.815 mi
Registration #4	2014-02-27	32.815 mi
Registration #5	2015-02-13	37.705 mi
Registration #6	2016-02-12	45.193 mi
Registration #7	2017-02-01	51.235 mi
Registration #8	2017-03-03	51.243 mi
Registration #9	2017-03-03	51.243 mi
Registration #10	2018-03-22	69.316 mi
Registration #11	2018-03-26	69.364 mi
Registration #12	2019-03-20	75.377 mi
Registration #13	2019-03-20	75.377 mi
Registration #14	2019-03-20	75.377 mi
Registration #15	2019-03-20	75.377 mi
Registration #16	2019-03-20	75.377 mi
Registration #17	2019-03-20	75.377 mi
Registration #18	2019-03-20	75.377 mi
Registration #19	2019-03-20	75.377 mi
Registration #20	2019-03-20	75.377 mi
Registration #21	2019-03-20	75.377 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	91%
Children	78%
Pedestrian	26%
Safety systems	71%
Overall rating	73%
Video	see crash video



Dimensions & weight

Width	1770 mm
Height	1457 mm
Length	4522 mm
Wheel base	2640 mm
Kerb weight	1442 kg
Max. allowed weight	1900 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	957553