



General information

Make	FORD
Model	FOCUS ZETEC
Colour	Black
Year of manufacture	2009
Top speed	123 mph
0 - 60 mph	10.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	125 BHP
Max. torque	165 Nm at 4.000 rpm
Engine capacity	1.798 cc
Cylinders	4
Fuel type	Petrol
Consumption city	29.7 mpg
Consumption extra urban	50.4 mpg
Consumption combined	40.4 mpg
CO2 emission	167 g/km
CO2 label	H





MOT history

MOT expiry date	2024-08-21
MOT pass rate	75 %
MOT passed	12
Failed MOT tests	4
Total advice items	16
Total items failed	16

MOT #16	2023-08-22 12:09
MOT test number	114292809682
Result	✓ Passed
Next expiry date	2024-08-21
Advice	Nearside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
Advice	Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #15	2023-08-18 16:41
MOT test number	655092092172
Result	✗ Failed
Advice	Exhaust emits blue smoke during acceleration (8.2.1.2 (g))
Fail	Offside Headlamp aim too high (4.1.2 (a))
Advice	Nearside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
Fail	Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))
Fail	Exhaust hydrocarbon content after 2nd fast idle exceeds manufacturer's specified limits (8.2.1.2 (a))
Fail	Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
Advice	Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Fail	Exhaust carbon monoxide content after 2nd fast idle exceeds manufacturer's specified limits (8.2.1.2 (a))

**MOT #14** 2022-07-25 12:35**MOT test number** 324522613815**Result** ✓ Passed**MOT #13** 2021-08-20 11:54**MOT test number** 446296219427**Result** ✓ Passed**MOT #12** 2021-08-20 11:54**MOT test number** 760277531354**Result** ✗ Failed**Pass with rectification** Stop lamp(s) remains on when the brakes are released (4.3.2 (a) (iii))**MOT #11** 2020-11-27 09:53**MOT test number** 235064773023**Result** ✓ Passed**Advice** Brake pedal rubber worn**Advice** Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #10**

2020-11-19 14:07

MOT test number

335598489372

Result

✗ Failed

Fail Exhaust hydrocarbon content after 2nd fast idle exceeds manufacturer's specified limits (8.2.1.2 (a))**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Fail** Nearside Front Tyre has ply or cords damaged (5.2.3 (d) (ii))**Fail** Exhaust carbon monoxide content after 2nd fast idle exceeds manufacturer's specified limits (8.2.1.2 (a))**Fail** Exhaust carbon monoxide content at idle exceeds default limits (8.2.1.2 (b))**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** Brake pedal rubber worn**Fail** Offside Front Tyre has ply or cords damaged (5.2.3 (d) (ii))**Fail** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))**MOT #9**

2019-10-30 16:39

MOT test number

698474275428

Result

✓ Passed

MOT #8

2018-11-16 11:23

MOT test number

307215832276

Result

✓ Passed

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #7**

2017-11-08 14:27

MOT test number

181813233305

Result

✓ Passed

**MOT #6** 2016-11-18 13:33**MOT test number** 755922953306**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit inner edge (4.1.E.1)**Advice** Rear registration plate deteriorated but not likely to be misread (6.3.1d)**MOT #5** 2016-11-17 12:19**MOT test number** 570060476702**Result** ✗ Failed**Fail** Front brake disc in such a condition that it is seriously weakened both (3.5.1i)**Advice** Rear registration plate deteriorated but not likely to be misread (6.3.1d)**Fail** Nearside Headlamp aim aimed so that it dazzles other road users (1.8.A.1a)**Advice** Nearside Rear Tyre worn close to the legal limit inner edge (4.1.E.1)**MOT #4** 2015-12-17 14:01**MOT test number** 698016606477**Result** ✓ Passed**MOT #3** 2014-12-17 14:21**MOT test number** 498881654393**Result** ✓ Passed**MOT #2** 2013-12-11 11:49**MOT test number** 899985143307**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)



MOT #1	2012-12-14 11:49
MOT test number	475879442345
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 April 2025

✓
MOT
Expires:
21 August 2024

Tax status	Valid until 1 April
Days left	336
MOT expiry date	21 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2009-12-18
Last registration	2023-08-22
Complete history	See info



Registration #1	2009-12-18	29 mi
Registration #2	2012-12-14	24.472 mi
Registration #3	2013-12-11	32.165 mi
Registration #4	2014-12-17	41.243 mi
Registration #5	2015-12-17	49.651 mi
Registration #6	2016-11-17	57.179 mi
Registration #7	2016-11-18	57.180 mi
Registration #8	2017-11-08	58.428 mi
Registration #9	2018-11-16	59.488 mi
Registration #10	2019-11-16	60.548 mi
Registration #11	2020-11-16	61.608 mi
Registration #12	2021-11-16	62.668 mi
Registration #13	2022-11-16	63.728 mi
Registration #14	2023-11-16	64.788 mi
Registration #15	2024-11-16	65.848 mi
Registration #16	2025-11-16	66.908 mi
Registration #17	2026-11-16	67.968 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2019 mm
Height	1500 mm
Length	4337 mm
Wheel base	2640 mm
Kerb weight	1347 kg
Max. allowed weight	1835 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	8C35715