



RENAULT



AF06GOK

report date: 2024-03-29

General information

Make	RENAULT
Model	SCENIC DYNAMIQUE VVT 111 SCENIC EU4
Colour	Green
Year of manufacture	-
Top speed	109 mph
0 - 60 mph	14.3 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	110 BHP
Max. torque	150 Nm at 4.250 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	25.9 mpg
Consumption extra urban	44.8 mpg
Consumption combined	35.3 mpg





LABEL UNKNOWN



Internet history

Entry 1

Date	2021-07-02
Pictures	12
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)

**MOT history****MOT #22**

2022-09-08 14:26

MOT test number

274861678122

Result**✗ Failed**

- MAJOR** Offside Track rod end ball joint has excessive play (2.1.3 (b) (i))
- MAJOR** Offside Front Lower Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- DANGEROUS** Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))
- MAJOR** Nearside Parking brake inoperative on one side (1.4.1 (a))
- MAJOR** Oil leaking excessively from engine (8.4.1 (a) (i))
- MAJOR** Nearside Track rod end ball joint has excessive play (2.1.3 (b) (i))
- Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- MAJOR** Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))
- MAJOR** Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))
- MAJOR** Rear Exhaust system insecure (6.1.2 (a))
- MAJOR** Offside Parking brake inoperative on one side (1.4.1 (a))
- MAJOR** Electronic parking brake warning indicates a malfunction (1.1.6 (e))

MOT #21

2021-09-24 12:44

MOT test number

573363752221

Result**✓ Passed**

- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #20** 2020-10-27 17:28**MOT test number** 705074524163**Result** ✓ Passed**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**MOT #19** 2020-10-27 17:28**MOT test number** 245978304798**Result** ✗ Failed**Pass with rectification** Nearside Front Headlamp aim too high (4.1.2 (a))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #18** 2019-05-01 11:08**MOT test number** 227929081020**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Minor** Nearside Front Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))**MOT #17** 2018-05-01 14:59**MOT test number** 950450156294**Result** ✓ Passed**MOT #16** 2018-05-01 09:45**MOT test number** 438680318104**Result** ✗ Failed**Fail** Offside Front coil spring broken (2.4.C.1a)

**MOT #15** 2017-04-22 10:20**MOT test number** 843971089414**Result** ✓ Passed**MOT #14** 2017-04-21 11:13**MOT test number** 909540262942**Result** ✗ Failed**Fail** Nearside Rear Registration plate lamp not working (1.1.C.1d)**Fail** Nearside Rear Shock absorber has a serious fluid leak (2.7.3)**Fail** Offside Rear Registration plate lamp not working (1.1.C.1d)**MOT #13** 2016-04-20 11:42**MOT test number** 755199563031**Result** ✓ Passed**Advice** Undertrays**Advice** N/s door mirror glass cracked**Advice** Engine covers**Advice** Rear discs corroded around edges**Advice** Chip in windscreen n/s**Advice** O/s/r brake pipe showing surface corrosion

**MOT #12**

2016-04-19 11:24

MOT test number

173430932080

Result

✗ Failed

Advice N/s door mirror glass cracked**Fail** Offside Front Front suspension has excessive play in a upper suspension ball joint (2.5.B.1a)**Advice** Engine covers**Advice** Rear discs corroded around edges**Fail** Centre Rear Seat belt locking mechanism does not secure or release (5.2.5a)**Advice** Chip in windscreen n/s**Fail** Nearside Front Front suspension has excessive play in a lower suspension ball joint (2.5.B.1a)**Advice** O/s/r brake pipe showing surface corrosion**Fail** Nearside Front Front suspension has serious deterioration of the bonding between metal and flexible material of an upper support bearing n/s/f wishbone rear bush worn (2.5.B.3a)**Advice** Undertrays**Fail** Nearside Rear Brake pipe excessively corroded (3.6.B.2c)**MOT #11**

2015-03-20 13:53

MOT test number

108229875488

Result

✓ Passed

Notice N/s front tyre wearing on inner edge**Notice** Child seat fitted not allowing full inspection of adult belt**Notice** O/s front tyre wearing on inner edge

**MOT #10**

2015-03-20 10:48

MOT test number

109529675033

Result

✗ Failed

- Notice** Child seat fitted not allowing full inspection of adult belt
- Notice** O/s front tyre wearing on inner edge
- Fail** Offside Rear Direction indicator incorrect colour (1.4.A.2f)
- Fail** Offside Track rod end ball joint has excessive play (2.2.B.1f)
- Notice** N/s front tyre wearing on inner edge
- Fail** Nearside Rear Direction indicator incorrect colour (1.4.A.2f)
- Fail** Nearside Track rod end ball joint has excessive play (2.2.B.1f)

MOT #9

2014-03-20 10:02

MOT test number

456549174065

Result

✓ Passed

- Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)
- Notice** Child seat fitted not allowing full inspection of adult belt

MOT #8

2013-03-20 17:28

MOT test number

419379373035

Result

✓ Passed

- Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)
- Notice** Wipers not clearing lower edge of screen incorrect wiper blades ?
- Notice** Under-trays fitted obscuring some underside components
- Notice** Nearside front tyre worn on inner edge

**MOT #7**

2013-03-20 10:21

MOT test number

299799373013

Result**✗ Failed**

- Notice** Wipers not clearing lower edge of screen incorrect wiper blades ?
- Notice** Under-trays fitted obscuring some underside components
- Fail** Offside Stop lamp not working (1.2.1b)
- Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)
- Notice** Nearside front tyre worn on inner edge
- Fail** Nearside Headlamp not working on dipped beam (1.7.5a)
- Fail** Offside Front Tyre has ply or cords exposed (4.1.D.1b)

MOT #6

2012-03-09 10:53

MOT test number

287189062063

Result**✓ Passed**

- Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)
- Notice** Slight damage to nearside rear wheel inner rim
- Notice** Nearside mirror missing

**MOT #5** 2012-03-07 15:00**MOT test number** 628587562094**Result** ✗ Failed**Fail** Offside Front Tyre has ply or cords exposed (4.1.D.1b)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Nearside Front Lower Suspension arm has excessive play in a ball joint (2.4.G.2)**Notice** Slight damage to nearside rear wheel inner rim**Fail** Offside Stop lamp not working (1.2.1b)**Fail** Nearside Rear Tyre has a bulge, caused by separation or partial failure of its structure (4.1.D.1b)**Fail** Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)**Notice** Nearside mirror missing**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**MOT #4** 2011-03-04 15:00**MOT test number** 165093361466**Result** ✓ Passed**Notice** Nearside mirror missing**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Notice** Slight play in steering**MOT #3** 2010-03-02 17:03**MOT test number** 563481760035**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Notice** Slight play in nearside of steering



MOT #2	2010-03-02 11:25
MOT test number	272251060047
Result	✗ Failed
Fail	Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)
Fail	Offside Front Tyre has ply or cords exposed (4.1.D.1b)
Advice	Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)
Notice	Slight play in nearside of steering

MOT #1	2009-02-17 08:32
MOT test number	121028849403
Result	✓ Passed
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.


Finance company	RENAULT	2024
Date of agreement	RENAULT	2024
Agreement type	RENAULT	2024
Agreement term	RENAULT	2024
Agreement number	RENAULT	2024
Contact info	RENAULT	2024

More info >



Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	2006-03-01
Last registration	2022-09-08
Complete history	See info



Registration #1	2006-03-01	8 mi
Registration #2	2009-02-17	22.876 mi
Registration #3	2010-03-02	29.602 mi
Registration #4	2010-03-02	29.604 mi
Registration #5	2011-03-04	32.838 mi
Registration #6	2012-03-07	37.864 mi
Registration #7	2012-03-09	37.865 mi
Registration #8	2013-03-20	43.714 mi
Registration #9	2013-03-20	43.715 mi
Registration #10	2014-03-20	49.209 mi
Registration #11	2015-03-20	56.116 mi
Registration #12	2015-03-20	56.117 mi
Registration #13	2016-03-20	56.117 mi
Registration #14	2016-03-20	56.117 mi
Registration #15	2016-03-20	56.117 mi
Registration #16	2016-03-20	56.117 mi
Registration #17	2016-03-20	56.117 mi
Registration #18	2016-03-20	56.117 mi
Registration #19	2016-03-20	56.117 mi
Registration #20	2016-03-20	56.117 mi
Registration #21	2016-03-20	56.117 mi
Registration #22	2016-03-20	56.117 mi
Registration #23	2016-03-20	56.117 mi
Registration #24	2016-03-20	56.117 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1810 mm
Height	1620 mm
Length	4259 mm
Wheel base	2685 mm
Kerb weight	1370 kg
Max. allowed weight	1950 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	D010807