



**HV58HBO**

report date: 2024-03-28

General information

Make	MAZDA
Model	5 D TS2
Colour	Blue
Year of manufacture	2008
Top speed	110 mph
0 - 60 mph	13.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	110 BHP
Max. torque	310 Nm at 3.500 rpm
Engine capacity	1.998 cc
Cylinders	4
Fuel type	Diesel
Consumption city	38.7 mpg
Consumption extra urban	52.3 mpg
Consumption combined	46.3 mpg
CO2 emission	162 g/km
CO2 label	G





Internet history

Entry 2

Date	2022-01-16
Pictures	13
Listing price	<a href="#">View report</a>



source: [cargurus.co.uk](https://www.cargurus.co.uk)

Entry 1

Date	2021-10-28
Pictures	12
Listing price	<a href="#">View report</a>



source: [cargurus.co.uk](https://www.cargurus.co.uk)



## MOT history

MOT expiry date	2024-08-29
MOT pass rate	81 %
MOT passed	13
Failed MOT tests	3
Total advice items	13
Total items failed	5

MOT #16	2023-08-08 10:54
MOT test number	665527696662
Result	✓ Passed
Next expiry date	2024-08-29
Advice	Hand brake performance 18% minimum pass 16%

MOT #15	2022-08-18 12:37
MOT test number	971017165371
Result	✓ Passed
Advice	Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear void (5.3.4 (a) (i))

MOT #14	2022-08-17 10:48
MOT test number	834096860084
Result	✗ Failed
Advice	Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear void (5.3.4 (a) (i))
Fail	Nearside Front Lower Suspension arm pin or bush excessively worn rear void (5.3.4 (a) (i))
Fail	Nearside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))

MOT #13	2021-08-17 10:22
MOT test number	675933024751
Result	✓ Passed

**MOT #12** 2020-08-28 08:58**MOT test number** 654482448667**Result** ✓ Passed**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**MOT #11** 2019-08-30 09:00**MOT test number** 904596267192**Result** ✓ Passed**MOT #10** 2018-09-06 11:07**MOT test number** 314643533459**Result** ✓ Passed**MOT #9** 2017-09-06 08:47**MOT test number** 856384485214**Result** ✓ Passed**MOT #8** 2016-09-08 12:59**MOT test number** 682602431680**Result** ✓ Passed**MOT #7** 2015-09-25 07:50**MOT test number** 457485559178**Result** ✓ Passed**Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #6** 2014-09-22 16:53**MOT test number** 567245764277**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**MOT #5** 2014-09-22 10:23**MOT test number** 107005664223**Result** ✗ Failed**Fail** Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)**Notice** Under-trays fitted obscuring some underside components**Fail** Offside Rear coil spring broken (2.4.C.1a)**MOT #4** 2013-09-18 11:02**MOT test number** 148821963266**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2013-09-18 11:02**MOT test number** 166321263237**Result** ✗ Failed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Pass with rectification** Battery insecure (1.9.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2012-09-20 14:17**MOT test number** 216754962224**Result** ✓ Passed



MOT #1	2011-09-21 11:07
MOT test number	638284361263
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 January 2025

✓  
**MOT**  
**Expires:**  
29 August 2024

<b>Tax status</b>	Valid until 1 January
<b>Days left</b>	247
<b>MOT expiry date</b>	29 August 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	G
<b>Single payment (12 months)</b>	£ 240,00,-
<b>Single six month payment</b>	£ 132,00,-
<b>Total payable by 12 monthly instalments</b>	£ 252,00,-



Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this MAZDA had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2020-01-01
Current registration	<b>XXXXXX</b>
Plate since	2020-01-01

More info >



Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MAZDA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2008-09-30
Last registration	2023-08-08
Complete history	<a href="#">See info</a>



Registration #1	2008-09-30	13 mi
Registration #2	2011-09-21	20.162 mi
Registration #3	2012-09-20	26.995 mi
Registration #4	2013-09-18	33.572 mi
Registration #5	2014-09-22	37.344 mi
Registration #6	2014-09-22	37.344 mi
Registration #7	2015-09-25	43.074 mi
Registration #8	2016-09-08	46.102 mi
Registration #9	2017-09-06	49.098 mi
Registration #10	2018-09-06	52.094 mi
Registration #11	2019-09-06	55.090 mi
Registration #12	2020-09-06	58.086 mi
Registration #13	2021-09-06	61.082 mi
Registration #14	2022-09-06	64.078 mi
Registration #15	2023-08-08	67.074 mi
Registration #16		
Registration #17		
Registration #18		

More info >



Safety ratings

NCAP rating	★★★★★
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1755 mm
Height	1615 mm
Length	4505 mm
Wheel base	2750 mm
Kerb weight	1535 kg
Max. allowed weight	2245 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7
Number of axles	2
Engine number	RF 330878