



TOYOTA



report date: 2024-03-28

General information

Make	TOYOTA
Model	HILUX INVINCIBLE 4X4 D-4D DCB
Colour	Grey
Year of manufacture	2011
Top speed	106 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	169 BHP
Max. torque	343 Nm at 3.400 rpm
Engine capacity	2.982 cc
Cylinders	4
Fuel type	Diesel
Consumption city	29.7 mpg
Consumption extra urban	42.2 mpg
Consumption combined	36.7 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-09-30
Pictures	22
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



MOT history

MOT expiry date	2024-08-22
MOT pass rate	69 %
MOT passed	9
Failed MOT tests	4
Total advice items	29
Total items failed	14

MOT #132024-03-07 16:16

MOT test number836398873085

Result	Failed
Fail	Nearside Seat belt anchorage prescribed area strength or continuity significantly reduced inner sill (7.1.1 (a) (i))
Fail	Offside Rear Vehicle structure or chassis has excessive corrosion to the extent that overall security or stability of the body is impaired (6.2.2 (d) (ii))
Advice	Offside Play in steering rack inner joint(s)
Fail	Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
Fail	Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))
Fail	Nearside Rear Vehicle structure or chassis has excessive corrosion to the extent that overall security or stability of the body is impaired (6.2.2 (d) (ii))
Fail	Offside Seat belt anchorage prescribed area strength or continuity significantly reduced inner sill (7.1.1 (a) (i))
Fail	Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
Minor	Offside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #12**

2023-08-23 12:41

**MOT test number**

343526370070

**Result**

✓ Passed

- Advice** General underbody corrosion
- Advice** Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**MOT #11**

2022-01-11 13:51

**MOT test number**

653364874820

**Result**

✓ Passed

- Advice** Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))

**MOT #10**

2021-01-06 16:24

**MOT test number**

723853429106

**Result**

✓ Passed

- Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))
- Advice** Nearside Rear Service brake binding but not excessively (1.2.1 (f))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #9**

2019-12-18 08:57

**MOT test number**

559110428319

**Result**

✓ Passed

**MOT #8** 2019-12-04 11:52**MOT test number** 267906921594**Result** ✗ Failed

- Minor** Nearside Front Position lamp light intensity obviously reduced (4.2.3 (a) (i))
- Fail** Brake pipe excessively corroded Four rear pipes at the brake load valve (1.1.11 (c))
- Fail** Parking brake lever has excessive movement indicating incorrect adjustment (1.1.6 (c))
- Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))
- Fail** Horn not working (7.7 (a) (ii))
- Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Fail** Exhaust has a major leak of exhaust gases Centre box (6.1.2 (a))

**MOT #7** 2018-12-13 10:00**MOT test number** 755162775160**Result** ✓ Passed

- Advice** Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Offside Rear Shock absorbers has a slightly worn bush (5.3.2 (c))
- Advice** Nearside Front Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Shock absorbers has a slightly worn bush (5.3.2 (c))

**MOT #6** 2018-12-13 10:00**MOT test number** 818745191196**Result** ✗ Failed**Advice** Nearside Rear Shock absorbers has a slightly worn bush (5.3.2 (c))**Pass with rectification** Offside Rear Direction indicator not working (4.4.1 (a) (ii))**Advice** Nearside Front Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Offside Rear Shock absorbers has a slightly worn bush (5.3.2 (c))**MOT #5** 2017-11-08 14:03**MOT test number** 926622328693**Result** ✓ Passed**Advice** All brake pipes in and out of compensator signs of corrosion**MOT #4** 2016-09-26 17:08**MOT test number** 997449182993**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Advice** Centre Rear Brake pipe slightly corroded to compensator (3.6.B.2c)**MOT #3** 2015-09-07 17:09**MOT test number** 112425790865**Result** ✓ Passed



MOT #2	2014-07-02 12:46
MOT test number	247073884483
Result	✗ Failed
Advice	Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)
Notice	N/s/f brake disc scored by previous defective brake pad
Pass with rectification	Registration plate lamp not working (1.1.C.1d)

MOT #1	2014-07-02 12:46
MOT test number	379123584165
Result	✓ Passed
Notice	N/s/f brake disc scored by previous defective brake pad
Advice	Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	YR11ASU
Plate since	2019-03-28
Current registration	YR11ASU
Plate since	2019-03-28

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2011-03-10
Last registration	2024-03-07
Complete history	<a href="#">See info</a>



Registration #1	2011-03-10	22 mi
Registration #2	2014-07-02	65.513 mi
Registration #3	2015-09-07	71.894 mi
Registration #4	2016-09-26	84.348 mi
Registration #5	2017-11-08	91.208 mi
Registration #6	2018-12-13	95.791 mi
Registration #7	2018-12-13	95.791 mi
Registration #8	2019-03-20	95.791 mi
Registration #9	2019-03-20	95.791 mi
Registration #10	2019-03-20	95.791 mi
Registration #11	2019-03-20	95.791 mi
Registration #12	2019-03-20	95.791 mi
Registration #13	2019-03-20	95.791 mi
Registration #14	2019-03-20	95.791 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1835 mm
Height	1860 mm
Length	5260 mm
Kerb weight	1975 kg
Max. allowed weight	3080 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
Number of axles	2
Engine number	1KD5220094