





report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	SCIROCCO GT TDI BLUEMOTION TECHNOLOGY
Colour	Silver
Year of manufacture	2014
Top speed	129 mph
0 - 60 mph	9.3 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	138 BHP
Max. torque	320 Nm at 1.750 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	51.4 mpg
Consumption extra urban	70.6 mpg
Consumption combined	62.8 mpg
CO2 emission	118 g/km
CO2 label	С



CarCheck.co.uk page 1/12



Internet history

Entry 1

Date 2021-02-06

Pictures 10

Listing price <u>View report</u>









source: autoonline.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2025-04-30
MOT pass rate	70 %
MOT passed	7
Failed MOT tests	3
Total advice items	2
Total items failed	9

MOT #10	2024-04-17 12:30
MOT test number	426978979083
Result	✓ Passed
Next expiry date	2025-04-30

MOT #9	2024-04-08 10:35
MOT test number	942874224019
Result	× Failed
Fail Nearside Front Side repeater not working (4.4.1 (a) (ii))	
Fail Offside Front Side repeater not working (4.4.1 (a) (ii))	

MOT #8	2023-04-27 10:51
MOT test number	654945533918
Result	✓ Passed
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #7		2022-05-01 16:32
MOT test	number	791438634441
Result		✓ Passed
Advice	Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

CarCheck.co.uk page 3/12



Pass with rectification

VN14NCO

report date: 2024-03-28

MOT #6		2021-03-26 16:39
MOT test number		442257511894
Result		✓ Passed
MOT #5		2021-03-26 16:39
MOT test number		786327471227
Result		X Failed
Pass with rectification	Nearside Front Road wheel fixing missing (5.2.1 (a) (i))	
Pass with rectification	Nearside Rear Road wheel fixing missing (5.2.1 (a) (i))	
Pass with rectification	Offside Front Road wheel fixing missing (5.2.1 (a) (i))	

MOT #4	2019-07-04 08:44
MOT test number	967311123168
Result	✓ Passed
MOT #3	2018-07-17 10:48
MOT test number	127785781284
Result	✓ Passed

Offside Rear Road wheel fixing missing (5.2.1 (a) (i))

MOT #	2	2018-04-19 11:00
MOT te	st number	956356240145
Result		≍ Failed
Fail	Nearside Front Tyre has ply or cords exposed (4.1.D.1b)	
Fail Nearside Front Tyre has a bulge, caused by separation or partial failure of its structure (4.1.D.1b)		
Fail	Offside Front Tyre has ply or cords exposed (4.1.D.1b)	

CarCheck.co.uk page 4/12



MOT #1 2017-06-02 14:34

MOT test number 828287888845

Result ✓ Passed

CarCheck.co.uk page 5/12



Tax & MOT check



Tax status	Valid until 1 May
Days left	366
MOT expiry date	30 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report here for the results.

Damage 1

Date	
Category	
Туре	
Damago 2	

Damage 2

Date Category

Type



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Dow here.	

	More info >
Plate changes	
See in this check if this VOLKSWAGEN had different number plates.	
Number of plates	,
Current registration	JK UK
Plate since	
Current registration	OK SIE
Plate since	
	More info >

CarCheck.co.uk page 9/12



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2014-05-31
Last registration	2024-04-17
Complete history	See info



Registration #1	2014-05-31	10 mi
Registration #2	2017-06-02	51.858 mi
Registration #3	2018-04-19	65.546 mi
Registration #4	2018-07-17	68.810 mi
Registration #5	2019-07-04	77.096 mi
Registration #6		11.117 es
Registration #7		11.777 es
Registration #8		11.117 es
Registration #9		11.777 es
Registration #10		111,7177 ess
Registration #11		10.107 es
Registration #12		11.777 es

More info >

CarCheck.co.uk page 11/12



Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Adult	87%
Children	73%
Pedestrian	53%
Safety systems	71%
Overall rating	76%
Video	see crash video



Dimensions & weight

Width	1810 mm
Height	1404 mm
Length	4256 mm
Wheel base	2578 mm
Kerb weight	1318 kg
Max. allowed weight	1750 kg

Additional information

Fuel tank capacity	55 I
Fuel delivery	Direct Injection
Number of doors	3
CarChack co.uk	page 12/1

CarCheck.co.uk page 12/12

Number of seats	4
Engine number	CFHC534795